

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5318K**AAD2001-137***Not Authorized
Penalty B4 point*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

PART

- 1 REAR BUMPER
 1 REAR BUMPER RE-INFORCEMENT
 1 REAR BUMPER TOWING COVER
 1 GUARD, REAR BUMPER, CENTER
 1 REAR BUMPER SIDE RETAINER LH
 1 REAR BUMPER SIDE RETAINER RH
 1 REAR TAILGATE
 1 REAR TAILGATE OUTER GARNISH
 1 REAR TAILGATE WEATHERSTRIP
 1 PANEL SUB-ASSY, BODY LOWER BACK
 1 TAILLAMP LOWER RH
 1 TAILLAMP UPPER RH
 1 REAR BUMPER SIDE RH
 1 REAR BUMPER SIDE LH
 1 TAILLAMP LOWER LH
 1 TAILLAMP UPPER LH
 1 COVER, DECK TRIM, REAR
 1 COVER, FLOOR UNDER, NO 1
 1 COVER, FLOOR UNDER, NO 2
 1 COVER, REAR FLOOR

SHD 5318K

JTDKB3FU103078509

TOYOTA

PRIUS

14.1.2020

AIG

19/12/2018

LIST

\$	<i>Bur</i>	442.60	✓
\$	Svc	332.70	✓
\$	<i>Net</i>	15.40	✓
\$	<i>Net/ln</i>	576.30	✓
\$	<i>ln</i>	116.50	} X
\$	<i>ln</i>	117.70	
\$	<i>ln</i>	1,147.80	
\$	<i>ln</i>	925.60	
\$	<i>ln</i>	372.30	
\$	<i>ln</i>	650.30	
\$	<i>ln</i>	502.00	
\$	<i>ln</i>	451.80	
\$	<i>ln</i>	123.70	
\$	<i>ln</i>	123.70	
\$	<i>ln</i>	502.00	
\$	<i>ln</i>	443.30	
\$	<i>ln</i>	126.70	
\$	<i>ln</i>	175.10	
\$	<i>ln</i>	241.90	
\$	<i>ln</i>	229.90	

TOTAL	\$	7,617.30
25%	\$	1,904.33
	\$	5,712.98

Special Nett

Trans-cab Auto Services Pte Ltd**AAD2001-137**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5318K

1SET	PARKING AID	\$	Ph	700.00	X
1SET	REAR BUMPER CLIP	\$	nn	66.00	
2	REAR WINDSCREEN SEALANT	\$	nn	80.00	
1	WINDSCREEN MOULDING	\$	nn	100.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
1	REAR TAILGATE TOYOTA LOGO	\$	nn	47.00	
1	REAR TAILGATE WORDING 'PRIUS'	\$	nn	52.90	
1	REAR TAILGATE WORDING 'HYBRID'	\$	nn	53.50	
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	nn	80.00	
1	REAR TAILGATE STICKER '6555-3333'	\$	nn	80.00	
1	REAR BUMPER PROTECTOR	\$	nn	100.00	
1	REAR WHEEL RIM	\$	Ph	1,879.40	
1	REAR TYRE 195/65/15	\$	Ph	350.00	
1	REAR WHEEL RIM COVER	\$	Ph	211.50	
1	REAR RH BUMPER RETAINER CLIP	\$	nn	25.00	
1	REAR LH BUMPER RETAINER CLIP	\$	nn	25.00	
TOTAL		\$		3,950.30	
TOTAL PARTS		\$		9,663.28	

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	nn	170.00	X
Putty And Spray Painting Of The Affected Portion.	\$		6,000.00	220/

Trans-cab Auto Services Pte Ltd**AAD2001-137**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5318K

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>501</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i> 380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>4</i> 170.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>2001</i>
To supply and re-do rear end panel insulation padding.	\$	<i>4</i> 380.00	<i>X</i>
TOTAL	\$	14,720.00	
Over All Total	\$	24,383.28	

(PART-BY-PART) Repair Days*20 Days*
2 days