

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5318K**AAD2001-137***Not Authorized
Permy B4 point*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

16 JAN 2020

SHD 5318K

JTDKB3FU103078509

TOYOTA

PRIUS

14.1.2020

AIG

19/12/2018

PART		LIST	
1	REAR BUMPER	\$	<i>Bu</i> 442.60 ✓
1	REAR BUMPER RE-INFORCEMENT	\$	332.70 ?
1	REAR BUMPER TOWING COVER	\$	<i>Net</i> 15.40 ✓
1	GUARD, REAR BUMPER, CENTER	\$	<i>Net/ln</i> 576.30 ✓
1	REAR BUMPER SIDE RETAINER LH	\$	<i>SL</i> 116.50
1	REAR BUMPER SIDE RETAINER RH	\$	<i>SL</i> 117.70
1	REAR TAILGATE	\$	<i>N</i> 1,147.80
1	REAR TAILGATE OUTER GARNISH	\$	<i>SL</i> 925.60
1	REAR TAILGATE WEATHERSTRIP	\$	<i>SL</i> 372.30
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>SL</i> 650.30
1	TAILLAMP LOWER RH	\$	<i>SL</i> 502.00
1	TAILLAMP UPPER RH	\$	<i>SL</i> 451.80
1	REAR BUMPER SIDE RH	\$	<i>SL</i> 123.70
1	REAR BUMPER SIDE LH	\$	<i>SL</i> 123.70
1	TAILLAMP LOWER LH	\$	<i>SL</i> 502.00
1	TAILLAMP UPPER LH	\$	<i>SL</i> 443.30
1	COVER, DECK TRIM, REAR	\$	<i>SL</i> 126.70
1	COVER, FLOOR UNDER, NO 1	\$	<i>SL</i> 175.10
1	COVER, FLOOR UNDER, NO 2	\$	<i>SL</i> 241.90
1	COVER, REAR FLOOR	\$	<i>SL</i> 229.90

TOTAL	\$	7,617.30
25%	\$	1,904.33
	\$	5,712.98

Special Nett

Trans-cab Auto Services Pte Ltd**AAD2001-137**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5318K

1SET	PARKING AID	\$	Ph	700.00	X
1SET	REAR BUMPER CLIP	\$	nn	66.00	
2	REAR WINDSCREEN SEALANT	\$	nn	80.00	
1	WINDSCREEN MOULDING	\$	nn	100.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
1	REAR TAILGATE TOYOTA LOGO	\$	nn	47.00	
1	REAR TAILGATE WORDING 'PRIUS'	\$	nn	52.90	
1	REAR TAILGATE WORDING 'HYBRID'	\$	nn	53.50	
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	nn	80.00	
1	REAR TAILGATE STICKER '6555-3333'	\$	nn	80.00	
1	REAR BUMPER PROTECTOR	\$	nn	100.00	
1	REAR WHEEL RIM	\$	Ph	1,879.40	
1	REAR TYRE 195/65/15	\$	Ph	350.00	
1	REAR WHEEL RIM COVER	\$	Ph	211.50	
1	REAR RH BUMPER RETAINER CLIP	\$	nn	25.00	
1	REAR LH BUMPER RETAINER CLIP	\$	nn	25.00	
TOTAL		\$		3,950.30	
TOTAL PARTS		\$		9,663.28	

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	nn	170.00	X
Putty And Spray Painting Of The Affected Portion.	\$		6,000.00	220/

Trans-cab Auto Services Pte Ltd**AAD2001-137**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5318K

To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	<i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i>	170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$		170.00	<i>501</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i>	380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i>	380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>4</i>	170.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,000.00	<i>2001</i>
To supply and re-do rear end panel insulation padding.	\$	<i>4</i>	380.00	<i>X</i>
TOTAL	\$		14,720.00	
Over All Total	\$		24,383.28	

(PART-BY-PART) Repair Days*20 Days*
2 days