

Kh

Arthur Kenneth

Cheng Hoe Motor Pte Ltd

SJG 7181J

TP/AIG

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Estimate No: ES2090054/YISHUN
Date: 17 Jan 2020
Policy No: 5076190009-04
Veh Reg No: SJG7181J
Make/Model: HONDA FIT 1.3G A
Chassis No: GE61082323
Engine No: L13A4092474
Reg. Date: 14/07/2008

TEL: 64193000
ATTN: Motor Claim Department
WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 15/01/2020
TP Veh Reg No: SMF4719Z

FAX: 64153727

NOT Authorized
11 Days @ 8730h
Presurvey After Paint

18 days

Estimate Repair Cost to Vehicle No :SJG7181J

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 REAR BUMPER	497.20	1 PC	<i>Rt</i> 497.20	—
2 REAR BUMPER SIDE RETAINERS	16.50	2 PCS	<i>Dir</i> 33.00	—
3 REAR BUMPER CLIPS	3.70	6 PCS	<i>na</i> 22.20	—
4 REAR BUMPER TOW COVER	13.00	1 PC	<i>na</i> 13.00	—
5 REAR TAILGATE	771.50	1 PC	<i>Rt</i> 771.50	—
6 TAILGATE EMBLEM (FIT)	35.00	1 PC	<i>na</i> 35.00	—
7 TAILGATE INNER LOCK	189.90	1 PC	<i>Tn</i> 189.90	—
8 TAILGATE INNER BOARD	<i>Dir / Bu</i> 100.20	1 PC	100.20	—
9 TAILGATE OUTER GARNISH	110.60	1 PC	<i>warp</i> 110.60	—
10 TAILGATE LOGO	27.40	1 PC	<i>na</i> 27.40	—
11 REAR WINDSCREEN GLASS	<i>Shatter</i> 1,200.50	1 PC	1,200.50	—
12 REAR WINDSCREEN GLASS MOULDING	120.80	1 PC	<i>na</i> 120.80	—
13 REAR WIPER MOTOR	218.30	1 PC	<i>Tn</i> 218.30	<i>na</i>
14 REAR NUMBER PLATE LAMP	48.00	1 PC	<i>CM</i> 48.00	<i>na</i>
15 REAR SPARE TYRE PANEL	737.00	1 PC	<i>Rt</i> 737.00	—
16 REAR SPARE TYRE PANEL INNER TOP BOARD	190.70	1 PC	<i>Reform</i> 190.70	<i>na</i>
17 REAR RH FENDER	652.90	1 PC	<i>Bu</i> 652.90	—
18 REAR RH FENDER INNER GARNISH	250.30	1 PC	<i>Reform</i> 250.30	—
19 REAR RH FENDER AIR SCROP GRILLE	28.80	1 PC	<i>Dir</i> 28.80	—
20 REAR RH FENDER INNER SHIELD	28.00	1 PC	<i>Tn</i> 28.00	—
21 REAR RH FENDER GLASS <i>R</i>	280.60	1 PC	<i>Pin</i> 280.60	<i>na</i>
22 REAR PANEL	276.50	1 PC	<i>Rt</i> 276.50	—
23 REAR PANEL INNER TOP GARNISH	60.80	1 PC	<i>na</i> 60.80	—
24 TAILLAMPS	206.50	2 PCS	<i>Bu</i> 413.00	—
25 TAILLAMP PANELS <i>nl R</i>	<i>cls Rt</i> 135.50	2 PCS	271.00	<i>na</i>
26 REAR LH FENDER INNER GARNISH	250.30	1 PC	<i>CM</i> 250.30	<i>na</i>
27 REAR EXHAUST PIPE	529.40	1 PC	<i>Rt</i> 529.40	—
28 CENTRE EXHAUST PIPE	506.90	1 PC	<i>Rt</i> 506.90	<i>na</i>
			7447.70	7,863.80
			Less 20%	1,572.76
				6,291.04
			<i>1489.54</i>	<i>5958.16</i>
Special Net				
29 REAR WINDSCREEN GLASS GUM	40.00	1 ROLL	<i>na</i> 40.00	—
30 REVERSE SENSOR	200.00	1 SET	<i>Short</i> 200.00	—
31 REAR NUMBER PLATE	35.00	1 PC	<i>na</i> 35.00	—
32 REVERSE CAMERA	380.00	1 PC	<i>Short</i> 380.00	<i>na</i>
33 REAR SPARE PANEL TOP COAT	80.00	1 PC	<i>na</i> 80.00	<i>bolu</i>
34 REAR RH FENDER GLASS GUM	30.00	1 PC	<i>na</i> 30.00	—

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 15/01/2020
TP Veh Reg No: SMF4719Z

Estimate No: ES2090054/YISHUN
Date: 17 Jan 2020
Policy No: 5076190009-04
Veh Reg No: SJJG7181J
Make/Model: HONDA FIT 1.3G A
Chassis No: GE61082323
Engine No: L13A4092474
Reg. Date: 14/07/2008

Estimate Repair Cost to Vehicle No :SJJG7181J

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			745 765.00	765.00
Labour				
35 TOWING (FROM SCENE TO HOME)	70.00	1 LA	70.00	✓
36 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
37 REMOVE & REFIX REAR RH FENDER GLASS	60.00	1 LA	60.00	50
38 REMOVE & REFIX TOP ROOF LINING,SEAT,GARNISH,ETC	120.00	1 LA	120.00	✓
39 REMOVE & REFIX REAR EXHAUST,STRAIGHTEN CENTRE EXHAUST	80.00	1 LA	80.00	✓
40 REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS,TAILGATE ASSY,CUT,WELD & RENEW REAR END PANEL,TAILLAMP PANELS,REAR RH FENDER,REAR SPARE TYRE COMPARTMENT,KNOCK & REPAIR REAR LH FENDER,REAR BOTH CHASSISS, TOP ROOF PANEL & REALIGN THE SAME	1,850.00	1 LA	1,850.00	1700
41 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT,TAILLAMP PANELS,REAR BOTH FENDERS,TAILGATE,REAR PANEL,REAR BUMPER	1,500.00	1 LA	1,500.00	1400
42 REMOVE & REFIX REAR UNDER CARRIAGE	180.00	1 LA	180.00	✓
43 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
44 RUSTPROOFING	120.00	1 LA	120.00	✓
45 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	50.00	1 LA	50.00	✓ 3950
			<u>4,210.00</u>	<u>4,210.00</u>
			Total	S\$ 11,266.04
			Add GST @ 7%	788.62
			Total Amount Payable	<u>S\$ 12,054.66</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

 AUTHORIZED SIGNATURE

Supp

for rear RH tyre #200/5W ✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST: 201001158E RCB NO: 201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department
 WS Ref: TP/AIG/YS
 Claim Type: Third Party
 Accident Date: 15/01/2020
 TP Veh Reg No: SMF4719Z

Estimate No: ES2090054/YISHUN
 Date: 21 Jan 2020
 Policy No: 5076190009-04
 Veh Reg No: SJJG7181J
 Make/Model: HONDA FIT 1.3G A
 Chassis No: GE61082323
 Engine No: L13A4092474
 Reg. Date: 14/07/2008

Estimate Repair Cost to Vehicle No :SJJG7181J

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 REAR SPARE TYRE TOOL SPONGE	220.40	1 PC	220.40	220.40
2 REAR BOOT INNER RUBBER	93.30	1 PC	93.30	93.30
		Less 20%	313.70 62.74	250.96
Special Net				
3 REAR RH TYRE	200.00	1 PC	200.00	200.00
			200.00	120
Total				S\$ 450.96
GST Amount				S\$ 31.57
Total Amount Payable				S\$ 482.53

For Cheng Hoe Motor Pte Ltd

DORLYN LI

 AUTHORISED SIGNATURE

PARTS: 5958.16
 SUPP: 776.32
 SN: 745 + 120 + 48.15
 L: 3950
10997.63
 LS: 8750.2
 PLS CHECK & CONFIRM