

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SJG 7181J
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 15/01/2020

TP Veh Reg No: SMF4719Z

Estimate No: ES2090054/YISHUN

Date: 17 Jan 2020

Policy No: 5076190009-04

Veh Reg No: SJG7181J

Make/Model: HONDA FIT 1.3G A

Chassis No: GE61082323

Engine No: L13A4092474

Reg. Date: 14/07/2008

Not Asstained
61 Imp & ?
Presurvey After Paint

16 days

Estimate Repair Cost to Vehicle No :SJG7181J

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	497.20	1 PC	<i>B1</i> 497.20	✓
2 REAR BUMPER SIDE RETAINERS	16.50	2 PCS	<i>D11</i> 33.00	✓
3 REAR BUMPER CLIPS	3.70	6 PCS	<i>M1</i> 22.20	✓
4 REAR BUMPER TOW COVER	13.00	1 PC	<i>T1</i> 13.00	✓
5 REAR TAILGATE	771.50	1 PC	<i>B1</i> 771.50	✓
6 TAILGATE EMBLEM (FIT)	35.00	1 PC	<i>M1</i> 35.00	✓
7 TAILGATE INNER LOCK	189.90	1 PC	<i>T1</i> 189.90	✓
8 TAILGATE INNER BOARD	<i>D11/B1</i> 100.20	1 PC	100.20	✓
9 TAILGATE OUTER GARNISH	110.60	1 PC	<i>warp</i> 110.60	✓
10 TAILGATE LOGO	27.40	1 PC	<i>M1</i> 27.40	✓
11 REAR WINDSCREEN GLASS	<i>Shattered</i> 1,200.50	1 PC	1,200.50	✓
12 REAR WINDSCREEN GLASS MOULDING	120.80	1 PC	<i>M1</i> 120.80	✓
13 REAR WIPER MOTOR	218.30	1 PC	218.30	?
14 REAR NUMBER PLATE LAMP	48.00	1 PC	48.00	?
15 REAR SPARE TYRE PANEL	737.00	1 PC	<i>B1</i> 737.00	✓
16 REAR SPARE TYRE PANEL INNER TOP BOARD	190.70	1 PC	190.70	?
17 REAR RH FENDER	652.90	1 PC	<i>B1</i> 652.90	✓
18 REAR RH FENDER INNER GARNISH	250.30	1 PC	<i>Return</i> 250.30	✓
19 REAR RH FENDER AIR SCROP GRILLE	28.80	1 PC	<i>M1</i> 28.80	✓
20 REAR RH FENDER INNER SHIELD	28.00	1 PC	<i>T1</i> 28.00	✓
21 REAR RH FENDER GLASS	280.60	1 PC	280.60	?
22 REAR PANEL	276.50	1 PC	<i>B1</i> 276.50	✓
23 REAR PANEL INNER TOP GARNISH	60.80	1 PC	<i>T1</i> 60.80	✓
24 TAILLAMPS	206.50	2 PCS	<i>B1</i> 413.00	✓
25 TAILLAMP PANELS	<i>als?</i> 135.50	2 PCS	<i>als B1</i> 271.00	✓
26 REAR LH FENDER INNER GARNISH	250.30	1 PC	250.30	?
27 REAR EXHAUST PIPE	529.40	1 PC	<i>B1</i> 529.40	✓
28 CENTRE EXHAUST PIPE	506.90	1 PC	506.90	?
			7,863.80	
		Less 20%	1,572.76	6,291.04

Special Net

29 REAR WINDSCREEN GLASS GUM	40.00	1 ROLL	<i>M1</i> 40.00	✓
30 REVERSE SENSOR	200.00	1 SET	<i>Short</i> 200.00	✓
31 REAR NUMBER PLATE	35.00	1 PC	<i>Net</i> 35.00	✓
32 REVERSE CAMERA	380.00	1 PC	380.00	?
33 REAR SPARE PANEL TOP COAT	80.00	1 PC	<i>M1</i> 80.00	<i>60%</i>
34 REAR RH FENDER GLASS GUM	30.00	1 PC	<i>M1</i> 30.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department
 WS Ref: TP/AIG/YS
 Claim Type: Third Party
 Accident Date: 15/01/2020
 TP Veh Reg No: SMF4719Z

Estimate No: ES2090054/YISHUN
Date: 17 Jan 2020
Policy No: 5076190009-04
Veh Reg No: SJG7181J
Make/Model: HONDA FIT 1.3G A
Chassis No: GE61082323
Engine No: L13A4092474
Reg. Date: 14/07/2008

Estimate Repair Cost to Vehicle No :SJG7181J

Description	U/Price	Quantity	List Price	Amount
				S\$
			765.00	765.00
Labour				
35 TOWING (FROM SCENE TO HOME)	70.00	1 LA (Bill)	70.00	?
36 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
37 REMOVE & REFIX REAR RH FENDER GLASS	60.00	1 LA	60.00	50
38 REMOVE & REFIX TOP ROOF LINING,SEAT,GARNISH,ETC	120.00	1 LA	120.00	✓
39 REMOVE & REFIX REAR EXHAUST,STRAIGHTEN CENTRE EXHAUST	80.00	1 LA	80.00	✓
40 REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS,TAILGATE ASSY,CUT,WELD & RENEW REAR END PANEL,TAILLAMP PANELS,REAR RH FENDER,REAR SPARE TYRE COMPARTMENT,KNOCK & REPAIR REAR LH FENDER,REAR BOTH CHASSISS, TOP ROOF PANEL & REALIGN THE SAME	1,850.00	1 LA	1,850.00	1700
41 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT,TAILLAMP PANELS,REAR BOTH FENDERS,TAILGATE,REAR PANEL,REAR BUMPER	1,500.00	1 LA	1,500.00	1400
42 REMOVE & REFIX REAR UNDER CARRIAGE	180.00	1 LA	180.00	✓
43 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
44 RUSTPROOFING	120.00	1 LA	120.00	✓
45 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	50.00	1 LA	50.00	✓
			4,210.00	4,210.00
			Total	S\$ 11,266.04
			Add GST @ 7%	788.62
			Total Amount Payable	S\$ 12,054.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE