

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 27003

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0079/2020/NS
Date	:	21-Jan-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SLX 9407 H

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Choo Swee Kiong
Address	:	24 Bedok North Drive #14-29 Singapore 465498
Telephone	:	(HP) +65 98620101
Type of Claim	:	Third Party Claims
Policy No.	:	1800135487
Vehicle No	:	SFP 5135 G
Model Code	:	Audi Q2 1.0 TFSI S Tronic
Model / Year	:	13/11/2018
Engine No	:	CHZ A90269
Chassis No	:	WAUZZZGA5KA000635
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	16-Jan-20
Place of Accident	:	ECP Near To Bedok Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFP 5135 G

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking iad. Check function and renew according to damage.	S/N	\$ 280.00	
2	To remove and transfer rear lid's convenience lock system, wire harness for tail light and rear wiper assy.	S/N	\$ 480.00	
3	To renew rear windscreen to facilitate lid renewal.	S/N	\$ 480.00	
4	To install rear solar windscreen.	S/N	\$ 400.00	
TOTAL LABOUR CHARGES		:	<u>\$ 1,640.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFP 5135 G

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 480.00	
6	To dismantle and renew rear bumper and rear lid. To cut out and reweld rear end panelling outer and inner. Re-organised crash management components. Reinstall all parts removed.		\$ 4,800.00	
7	To respray rear bumper, hinges, rear lid, end panelling and spare wheel housing.		\$ 4,500.00	
8	To carry out diagnostic check.	S/N	\$ 192.00	
TOTAL LABOUR CHARGES		:	<u>\$ 11,612.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFP 5135 G

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
1	REAR BUMPER	\$ 1,108.00	
2	REAR BUMPER FIXING PARTS	\$ 73.00	
3	REAR BUMPER SPOILER - LH	\$ 268.00	
4	REAR BUMPER TOWING EYE COVER	\$ 41.00	
5	REAR LIGHT REFLECTOR - LH / RH	2 \$ 56.00	
6	REAR BUMPER CARRIER	\$ 517.00	
7	REAR BUMPER HOLDING STRAP - LH / RH	2 \$ 24.00	
8	REAR BUMPER GUIDE SECTION - LH / RH	\$ 102.00	
9	REAR PARKING AID SENSOR - INNER / OUTER	4 TBC	
10	REAR PARKING AID SEAL RING	4 \$ 14.00	
11	REAR BUMPER WIRING SET	\$ 484.00	
12	REAR LID	\$ 2,221.00	
13	REAR LID HINGE	2 \$ 280.00	
14	REAR LID ATTACHMENT PARTS	\$ 113.00	
15	REAR LID LOCK STRIKER	\$ 274.00	
16	FLAP GASKET	\$ 112.00	
17	REAR LID LOCK	\$ 232.00	
18	BONNET LOCK COVER	\$ 12.00	
19	LID LOCK PUSH BUTTON	\$ 170.00	
20	AUDI EMBLEM	\$ 117.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 6,218.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFP 5135 G

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
21	Q2 INSCRIPTION	\$ 90.00	
22	REAR WINDSCREEN	\$ 734.00	
23	PRIMER	\$ 19.00	
24	TAIL LIGHT - LH	\$ 1,245.00	
25	TAIL LIGHT TRIM - LH	\$ 28.00	
26	LED LICENCE PLATE LIGHT	2 \$ 95.00	
27	SPOILER FIXING PARTS	\$ 125.00	
28	CROSS PANEL REINFORCEMENT	\$ 691.00	
29	REAR CROSS PANEL	\$ 231.00	
30	REAR WHEEL COVER - LH / RH	2 \$ 320.00	
31	ACRYLIC SEALANT	S/N \$ 180.00	
32	CAVITY WAX	S/N \$ 140.00	
33	STONE CHIP	S/N \$ 180.00	
34	REAR WINDSCREEN SEALANT	S/N \$ 200.00	
35	REAR NO PLATE	S/N \$ 40.00	
36	SUNDRIES	\$ 400.00	

TOTAL SPARE PARTS CHARGES	:	\$ 10,936.00
TOTAL LABOUR CHARGES	:	\$ 11,612.00
GRAND TOTAL	:	\$ 22,548.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant