

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: FIRST CAPITAL INSURANCE LIMITED	DATE	: 16/01/2020
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJW3563U		Asher
MODEL	: TOYOTA WISH 1.8A		
CHASSIS NO			JTDGJ20W905002456
<u>ACCIDENT DETAILS</u>		DATE	: 15/01/2020
		TIME	: 02:15HRS
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	BONNET <i>new</i>	1	\$ 820.00	\$ 820.00	+
2	FRONT BUMPER <i>Del'd</i>	1	\$ 653.80	\$ 653.80	✓
3	FRONT BUMPER SIDE RETAINER <i>in RH</i>	2	\$ 62.40	\$ 124.80	62.40
4	FRONT BUMPER FOG LAMP <i>new</i>	1	\$ 320.00	\$ 320.00	+
5	FRONT BUMPER FOG LAMP HOUSING <i>new</i>	1	\$ 130.20	\$ 130.20	+
6	HEADLAMP <i>RH cracked</i>	2	\$ 444.60	\$ 889.20	444.60
7	FRONT FENDER RH <i>Distorted</i>	1	\$ 865.00	\$ 865.00	✓
8	FRONT FENDER INNER COWLING RH <i>Del'd</i>	1	\$ 254.00	\$ 254.00	✓
9	FRONT FENDER SIGNAL LAMP RH <i>new</i>	1	\$ 70.00	\$ 70.00	+
10	FRONT FENDER WT-I RH <i>new</i>	1	\$ 80.00	\$ 80.00	65
11	WASHER TANK <i>Del'd</i>	1	\$ 250.00	\$ 250.00	✓
12	WASHER TANK MOTOR <i>new</i>	1	\$ 320.00	\$ 320.00	+
13	FRONT SIDE SKIRT RH <i>Del'd</i>	1	\$ 830.00	\$ 830.00	✓
14	FRONT DOOR RH <i>Distorted</i>	1	\$ 1,288.90	\$ 1,288.90	✓
15	FRONT DOOR HINGE <i>Best</i>	2	\$ 80.00	\$ 160.00	✓
16	FRONT DOOR CHECKER RH <i>new</i>	1	\$ 155.20	\$ 155.20	+
17	FRONT DOOR LOCK <i>new</i>	1	\$ 380.00	\$ 380.00	+
18	REAR DOOR RH <i>Distorted</i>	1	\$ 1,368.00	\$ 1,368.00	✓

19	REAR DOOR HINGE	neu	2	\$ 80.00	\$ 160.00	f
20	REAR DOOR CHECKER RH	neu	1	\$ 155.20	\$ 155.20	f
21	FRONT KNUCLE ARM RH	Repld	1	\$ 489.60	\$ 489.60	✓
22	FRONT KNUCLE BEARING RH	ne	1	\$ 198.90	\$ 198.90	✓
23	FRONT WHEEL HUP RH	Repld	1	\$ 314.80	\$ 314.80	✓
24	FRONT SHOCK ABSORBER RH	Best	1	\$ 478.10	\$ 478.10	✓
25	FRONT LOWER ARM RH	Best	1	\$ 561.70	\$ 561.70	✓
26	FRONT ANTI ROLL BAR LINKAGE RH	Best	1	\$ 194.30	\$ 194.30	✓
27	FRONT ABS SENSOR	neu	1	\$ 260.00	\$ 260.00	f
28	STEERING RACK AND PINION	neu	1	\$ 1,855.30	\$ 1,855.30	f
29	FRONT DRIVESHAFT	neu	1	\$ 1,258.70	\$ 1,258.70	f

8479.10
6359.32

TOTAL PRICE \$ 14,885.70
LESS 25% \$ 3,721.43
SUB TOTAL PRICE \$ 11,164.28

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP(SET)	1	\$ 20.00	\$ 20.00
2	FRONT FENDER SEALANT RH	1	\$ 80.00	\$ 80.00
3	FRONT FENDER COWLING RH CLIP(SET)	1	\$ 20.00	\$ 20.00
4	SIDE SKIRT CLIPS(SET)	1	\$ 20.00	\$ 20.00
4	FRONT WHEEL TYRE RH	1	\$ 350.00	\$ 350.00
5	FRONT WHEEL SPORT RIM RH	1	\$ 850.00	\$ 850.00

660

TOTAL \$ 1,340.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	800.
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	1000
3	WIRING AND BULB CHECK	\$ 120.00	30
4	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x
5	TO REMOCVE AND REFIX FRONT UNDERCARRIAGE	\$ 350.00	220
6	FOUR WHEEL ALIGHMENT	\$ 120.00	80
7	TO REMOVE AND REFIX FRONT DOOR MECHANISM	\$ 450.00	80

	TO REMOVE AND REFIX REAR DOOR 8 MECHANISM	\$ 450.00	80	
--	--	----------------------	----	--

TOTAL

\$5,270.00

2290

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,504.28
TOTAL LABOUR COST : \$ 5,270.00
TOTAL REPAIR COST : \$ 17,774.28

Adrian Lj
L/S 17/01/20

07 Days

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

total: 9309.32
L/S : 7.4K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: