

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 13/1/2020

INSURANCE: CHINA TAIPING

MODEL: HYUNDAI SONATA-I40

MVA: \_\_\_\_\_

VEHICLE NO.: SHA7091Z

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	BOOTLID <i>Dented / St</i>		\$2,174.90	✓
	BOOTLID RUBBER <i>defunct</i>		\$96.50	✓
	BOOTLID HINGE (LH/RH) <i>NH</i>		\$284.60	X
	BOOTLID LOCK UPPER <i>Stc</i>		\$114.90	X
	BOOTLID LOCK LOWER <i>NH</i>		\$23.20	X
	BOOTLID SONATA PLATE <i>NH NF</i>		\$37.90	X
	BOOTLID HYUNDAI PLATE <i>NH NF</i>		\$21.10	X
	BOOTLID 'H' EMBLEM <i>NH</i>		\$22.70	✓
	BOOTLID CRDI PLATE <i>NH</i>		\$27.90	X
	BOOTLID TRIMBOARD <i>NH</i>		\$143.90	X
	BOOTLID TRIMBOARD CLIPS (11 PCS) <i>NH</i>		\$11.00	X
	BOOTLID MOULDING (I40) <i>NH</i>		\$85.00	X
	BOOTLID I40 EMBLEM (I40) <i>NH</i>		\$27.90	X
	BOOTLID LOWER GARNISH (I40) <i>NH</i>		\$227.90	X
	REAR BUMPER <i>Dented</i>		\$1,106.00	✓
	REAR BUMPER REINFORCEMENT BRACKET <i>Dented</i>		\$160.60	✓
	REAR BUMPER REINFORCEMENT <i>crack</i>		\$428.40	✓
	REAR BUMPER CLIP <i>NH</i>		\$19.00	✓
	REAR BUMPER SPONGE <i>thin</i>		\$119.50	✓
	REAR BUMPER UNDER COVER <i>dented / crack</i>		\$228.00	✓
	REAR BUMPER REFLECTOR LAMP (I40) <i>NH</i>		\$32.00	X
	TAIL LAMP (LH/RH) <i>crack</i>	2	\$697.80	✓ \$1,395.60
	TAIL LAMP QUARTER PANEL (LH/RH) <i>NH</i>		\$453.00	X
	REAR PANEL <i>Dented</i>		\$526.70	✓
	REAR PANEL GARNISH <i>widely dented</i>		\$57.70	✓
	SPARE TYRE HOLDER <i>NH</i>		\$223.10	X
	TAIL LAMP PANEL TOP (LH/RH) <i>NH</i>		\$189.10	X
	SPARE TYRE PANEL <i>NH</i>		\$852.80	X
	SPARE TYRE PANEL CUSHION <i>NH</i>		\$223.10	X
	REAR PANEL INNER PANEL (I40) <i>NH</i>		\$380.00	X
	EXHAUST PIPE INSULATOR <i>NH</i>		\$117.10	X
	EXHAUST SILENCER <i>NH</i>		\$1,935.40	X
	EXHAUST PIPE HANGER <i>NH</i>		\$117.10	X
	BONNET <i>NH</i>		\$2,265.90	X
	BONNET LOCK <i>NH</i>		\$42.40	X
	BONNET SEAL <i>NH</i>		\$31.90	X
	BONNET INSULATOR CLIPS <i>NH</i>		\$7.00	X
	RADIATOR GRILLE H EMBLEM <i>NH</i>		\$39.50	✓
	RADIATOR GRILLE <i>broken</i>		\$1,480.00	✓
	FRONT BUMPER COVER <i>dented / widely crack</i>		\$1,052.20	✓
	FRONT BUMPER SPONGE <i>thin</i>		\$99.20	✓
	FRONT BUMPER REINFORCEMENT <i>Dented</i>		\$438.40	✓

FRONT BUMPER GRILLE (LH/RH) <i>NH</i>	2	\$49.20	X	\$98.40
FRONT BUMPER BRACKET TOP (LH/RH) <i>NH</i>		\$44.80	X	
FRONT BUMPER CENTRE GRILLE TOP GARNISH (I40) <i>NH</i>		\$32.00	X	
FRONT BUMPER BRACKET (LH/RH) <i>NH</i>		\$49.20	X	
FRONT BUMPER SIDE BRACKET <i>NH</i>		\$4.60	X	
FRONT BUMPER RETAINER MOUNTING <i>NH</i>		\$8.00	X	
HEADLAMP SUPPORT PANEL ASSY <i>2 1st</i>		\$907.40	<del>X</del> ✓	
HEADLAMP (LH/RH) <i>crack mounty</i>	2	\$2,776.00	✓	\$5,552.00 <i>photo</i>
HEADLAMP SUPPORT TOP COVER <i>NH</i>		\$222.60	X	
HEADLAMP HALOGEN BULB (LH/RH) <i>NH</i>		\$28.80	X	
RADIATOR <i>NH</i>		\$708.50	X	
RADIATOR GUARD <i>NH</i>		\$35.00	X	
HORN UNIT (LH/RH) <i>NH</i>		\$72.30	X	
HORN WIRE <i>NH</i>		\$156.60	X	
AIRCON CONDENSER <i>2 1st</i>		\$947.80	<del>X</del> ✓	
<i>14076-10</i>				
<i>11260-88</i>				
SUB TOTAL		\$26,188.10		
LESS 20%		\$5,237.62		
DISCOUNTED TOTAL		\$20,950.48		
BOOTLID COMFORT LOGO & TEL NO. STICKER SN <i>NH</i>		\$16.60	✓	
FRONT NUMBER PLATE SN <i>crack</i>		\$30.00	✓	
FRONT NO PLATE TRIM COVER SN <i>1st</i>		\$30.00	✓	
REAR BUMPER MAT SN <i>NH</i>		\$50.00	✓	
REAR BUMPER REVERSE SENSOR SN <i>Dam</i>		\$118.00	✓	
SUB TOTAL		\$244.60		
<b>Labour Charge</b>				
Panel Beating		\$1,600.00	<i>700/-</i>	
Spray Painting Charge		\$1,800.00	<i>700/-</i>	
Wiring Charge		\$120.00	<i>30/-</i>	
Tuff Kote		\$150.00	<i>40/-</i>	
Towing Charge		\$50.00	<i>NH</i>	
Remove/Refix Reverse Sensor		\$120.00	<i>40/-</i>	
Remove/Refix Exhaust Pipe		\$80.00	<i>NH</i>	
Front/Four Wheel Alignment		\$120.00	<i>NH</i>	
Remove/Refix Radiator		\$90.00	<i>NH</i>	
Remove/Refix Aircon & Refill Gas		\$130.00	<i>80/-</i>	
<i>13080-48</i>		TOTAL LABOUR	\$4,260.00	
<i>4/5 10400/-</i>		ESTIMATE TOTAL	\$25,455.08	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after

15/01/2020 @ 1508hrs

*Not Actual 9 days.*  
*2/sum*

*P*

*yan*

*LKK Auto*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: