

ASS. REC. BY:

REF: CS/CT20001160/Wf3

Special Instruction:

Surveyor: marcus

ASSIGNMENT (Office)

From (Person): Tan Kah Leong

of 091

Date/Time: 20. Jan. 2020 11.05 a.m.

~~Estimated Cost:~~

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: **FBI 709E**

Insured:

YN 6065D

at Workshop m/s Ban Hock Hin

Tel: 62816520

of NO 6 Defu lan 4

Policy No: DMCRSN/190859/19000

Claim No: SYM 20D 200 366C 02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 11.1.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 20-1-2020 11:42 AM

Person Contacted: Hashiana

Vehicle ~~IN~~ OUT[illegible]

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

C711

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FB8709E
at Workshop m/s 344
of _____

Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 7k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: net 2657

Veh No: FB8709E Yr Regn: 11 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: PIAGGIO VESPA c.c. 198

Colour: S. her A/C: Insured / Std / NI / NA

Sp. Reading: 75355 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZAPM 31200000 24142

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 100-70-12
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or metreker

Front 6 Rear 6

R/Bal. mm R/Bal. mm

L/Bal. mm L/Bal. mm

D.O.A. 11/1/20 D.O.I. 20/1/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

see 14-11-2026 17A 4343

2/2/20 confirmed 1/5 @ 1300 with Raymond (Red 1081,45%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 7/7/20-Typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$) \$ + RS, \$ SI

☐

: Interview (\$) Photos

☐

: Tech. Invs (\$) Others

☐

: Weekend (\$)

Report Format : Merimen

Lump Sum / ~~L.B.~~: (\$ 1300)

TOTAL



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

Customer :

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534
CHINA TAIPING INSURANCE (S) PTE LTD

VEHICLE NO. : FBB0709E
MAKE/MODEL : PIAG / VESPA GT200A

QUOTATION

NO. : 35490

DATE : 16/01/2020
CLAIM NO. : 11488
POLICY NO. : MC/00602375
FROM : HASRIANAH

*not Allred
all
d/s = 1300
Hdy.
20/1/20
the price has to be*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BEADING WINDSHIELD LH P/N: 26854	REPLACE	1.00	\$63.00	63.00
2	BEADING WINDSHIELD RH P/N: 30066	REPLACE	1.00	\$42.00	42.00
3	BRACKET (RAM) DOUBLE SOCKET (SHORT) 2.38" P/N: 46441	REPLACE	1.00	\$38.00	38.00
4	BRACKET (RAM) U-BOLT ZINC COATED 0.5 TO 1.25" P/N: 59540	REPLACE	1.00	\$38.00	38.00
5	COVER LEG SHIELD FRONT (PRIMED)	REPLACE	1.00	\$268.00	268.00
6	COVER MASTER CYLINDER PUMP LH	REPLACE	1.00	\$19.00	19.00
7	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	Supply/Install	10.00	\$63.00	630.00
8	LEVER BRAKE P/N: 27992	REPLACE	2.00	\$35.00	70.00
9	LOGO (GRANTURISMO) P/N: 45573	REPLACE	1.00	\$38.00	38.00
10	LOGO (VESPA) P/N: 45239	REPLACE	1.00	\$35.00	35.00
11	LOGO (VESPA) BIG P/N: 34447	REPLACE	1.00	\$38.00	38.00
12	MIRROR LH P/N: 41228	REPLACE	1.00	\$113.00	113.00
13	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$24.00	24.00

*35490 *

biSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0363
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
14	PROTECTOR EXHAUST P/N: 49818	REPLACE	1.00	\$68.00	68.00 ✓
15	SPRAY PAINT WHOLE BIKE	Spray	1	\$812.00	812.00 ✓
16	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1	\$19.00	19.00 10
17	X-GRIP (RAM) UNIVERSAL (STANDARD) P/N: 46452	REPLACE	1.00	\$66.00	66.00 ✓
SUB TOTAL					\$2,381.00
GST @ 7 %					\$166.67
GRAND TOTAL					\$2,547.67

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



HASRIANAH

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7861
11898
134

*35490 *

bizSAFE₃

