

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20001160/UVF3E2

Date: 13/07/2020

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN19085919000

Claimant Vehicle  
No : FBB709EInsured Vehicle  
No : YN6065D

Date of Loss: 11/01/2020

Nature of Claim: TP

Claim  
No: SNM20D200366C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBB709E

Make &amp; Model: PIAGGIO VESPA GT200A, 198cc

Engine No: M312M24422

Reg. Date: 15/11/2006 (Man. Year: 2005)

Chassis No: ZAPM3120000024142

Colour: Silver

Odometer: 75355 km

Engine Capacity: 198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	100-70-12	Rear Tyre Size:	100-70-12
Front Left Side:	Metzeler 6 mm	Rear Left Side:	Metzeler 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	939.00	799.90	139.10	14.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,442.00	860.00	582.00	40.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,381.00</b>	<b>1,659.90</b>	<b>721.10</b>	<b>30.29</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,300.00</b>		
<b>(S\$)</b>	2,381.00	1,300.00	1,081.00	45.40
<b>+ GST 7.00/7.00% (S\$)</b>	166.67	91.00	75.67	45.40
<b>Nett Amount (S\$)</b>	<b>2,547.67</b>	<b>1,391.00</b>	<b>1,156.67</b>	<b>45.40</b>

### INSPECTION

Date of Assignment: 20/01/2020

Date Inspected: 20/01/2020 Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)  
No. 6 Defu Lane 4  
Singapore 539410

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 12 Jul 2020)	
<b>Parts:</b>	N/A	PIAGGIO VESPA GT200A 198cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBB709E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BEADING WINDSHIELD LH	Scratched	63.00 F	*63.00 FL
2	1		*BEADING WINDSHIELD RH	Scratched	42.00 F	*42.00 FL
3	1		*BRACKET (RAM) DOUBLE SOCKET (SHORT) 2.38	Bent	38.00 F	*38.00 FL
4	1		*BRACKET (RAM) U-BOLT ZINC COATED 0.5 TO 1.25	Bent	38.00 F	*38.00 FL
5	1		*COVER LEG SHIELD FRONT (PRIMED)	Cracked	268.00 F	*268.00 FL
6	1		*COVER MASTER CYLINDER PUMP LH	Missing	19.00 F	*19.00 FL
7	1		*LEVER BRAKE	N/S Scratched	70.00 F	*35.00 FL
8	1		*LOGO (GRANTURISMO)	Necessary	38.00 F	*38.00 FL
9	1		*LOGO (VESPA)	Necessary	35.00 F	*35.00 FL
10	1		*LOGO (VESPA) BIG	Necessary	38.00 F	*38.00 FL
11	1		*MIRROR LH	Cut	113.00 F	*113.00 FL
12	1		*PLATE NUMBER REAR (6.5 INCH X 9 INCH)	Cracked	24.00 FS	*15.00 FS
13	1		*PROTECTOR EXHAUST	Cracked	68.00 F	*68.00 FL
14	1		*STICKER NUMBER PLATE FRONT (BLACK)	Necessary	19.00 FS	*10.00 FS
15	1		*X-GRIP (RAM) UNIVERSAL (STANDARD)	Damaged	66.00 F	*66.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>939.00</b>	<b>886.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	86.10
<b>Total Parts (\$\$)</b>	<b>939.00</b>	<b>799.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	New	630.00	380.00
2	SPRAY PAINT WHOLE BIKE	New	812.00	480.00
<b>Gross Labour Cost (S\$)</b>			<b>1,442.00</b>	<b>860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >