

ASS. REC. BY:

REF: CS/IAIG 2000/1167/Ht 4302

Special Instruction:

Surveyor: Flick, mm **ASSIGNMENT (Office)**From (Person): Subharnish Dnyashni of ALG Date/Time: 20.1.20 1.50p.m

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: PB A 991K Insured: SGZ 7923Xat Workshop m/s O.M motor Services Tel: 87990940 → Johnof 10 Kaki Bukit Road 2 #10136Policy No: _____ Claim No: 7096227552SG

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 13.1.2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 20.1.20 1.58p.m Person Contacted: MS Lim

H.O.D. Endorsement: _____

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SGZ 7923X X
	PBA 991K X
21/1/20	→ survey taken
31/1/20	→ survey taken
1/1	→ after party workshop up to

ASSIGNMENT

From: _____ Date: 21 Jan. 2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FBA 991K

at Workshop n/s: O.M motor services

of 10 Kari Bukit Rd 2 #036

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: After 12:00 p.m.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBA 991K Yr Regn: 26/1/2016

Type: M.Car (M.Cycle) Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda CR 450 cc 399

Colour: Silver/White AC: Insured / Std / NI / NA

Sp. Reading: 167180/km T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JH2NC 399 43 m 100 785

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/60/2R17

R: 160/60/2R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 5 mm Rear: 5 mm

R/Bal: 5 mm L/Bal: 5 mm

L/Bal: mm L/Bal: mm

D.O.A. 13/1/20 D.O.I. 21/1/20

Survey held at: O.M motor services

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

rpt Days - 3 days
DAR - / on* FBA 991K
LPRS case

Submit DAR Report

MV - 11000

PV - 3721

NV - 7200

RECEIVED 05 FEB 2020

Date/Time, File Pass to?

☐ : Prel. Report☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3 + RS \$

Photos

Notes

TOTAL

Report Format: DAR Report

Lump Sum / TR: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

PRE-REPAIR INSPECTION REQUEST – FBA991K vs SGZ7923X (OI) on D.O.A.: 13/01/2020

From: Subramaniam, Divyashni
To: assignments@lkkauto.com, Admin A
Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Hor, Yinrul, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, 'OM Rental'
Sent: Monday, 20 January, 2020 1:50:07 PM

Hi,

Please refer to the enclosed request from VISION LAW LLC.

Claim no : 7096227552SG003
Case Owner : Bennie

If you have any queries/concerns, please let us know.
Kindly assist to assign Xing Guo Qiang as Single Joint Expert as requested.

Thanks & Regards,

Divyashni Subramaniam
AIG
PICOL Adjuster I
Auto Claims | AIG Asia Pacific Insurance Pte. Ltd

Tel: 8001200556 | Ext: 1012103
Divyashni.Subramaniam@aig.com | www.aig.sg

From: Sally Chong <sallychong@visionlawllc.com>
Sent: Monday, January 20, 2020 1:39 PM
To: Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; 'OM Rental' <omrental0136@gmail.com>; ngwingann@gmail.com; 'Judy Soh' <judysoh@visionlawllc.com>
Subject: [EXTERNAL] OUR REF.: 029-112668.20 (FBA 991K @ 13.01.2020) // AIG REF.: 7096227552SG003

This message is from an external sender; be cautious with links and attachments.

VERY URGENT

Dear Divyashni,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: MUHAMMAD RUSTAM BIN MAIDEEN GANI

ACCIDENT INVOLVING FBA 991K & SGZ 7923X ON 13 JAN 2020 ALONG TAMPINES AVE 5 AT ABOUT 20:00 HRS

Thank you for your email of 20 Jan 2020 below.

Our client confirms the appointment of XING GUO QIANG - LKK AUTO CONSULTANTS PTE LTD as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue	O.M. MOTOR SERVICES 10, Kaki Bukit Road 2, #01-36, First East Centre, Singapore 417868
Contact	Mr. John Ng (Tel: 6538-1009 / H/P: 8799-0940)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Sally Chong

(Secretary)
VISION LAW LLC
133 NEW BRIDGE ROAD,
#18-01/02, CHINATOWN POINT,
SINGAPORE 059413
TEL: 6534-2811 (ext 115)
FAX: 6535-6802

From: Subramaniam, Divyashni
Sent: Mon, 20 Jan 2020 03:21:23 +0000
To: Sally Chong
Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Hor, Yinrul, Lim, Sheng Yang, Mithoosingh,

Aashweenjeetkaur, Parthiban, Theerthan

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGZ7923X AND FBA991K ON 13/01/2020

www.aig.sg

From: Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>

Sent: Friday, January 17, 2020 10:32 AM

To: Sally Chong <sallychong@visloriaawllr.com>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Hor, Yinnul <Yinnul.Hor@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>

Subject: sigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGZ7923X AND FBA991K ON 13/01/2020

Without Prejudice

Your Reference : FBA991K

Our Reference : 7096227552SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Divyashni Subramaniam

AIG

PNOL Adjuster I

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 800120556 (Ext: 1012103)

Divyashni.Subramaniam@aig.com | www.aig.sg

From: Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
 Sent: Friday, January 17, 2020 10:32 AM
 To: Sally Chong <sallychong@visionlawllc.com>
 Cc: Fong, Andy-SY <andy-sy.fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariessa <NoorMariessa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Hor, Vinrul <vinrul.hor@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithooosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithooosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
 Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGZ7923X AND FBA991K ON 13/01/2020

Without Prejudice

Your Reference : FBA991K

Our Reference : 709622755250003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Kean (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Qun Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Raul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Divyashni Subramaniam

AIG

PNOL Adjuster

Auto Claims / AIG Asia Pacific Insurance Pte. Ltd.

Tel : 8001290068 | Ext : 1012100

Divyashni.Subramaniam@visionlawllc.com

From: Sally Chong [mailto:sallychong@visionlawllc.com]
 Sent: Friday, 17 January, 2020 1:43 PM
 To: 'OM Rental'; 'ngwingann@gmail.com'
 Subject: FW: OUR REF.: 029-112668.20 (FBA 991K @ 13.01.2020) // AIG REF.: 70962275525G003

Dear John/Ms. Lin,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: MUHAMMAD RUSTAM BIN MAIDEEN GANI

ACCIDENT INVOLVING FBA 991K & SGZ 7923X ON 13 JAN 2020 ALONG TAMPINES AVE 5 AT ABOUT 20:00 HRS

Please advise on surveyor as follows:-

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Razul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Tks!

Sally Chong

(Secretary)
 VISION LAW LLC
 133 NEW BRIDGE ROAD,
 #18-01/02, CHINATOWN POINT,
 SINGAPORE 059413
 TEL: 6534-2811 (ext 115)
 FAX: 6535-6802

From: Subramaniam, Divyashni
 Sent: Fri, 17 Jan 2020 02:32:08 +0000
 To: Sally Chong
 Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Hor, Yinrui, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni
 Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGZ7923X AND FBA991K ON 13/01/2020

Without Prejudice

Your Reference : FBA991K

Our Reference : 70962275525G003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd

Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Muhammad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Divyashree Subramaniam

AIG

FNOL Adjuster I

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 8001206556 | Ext: 1012103

Divyashree.Subramaniam@aig.com www.aig.sg

From: Sally Chong (<mailto:sallychong@visionlawllc.com>)

Sent: Friday, 17 January, 2020 10:12 AM

To: Yinru.Hon@aig.com; 'Azlan, Syazairdina'; Lee-Ying.Chin@aig.com; AIGSGP_ClaimsSurvey@aig.com; 'Lim, Sheng Yang'

Cc: 'OM Rental'; ngwinnan@gmail.com; 'Leong, Kah Yin'; 'Hassim, Mohd Fitri'; 'Abu Kassim, Noor Mariesa'; 'Md Ishak, Mohd Imran'; judysoh@visionlawllc.com

Subject: OUR REF.: 029-MISC.20 (FBA 991K @ 13.01.2020) // AIG REF.: SGZ 7923X

Importance: High

VERY URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NEMA CASES

CLAIMANT: MUHAMMAD RUSTAM BIN MAIDEEN GANI

ACCIDENT INVOLVING FBA 991K & SGZ 7923X ON 13 JAN 2020 ALONG TAMPINES AVE 5 AT ABOUT 20:00 HRS

We are instructed by MUHAMMAD RUSTAM BIN MAIDEEN GANI to notify you of a road traffic accident ON 13 JAN 2020 ALONG TAMPINES AVE 5 AT ABOUT 20:00 HRS involving our client's vehicle registration number FBA 991K and vehicle registration number SGZ 7923X driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

Sally Chong

(Secretary)
VISION LAW LLC
133 NEW BRIDGE ROAD,
#18-01/02, CHINATOWN POINT,
SINGAPORE 059413
TEL: 6534-2811 (ext 115)
FAX: 6535-6802

C.c.: VEHICLE OWNER OF SGZ 7923X
POK EE
169, Tanah Merah Kechil Ave,
Singapore 465712

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Address: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Address : 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

From: Divyashri Subramaniam <divyashri@visionlawllc.com>

To: sallychong@visionlawllc.com

Cc: Andy-SY Fong <andy@visionlawllc.com>, Winnie-LW Fan <winnie@visionlawllc.com>

Subject: **URGENT PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGZ7923X AND FBA991K ON 13/01/2020**

Date: Fri, 17 Jan 2020 02:32:08 +0000

Without Prejudice

Your Reference : FBA991K

Our Reference : 7096227552SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Ning Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasol	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Divyashri Subramaniam

AIG

Title: Adjuster I

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 8001200006 / Ext: 1012103

divyashri.subramaniam@aig.com | www.aig.sg

From: Sally Chong <sallychong@visionlawllc.com>

Sent: Friday, January 17, 2020 10:12 AM

To: Hor, Yirul <yirul.hor@aig.com>; Azlan, Syazairidina <Syazairidina.Azlan@aig.com>; Chin, Lee-Ying <Lee.Ying.Chin@aig.com>; AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>

Cc: 'OM Rental' <omrental0136@gmail.com>; Leong, Kah Yin Hidden on 03-09-2017, 03:47:55 <KahYin.Leong@aig.com>; 'Hassim, Mohd Fitri' <MohdFitri.Hassim@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; 'Md Ishak, Mohd Imran' <imran.ishak@aig.com>; jaydysph@visionlawllc.com

Subject: [EXTERNAL] OUR REF.: O29-MISC.20 (FBA 991K @ 13.01.2020) // AIG REF.: SGZ 7923X

Importance: High

This message is from an external sender; be cautious with links and attachments.

VERY URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: MUHAMMAD RUSTAM BIN MAIDEEN GANI

ACCIDENT INVOLVING FBA 991K & SGZ 7923X ON 13 JAN 2020 ALONG TAMPINES AVE 5 AT ABOUT 20:00 HRS

We are instructed by MUHAMMAD RUSTAM BIN MAIDEEN GANI to notify you of a road traffic accident ON 13 JAN 2020 ALONG TAMPINES AVE 5 AT ABOUT 20:00 HRS involving our client's vehicle registration number FBA 991K and vehicle registration number ~~SGZ~~ 7923X driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

Sally Chong

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL: 6534-2811 (ext 115)

FAX: 6535-6802

C.c.: VEHICLE OWNER OF SGZ 7923X

POK EE

169, Tanah Merah Kechil Ave,

Singapore 465712

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Address : 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

Advertisement

Home > Motorbikes



DOR - 13/1/20

MV - 11000
 PV - 3721
 NV - 7200

Advertisement



fazstarksky

★★★★★ 13

Sold

S\$12,000

Share

Honda CB400 Super Four (4) Spec 3 Coe Ending 2025

Tampines

Meetup

Used

Got this bike from a fellow Super 4 kaki for 12k last year. It is only used from Monday to Friday, mainly to and from work (approx 50km daily). Initially when I bought from him, the bike is fully stock. Thinking I would ride this forever, these are the changes I've made in the year:

- 1) helmet (sgd 60)
- 2) Brembo clutch and brake lever and Rizoma brake reservoir (sgd 700)
- 3) HEL brake hose (can't remember)
- 4) Yoshimura titanium blue end can (sgd 950)
- 5) Rizoma grip and balancer (sgd 180)
- 6) new seat with added gel (\$200)
- 7) anti theft nuts for front brake caliper and suspension (100 for 4)
- 8) anti theft nuts for Rizoma brake reservoir (sgd 25)
- 9) slider (sgd 20)
- 10) Radiator cover (sgd 25)
- 11) electrical grounding (sgd 40)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	199B
Vehicle Details	
Vehicle No.:	FBA991K
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jan 2020
Vehicle Make:	HONDA
Vehicle Model:	CB400
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	NC23E3000306
Chassis No.:	JH2NC39945M100285
Maximum Power Output:	-
Open Market Value:	\$6,855.00
Original Registration Date:	26 Jan 2006
First Registration Date:	26 Jan 2006
Transfer Count:	6
Actual ARF Paid:	\$1,029.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$6,265.00
COE Rebate Amount:	\$3,721.00
Total Rebate Amount:	\$3,721.00

The information contained herein is correct as at 22 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/01/2020 14:16
Date Of Accident	13/01/2020 20:00
Exact Location Of Accident	TAMPINES AVE 05/ TAMPINES 04 (SLIP RD)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBA991K
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD RUSTAM BIN MAIDEEN GANI
NRIC No	SXXXX199B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90936955
Alternative Phone No	OTHERS-90936955

Vehicle Particulars

Manufacturer	HONDA
Model	HONDA / CB400
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5075961335-03
Cover Note Number	

Driver

Name of Driver	PRASAD S/O ARUNASALAM
NRIC No	SXXXX849E
Date Of Birth	05/02/1988
Occupation	OUTDOOR
Date Of Driving Pass	11/12/2009
Driving Experience	10 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-84880502
Fax Number	
Contact Number	
EMail Address	SAFETYARUN1988@GMAIL.COM

Address	BLK 842E TAMPINES STREET 82 #02-122
Postcode	525842
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES N.P.C
Police Station Address	ROAD: TAMPINES N.P.C , POSTCODE: 529682 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20200114/2061;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGZ7923X
Vehicle Make/Model/Colour	SUBARU / 2.5 WRX
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	PRASAD S/O ARUNASALAM
Approximate Age	31
Injuries Sustain	
Injured person in which vehicle?	FBA991K
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 842E TAMPINES STREET 82 #02-122
Postcode	525842

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(if driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vacom.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No: 15 JAN 2020

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

[Large handwritten signature]

Safetyaran1988@gmail.com

DECLARATION

✓We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
25 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416897 Fax: 67492305
Email: vackb@vicom.com.sg
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GMAT/C SketchPlanForm_V9

15 JAN 2020



SINGAPORE POLICE FORCE



T/20200114/2061

1 of 4

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20200114/2061

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/01/2020 13:56		Vide Report No.:		Station Diary No.: 101	
Informant's Particulars					
Name of Informant: PRASAD S/O ARUNASALAM			Address: APT BLK 842E TAMPINES STREET 82 #02-122 SINGAPORE 525842		
ID Type / ID No.: NRIC NO / S8803849E / 1336			Contact No.: Home/Office: Mobile: 84880502		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 31	Date of Birth: 05/02/1988	Type of Informant: Rider		
Race: Indian			Language:		Institution / School Name:
Occupation: SAFETY COORDINATOR			Driving Licence Information: Class: 2B,2A,2 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 13/01/2020 20:00	Type of Location: Bend
Location: Along Road 1 Traveling Toward Road 2 TAMPINES AVENUE 5 TAMPINES AVENUE 4 From Tampines Ave 5, slip road to Tampines ave 4				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBA991K	Motorcycle				Seriously Damaged	0
SGZ7923X	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20200114/2061

CONTINUATION OF REPORT

Rider			
Name	PRASAD S/O ARUNASALAM	ID No.	S8803849E
Related Vehicle	FBA991K (Motorcycle)	Contact No.	84880502
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2 Date of Expiry: NIL
Date Treatment	13/01/2020	Date Discharge	13/01/2020
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Driver			
Name	POK SAI SHEN	ID No.	S7802311B
Related Vehicle	SGZ7923X (Car)	Contact No.	92378580
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 2000hrs, I was riding my bike FBA991K along Tampines Ave 5. At the cross-junction of Tampines Ave 5 and Ave 4, I was on the most left lane, riding on the slip road to turn left into Tampines Ave 4.

While I was stationary at the stop line after the zebra crossing, suddenly something collided from the rear of my bike. I flew from front off from my bike and fell onto the ground face down, with my arms supporting my body. Subsequently, I rested on the ground for a bit before I got up with the help of some of the passerbys.

I also realised that it was SGZ7923X, which collided onto the rear of my bike. The driver then spoke to me for a bit before I called my insurance agent. My insurance agent came down to scene to assist me with the accident and called for police. The ambulance also came along.

I was being checked by the paramedic and I was told that I should be conveyed in case there is any fracture to my right leg. I also informed them that I feel pain at my shoulder and scapular area after the fall as I used them as support when I landed on the ground from the fall.

I was then conveyed to Changi General Hospital by the ambulance. I was given 3 days MC and a week light-duty.

I wish to state that there is a give-way sign at the stop line where I stopped.

So far, I know that my bike's suspension broken, engine leaking, right side signal, light headlight broken, fuel tank scratched, exhaust pipe dented.



SINGAPORE
POLICE FORCE



T/20200114/2061

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

4 of 4

Report No. T/20200114/2061

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 CHIN XUE NI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

14/01/2020 13:56

Officer In Charge Of Case:

TP / GIT /

Sgt 2 HO JIEKANG, IVAN

Contact No.: 65476170

Classification Of Case:

Authentication Stamp
NP168



SINGAPORE
POLICE FORCE

SIGNATURE



**SINGAPORE
POLICE FORCE**



T/20200114/2061

3 of 4

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20200114/2061

CONTINUATION OF REPORT

The other party informed that there is no injury to him.

I do not have any camera on my vehicle.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Jan 2020 Edit Reg		20 Jan 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: POK EE , ID: S0481137B									
Main Claimant: MUHAMMAD RUSTAM BIN MAIDEEN GANI									
Vehicle Reg. No.: FBA991K		Date of Loss: 13/01/2020 00:00 - :59 [167 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 7096227552SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SGZ7923X		Policy No. (Claimant):							
		Excess:							
Repairer: O.m. Motor Services (HQ) 10 KAKI BUKIT ROAD 2, #01-36, 417868 Kaki Bukit - Tel: 87990940									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chew, Mavis] Chew.Mavis@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 30/01/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_5G (21/01/2020): TP GIA report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBA991K (7096227552SG)
[SGZ7923X]

TP

MUHAMMAD RUSTAM BIN MAIDEEN GANI

Jan 13 2020 12:00AM

[POK EE]

O.m. Motor Services

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	22/01/20 09:38	Chassis Number				 Load JPG	☒
2	22/01/20 09:38	Odometer Reading				 Load JPG	☒
3	22/01/20 09:39	General View				 Load JPG	☒
4	22/01/20 09:39	General View				 Load JPG	☒
5	22/01/20 09:39	General View				 Load JPG	☒
6	22/01/20 09:39	General View				 Load JPG	☒
7	22/01/20 09:39	General View				 Load JPG	☒
8	22/01/20 09:39	General View				 Load JPG	☒
9	22/01/20 09:39	General View				 Load JPG	☒
10	22/01/20 09:39	General View				 Load JPG	☒
11	22/01/20 09:39	General View				 Load JPG	☒
12	22/01/20 09:39	General View				 Load JPG	☒
13	22/01/20 09:39	General View				 Load JPG	☒
14	22/01/20 09:39	General View				 Load JPG	☒
15	22/01/20 09:39	General View				 Load JPG	☒
16	22/01/20 09:39	General View				 Load JPG	☒
17	22/01/20 09:39	General View				 Load JPG	☒
18	22/01/20 09:39	General View				 Load JPG	☒
19	22/01/20 09:39	General View				 Load JPG	☒
20	22/01/20 09:39	General View				 Load JPG	☒
21	22/01/20 09:39	General View				 Load JPG	☒
22	22/01/20 09:39	General View				 Load JPG	☒
23	22/01/20 09:39	General View				 Load JPG	☒
24	22/01/20 09:39	General View				 Load JPG	☒
25	22/01/20 09:39	General View				 Load JPG	☒
26	22/01/20 09:39	General View				 Load JPG	☒
27	22/01/20 09:39	General View				 Load JPG	☒
28	22/01/20 09:39	General View				 Load JPG	☒
29	22/01/20 09:39	General View				 Load JPG	☒
30	22/01/20 09:39	General View				 Load JPG	☒
31	22/01/20 09:39	General View				 Load JPG	☒
32	22/01/20 09:39	General View				 Load JPG	☒
33	22/01/20 09:39	General View				 Load JPG	☒
34	22/01/20 09:39	General View				 Load JPG	☒
35	22/01/20 09:39	General View				 Load JPG	☒
36	22/01/20 09:39	General View				 Load JPG	☒
37	22/01/20 09:39	General View				 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/01/20 09:39	General View	 Load JPG	☒
39	22/01/20 09:39	General View	 Load JPG	☒
40	22/01/20 09:39	General View	 Load JPG	☒
41	22/01/20 09:39	General View	 Load JPG	☒
42	22/01/20 09:39	General View	 Load JPG	☒
43	22/01/20 09:39	General View	 Load JPG	☒
44	22/01/20 09:39	General View	 Load JPG	☒
45	22/01/20 09:39	General View	 Load JPG	☒
46	22/01/20 09:39	General View	 Load JPG	☒
47	22/01/20 09:39	General View	 Load JPG	☒
48	22/01/20 09:39	General View	 Load JPG	☒
49	22/01/20 09:39	General View	 Load JPG	☒
50	22/01/20 09:39	General View	 Load JPG	☒
51	22/01/20 09:39	General View	 Load JPG	☒
52	22/01/20 09:39	General View	 Load JPG	☒
53	22/01/20 09:39	General View	 Load JPG	☒
54	22/01/20 09:39	General View	 Load JPG	☒
55	22/01/20 09:39	General View	 Load JPG	☒
56	22/01/20 09:39	General View	 Load JPG	☒
57	22/01/20 09:39	General View	 Load JPG	☒
58	22/01/20 09:39	General View	 Load JPG	☒
59	22/01/20 09:39	General View	 Load JPG	☒
60	22/01/20 09:39	General View	 Load JPG	☒
61	22/01/20 09:39	General View	 Load JPG	☒
62	22/01/20 09:39	General View	 Load JPG	☒
63	22/01/20 09:40	General View	 Load JPG	☒
64	22/01/20 09:40	General View	 Load JPG	☒
65	22/01/20 09:40	General View	 Load JPG	☒
66	22/01/20 09:40	General View	 Load JPG	☒
67	22/01/20 09:40	General View	 Load JPG	☒
68	22/01/20 09:40	General View	 Load JPG	☒
69	22/01/20 09:40	General View	 Load JPG	☒
70	22/01/20 09:40	General View	 Load JPG	☒
71	22/01/20 09:40	General View	 Load JPG	☒
72	22/01/20 09:40	General View	 Load JPG	☒
73	22/01/20 09:40	General View	 Load JPG	☒
74	22/01/20 09:40	General View	 Load JPG	☒
75	22/01/20 09:40	General View	 Load JPG	☒
76	22/01/20 09:40	General View	 Load JPG	☒
77	22/01/20 09:40	General View	 Load JPG	☒
78	22/01/20 09:40	General View	 Load JPG	☒
79	22/01/20 09:40	General View	 Load JPG	☒
80	22/01/20 09:40	General View	 Load JPG	☒
81	22/01/20 09:40	General View	 Load JPG	☒
82	22/01/20 09:40	General View	 Load JPG	☒
83	22/01/20 09:40	General View	 Load JPG	☒
84	22/01/20 09:40	General View	Load JPG	☒
85	22/01/20 09:40	General View	Load JPG	☒
86	22/01/20 09:40	General View	Load JPG	☒
87	22/01/20 09:40	General View	Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
89	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
90	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
91	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
92	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
93	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
94	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
95	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
96	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
97	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
98	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
99	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
100	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
101	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
102	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
103	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
104	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
105	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
106	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
107	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
108	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
109	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
110	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
111	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
112	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
113	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
114	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
115	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
116	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
117	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
118	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
119	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
120	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
121	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
122	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
123	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
124	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
125	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
126	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
127	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
128	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
129	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
130	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
131	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
132	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
133	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
134	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
135	03/02/20 09:49	Reinspection Photo	 Load JPG	☒
136	03/02/20 09:50	Reinspection Photo	 Load JPG	☒
137	03/02/20 09:50	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	03/02/20 09:50	Reinspection Photo	 Load JPG	☒
139	03/02/20 09:50	Reinspection Photo	 Load JPG	☒
140	03/02/20 09:50	Reinspection Photo	 Load JPG	☒
141	03/02/20 09:50	Reinspection Photo	 Load JPG	☒
142	03/02/20 09:50	Reinspection Photo	 Load JPG	☒
143	03/02/20 09:50	Reinspection Photo	 Load JPG	☒
144	03/02/20 09:50	Reinspection Photo	 Load JPG	☒
145	03/02/20 09:50	Reinspection Photo	 Load JPG	☒
146	03/02/20 09:50	Reinspection Photo	 Load JPG	☒
147	03/02/20 09:50	Reinspection Photo	 Load JPG	☒
148	03/02/20 09:50	Reinspection Photo	 Load JPG	☒
149	03/02/20 09:50	Reinspection Photo	 Load JPG	☒
150	03/02/20 09:50	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/02/20 16:02	Police Report	 Load PDF	
2	05/02/20 16:02	Singapore Accident Statement	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/01/20 15:28	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer. Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20001167/HTF3E2

Date: 07/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBA991K

Insured Vehicle No : SGZ7923X

Date of Loss: 13/01/2020

Nature of Claim: TP

Claim No: 7096227552SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBA991K

Make & Model: HONDA CB 400 F3WYB, 399cc (M)

Engine No: NC23E3000306

Reg. Date: 26/01/2006 (Man. Year: 2005)

Chassis No: JH2NC39945M100285

Colour: Blue/Silver

Odometer: 169180 km

Engine Capacity: 399 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60Z R17

Rear Tyre Size:

160/60Z R17

Front Left Side: Michelin 5 mm

Rear Left Side:

Michelin 5 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/01/2020

Date Inspected: 21/01/2020 Inspected At:

O.m. Motor Services (HQ)

10 KAKI BUKIT ROAD 2, #01-36

Singapore 417868

Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	0.00 F	*-F
2	1		*FRONT FORK ASSY	Repair	0.00 F	*-F
3	1		*FRONT HEADLAMP	Cracked	0.00 F	*-F
4	1		*FRONT HEADLAMP BRACKET	Repair	0.00 F	*-F
5	1		*FRONT HEADLAMP FAIRING	Scratched	0.00 F	*-F
6	1		*FRONT WING MIRROR	Scratched	0.00 F	*-F
7	1		*FRONT RH SIGNAL LAMP	Cracked	0.00 F	*-F
8	1		*METER CASING	Cracked	0.00 F	*-F
9	1		*COWLING STAY	Repair	0.00 F	*-F
10	1		*STEERING STEM	Repair	0.00 F	*-F
11	1		*STEERING CONE	Repair	0.00 F	*-F
12	1		*HANDLE BAR	Bent	0.00 F	*-F
13	1		*HANDLE BAR BALANCER LH	Scratched	0.00 F	*-F
14	1		*HANDLE BAR BALANCER RH	Scratched	0.00 F	*-F
15	1		*FUEL TANK	Bent	0.00 F	*-F
16	1		*CLUTCH LEVER	Bent	0.00 F	*-F
17	1		*HAND BRAKE LEVER R/H	Scratched	0.00 F	*-F
18	1		*SIDE FAIRING TOP GARNISH	Repair	0.00 F	*-F
19	1		*SIDE FAIRING INNER GARNISH	Repair	0.00 F	*-F
20	1		*FAIRING SHIELD	Repair	0.00 F	*-F
21	1		*FRONT TOP FAIRING INNER GARNISH	Repair	0.00 F	*-F
22	1		*FAIRING TOP GARNISH	Repair	0.00 F	*-F
23	1		*RADIATOR	Bent	0.00 F	*-F
24	1		*RADIATOR COWLING	Scratched	0.00 F	*-F
25	1		*ENGINE CRASH BAR	Bent	0.00 F	*-F
26	1		*FRONT FOOT REST	Bent	0.00 F	*-F
27	1		*FRONT FOOT REST BRACKET	Cracked	0.00 F	*-F
28	1		*REAR FOOT REST	Bent	0.00 F	*-F
29	1		*REAR FOOT REST BRACKET	Bent	0.00 F	*-F
30	1		*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*-F
31	1		*EXHAUST MUFFLER ASSY	Bent	0.00 F	*-F
32	1		*REAR RH SHOCK ABSORBER	Crumpled	0.00 F	*-F
33	1		*REAR BRAKE DISC	Repair	0.00 F	*-F
34	1		*SWING ARM	Bent	0.00 F	*-F
35	1		*REAR BOX	Scratched	0.00 F	*-F
36	1		*REAR BOX BRACKET	Repair	0.00 F	*-F
37	1		*RADIATOR HOSE	Cracked	0.00 F	*-F
38	1		*REAR BRAKE CALIPER HOSE	Cracked	0.00 F	*-F
39	1		*TAIL LAMP	Scratched	0.00 F	*-F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
--------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >