

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
20/1/20
Hony

1/5 \$4000

VEHICLE NO: SLR8130M

QTY	PARTICULAR
1 PCS	BOOTLID
1 PCS	BOOTLID REAR LOGO
1 PCS	BOOTLID 'SKYACTIVE' EMBLEM
1 PCS	BOOTLID 'MAZDA' EMBLEM
1 PCS	BOOTLID '3' EMBLEM
1 PCS	BOOTLID WEATHERSTRIP
1 PCS	BOOTLID INNER LOCK
2 PCS	BOOTLID REFLECTORS @\$485.00
2 PCS	BOOTLID HINGES @\$121.00
2 PCS	TAILLAMPS @\$1050.00
2 PCS	TAILLAMP GASKETS @\$28.00
1 PCS	REAR BUMPER
2 PCS	REAR BUMPER REFLECTORS @\$150.00
2 PCS	REAR BUMPER TOWING COVERS @\$45.00
2 PCS	REAR BUMPER SIDE RETAINERS @\$66.50
1 SET	REAR BUMPER CLIPS
1 PCS	REAR BUMPER REINFORCEMENT
4 PCS	REAR BUMPER ULTRASONIC SENSORS @\$185.00
1 PCS	REAR END PANEL
1 PCS	REAR END PANEL TOP GARNISH
2 PCS	REAR FENDER INNER TRIMS @\$385.00
1 PCS	REAR EXHAUST
2 PCS	REAR EXHAUST MOUNTING @\$65.00
1 PCS	REAR END PANEL SELANT

915.00
20.90 x 2 = 41.80

537.30

505.10

11	\$1,269.00	X
11	\$75.00	X
11	\$63.60	X
11	\$64.00	X
11	\$74.40	X
11	\$225.00	X
11	\$271.00	X
11	\$970.00	X
11	\$242.00	X
0/500	\$2,100.00	100
11	\$56.00	X
00/00	\$1,074.00	X
11	\$300.00	X
11	\$90.00	X
11	\$133.00	X
11	\$60.00	X
11	\$741.00	X
11	\$740.00	2005.2
11	\$625.00	X
11	\$288.00	X
11	\$770.00	X
11	\$1,024.00	X
11	\$130.00	X
11	\$60.00	X
	\$11,445.00	

20%

LABOUR CHARGES:

- TO CHECK WIRING
- TO DISMANTLE & REPLACING REVERSE SENSOR
- TO TRANSFER BOOTLID MECHANISM
- TO DISMANTLE & REFIX REAR EXHAUST
- TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY
- TO MOUNT VEHICLE ON CAR O-LINER
- TO SPRAY RUST PROOFING
- LABOUR FOR PANEL BEATING & REPLACING PARTS
- TO PUTTY & SPRAY PAINTING

	\$80.00	30
	\$80.00	50
11	\$120.00	X
11	\$120.00	X
	\$150.00	80
11	\$380.00	X
	\$100.00	40
	\$1,500.00	600
	\$1,500.00	980
TOTAL	\$15,475.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 3796.20
202
P- 3036.96
S.W- 200.00
L- 1780.00
5016.96
4013.58