

MR053HY9305044349

ARCAutomotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C**Estimate**38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2001-007
DATE : 14-Jan-2020
POLICY NO. : MSIG A29061852
VEHICLE REG. NO. : SJB5562H
VEHICLE MAKE : TOYOTA XIOS 1.8 AUTOTO Motor Claim Department
India International Insurance Pte Ltd
64 Cecil Street, #04-#05 IOB Building, Singapore 049711
Tel: 6347 6100
Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

ARR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE REPAIR COST

Acknowledged by Repairer

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper / PD	1	\$ 580.00	\$ 580.00
2	Rear Bumper Clips - NEC	10	\$ 5.00	\$ 50.00
3	Rear Bumper Side Retainer RH X SVC	1	\$ 40.00	\$ 40.00
4	Rear Bumper Side Retainer LH X SVC	1	\$ 40.00	\$ 40.00
5	Rear Bumper Lower Side Retainer RH X SVC	1	\$ 40.00	\$ 40.00
6	Rear Bumper Lower Side Retainer LH X SVC	1	\$ 40.00	\$ 40.00
7	Rear Bumper Seal Bracket RH X SVC	1	\$ 40.00	\$ 40.00
8	Rear Bumper Seal Bracket LH ? X SVC	1	\$ 40.00	\$ 40.00
9	Rear Bumper Side Extension LH / CRU	1	\$ 60.00	\$ 60.00
10	Rear Reinforcement Bracket RH ? X SVC	1	\$ 70.00	\$ 70.00
11	Rear Reinforcement Bracket LH ? X SVC	1	\$ 70.00	\$ 70.00
12	Rear Bumper Reflector LH / CRU	1	\$ 100.00	\$ 100.00
13	Rear / End Panel Garnish ? X SVC	1	\$ 220.00	\$ 220.00
14	End Panel ? X SVC	1	\$ 400.00	\$ 400.00
Total Spare Parts			\$	1,790.00
SPECIAL NETT				
15	Reverse Sensor / short	1	\$ 200.00	\$ 200.00
Total Special Nett			\$	200.00
LABOUR				
16	Spray painting Rear Bumper, Rear Fender LH and Inner Panel	1	\$ 600.00	\$ 600.00
17	Repair and Replace Affected Accident Parts	1	\$ 600.00	\$ 600.00
18	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
19	Remove and Replace Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
20	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour			\$	1,410.00
Amount Before Excess			\$	3,400.00
Add GST @ 7%				238.00
Total Amount Payable			\$	3,638.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

Repair day - 3 days
Lump Sum Repair
After part photo

Sun Pm (L/L/L)

20/01/2020

Tp without prejudice

4/5
\$1,150
3 days

Oi Sun Pin (LKK Auto)

From: raymond@automotiverepaircentre.com.sg
Sent: Saturday, 7 March, 2020 8:59 AM
To: Oi Sun Pin (LKK Auto)
Cc: kenguan@automotiverepaircentre.com.sg; shujuan@automotiverepaircentre.com.sg
Subject: RE: SJB5562H - TP Claim against SHB6232C

Follow Up Flag: Follow up
Flag Status: Flagged

Hi Sun Pin,

We confirmed L/S repair at \$1,150.00 before gst (3 repair days)

Thank you.

Best Regards,
Raymond Tan
Automotive Repair Centre Pte Ltd
38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: +65 64688834
Fax: +65 64622278

From: Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com>
Sent: Friday, 6 March 2020 6:08 PM
To: raymond@automotiverepaircentre.com.sg
Cc: kenguan@automotiverepaircentre.com.sg; shujuan@automotiverepaircentre.com.sg
Subject: RE: SJB5562H - TP Claim against SHB6232C

Hi Raymond,

Kindly refer the finalize amount is \$1,150. Repair day 3 days. (L/S, before gst).
If agree please update.

Thank you.

Best Regards,
Oi Sun Pin | Assistant Automotive Assessor
LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: raymond@automotiverepaircentre.com.sg [<mailto:raymond@automotiverepaircentre.com.sg>]
Sent: Wednesday, 29 January, 2020 12:19 PM
To: Oi Sun Pin (LKK Auto)
Cc: kenguan@automotiverepaircentre.com.sg; shujuan@automotiverepaircentre.com.sg
Subject: RE: SJB5562H - TP Claim against SHB6232C

Dear Sun Pin,

Please find attached completion photos for our finalisation.