



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 1960P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RH SIDE MIRROR	* CHECK	451.30	-
1	FRONT RH SIDE MIRROR COVER	* CHECK	47.40	-
	LESS 20% DISCOUNT		-99.74	-
			398.96	-
	<u>LABOUR</u>			
	TO INSTALL OF SIDE MIRROR .		80.00	50.00
	SPRAY PAINTING ON REPLACE PARTS.		250.00	50.00
			330.00	100.00
	GRAND TOTAL		728.96	100.00
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$498.70 NETT)			100.00

Report Ref No. CC4/FCI20001178/Kka3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.