

FASTTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Ref No: 20-0006262-D

the Repairer of the following:

- To resurvey before/after spray paint
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Uth: Ispe

PAGE 1 OF 2

1/5 4250 4 days.

4 Days.

Unpsum repair
After repair photos
Gue App
8288082

17/1/2020

Estimate : 21669

Date : 17.01.2020

Vehicle Num : GBH 3510J

Make/Model : NISSAN NV200

Chassis/Engine no : V56 Y3

Accident Date : 17.01.2020

Claim No : 0120-21669

Reference :

Policy No :

Qty	Particular	Amount S\$
1	Item : net item	
2 pc	Rear door hinge @ 112.60 X NN	\$ 225.20 X
1 pc	Rear door lock X NN	\$ 182.30 X
1 pc	Rear door LH / Buc	\$ 1,926.50 / 1545
1 pc	Rear door centre garnish LH X NN	\$ 312.00 X
1 pc	Rear door inner board LH X NN	\$ 356.80 X
1 pc	Rear door RH X Repair	\$ 1,895.20 X
1 pc	Rear door inner board RH X NN	\$ 325.10 X
2 pc	Rear door hinge RH @ 112.60 X NN	\$ 225.20 X
1 pc	Rear door rubber X NN	\$ 215.50 X
2 pc	Rear fender @ 1798.50 X NN	\$ 3,597.00 X
1 pc	Rear floor board panel X NN	\$ 1,835.50 X
1 pc	Rear bumper / R	\$ 628.50 ✓
1 pc	Rear bumper inner sponge 7 ✓ CRA	\$ 115.60 98.5
2 pc	Rear bumper side bracket @ 119.20 X NN	\$ 238.40 X
2 pc	Rear bumper reflector @ 42.50 n/sra	\$ 85.00 1 PC
1 pc	Rear end pnael (outer) no/buc	\$ 348 765.50
1 pc	Rear end panel (inner) no/buc	\$ 425.10 958.20
2 pc	Rear bumper reflector @ 63.60 X Repetel	\$ 127.20 X
1 pc	Rear door emblem (dci) X NN	\$ 73.10 X
1 pc	Rear door emblem (nv 200) / spec	\$ 100.70 87.5
1 pc	Rear door emblem logo	\$ 70.90
2 pc	Rear number plate lamp @ 70.20 X NN	\$ 140.40 X
1 pc	Rear boot rubber X NN	\$ 258.50 X
1 pc	Rear boot rubber top garnish X NN	\$ 142.00 X
2 pc	Rear tail lamp @ 364.50 X NN	\$ 729.00 X
1 pc	Rear spare tyre carrier X NN	\$ 395.20 X
1 pc	Rear exhaust pipe X NN	\$ 825.50 X
2 pc	Rear exhaust rubber @ 35.00 X NN	\$ 70.00 X
	Nett Item Total :	2415.4 \$ 16,820.00
	Discount 10 % :	\$ 1,682.00
		2173.86 \$ 15,138.00

3303
107
297270

FASTECH AUTO PTE LTD

PAGE 2 OF 2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 21669

Date : 17.01.2020

Vehicle Num : GBH 3510J

Make/Model : NISSAN NV200

Chassis/Engine no :

Accident Date : 17.01.2020

Claim No : 0120-21669

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>Special Nett Item :</u>		
4 pc	Rear end panel top garnish clips @ 6.50 X NN	\$ 26.00 X
20pc	Rear door inner cover board clips @ 6.50 X NN	\$ 130.00 X
1 pc	Rear door sticker (70km/h) / <i>LMC</i>	\$ 25.00 10
1 pc	Rear door sticker (6 pax) / <i>LMC</i>	\$ 25.00 10
4 pc	Rear tail lamp clips @ 6.50 X NN	\$ 26.00 X
2 pc	Rear windscreen sealant 1 pc / <i>MLC</i>	\$ 120.00 40
1 pc	Rear number plate X NN	\$ 45.00 X
2 pc	Rear end panel sealant <i>MLC</i>	\$ 80.00 50
1 set	Rear bumper reverse sensor <i>Shorles</i>	\$ 450.00 200
Special Nett Total :		\$ 927.00 310
<u>Labour Charge :</u>		
	To check wiring	\$ 30 180.00
	Tuff kote	\$ 60 180.00
	Remove and refix rear floor mat etc	\$ 11 X 100.00
	Remove and refix rear windscreen L & R	\$ 100 250.00
	Remove and replace reverse sensor	\$ 40 160.00
	Remove and replace exhaust pipe	\$ NN X 160.00
	Remove and refix rear carpet etc	\$ 60 120.00
	To remove and replace spare part and panel beating	\$ 800 1,800.00
	To spray painting and etc	\$ 700 1,600.00
Labour Charge Total :		\$ 4,550.00 1190
E & O . E		
Total Amount :		\$ 20,615.00 50727 4058

FASTECH AUTO PTE LTD