

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jan 2020 Edit Reg		17 Jan 2020 00:00 Edit Adj Rpt	S\$4,050.00 Edit Estimates	S\$4,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LI WENJING , ID: S8383213D									
Main Claimant: BEST COOL AIR-CON ENGINEERING , Co. Reg. No.: -									
Vehicle Reg. No.:	GBH3510J	Date of Loss:	17/01/2020 12:00 - :59 [20 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2975361581SG	Policy/Cover Note No.:	1900078753 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKG923U	Policy No. (Claimant):	5108847351						
		Excess:							
Repairer: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Goh, Jeremy-CX] Jeremy.Goh@aig.com									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 30/01/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (12/08/2020): Alert - Adj Mandate Approved (S\$4575.50) - GBH3510J - Claim Handler: Goh, Jeremy... - AIG_SG (21/01/2020): TP GIA report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBH3510J (2975361581SG)
[SKG923U]

TP

BEST COOL AIR-CON ENGINEERING

Jan 17 2020 12:15PM

[LI WENJING]

Fastech Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#)

Letters/Correspondences

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1 per page	
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page	
1	06/03/20 15:24	General View	Load JPG	
2	06/03/20 15:24	General View	Load JPG	
3	06/03/20 15:24	General View	Load JPG	
4	06/03/20 15:24	General View	Load JPG	
5	06/03/20 15:25	General View	Load JPG	
6	06/03/20 15:25	General View	Load JPG	
7	06/03/20 15:25	General View	Load JPG	
8	06/03/20 15:25	General View	Load JPG	
9	06/03/20 15:25	General View	Load JPG	
10	06/03/20 15:25	General View	Load JPG	
11	06/03/20 15:25	General View	Load JPG	
12	06/03/20 15:25	General View	Load JPG	
13	06/03/20 15:25	General View	Load JPG	
14	06/03/20 15:25	General View	Load JPG	
15	06/03/20 15:25	General View	Load JPG	
16	06/03/20 15:25	General View	Load JPG	
17	06/03/20 15:25	General View	Load JPG	
18	06/03/20 15:25	General View	Load JPG	
19	06/03/20 15:25	General View	Load JPG	
20	06/03/20 15:25	Odometer Reading	Load JPG	
21	06/03/20 15:25	Chassis Number	Load JPG	
22	21/07/20 08:02	Reinspection Photo	Load JPG	
23	21/07/20 08:02	Reinspection Photo	Load JPG	
24	21/07/20 08:02	Reinspection Photo	Load JPG	
25	21/07/20 08:03	Reinspection Photo	Load JPG	
26	21/07/20 08:03	Reinspection Photo	Load JPG	
27	21/07/20 08:03	Reinspection Photo	Load JPG	
28	21/07/20 08:03	Reinspection Photo	Load JPG	
29	21/07/20 08:03	Reinspection Photo	Load JPG	
30	21/07/20 08:03	Reinspection Photo	Load JPG	
31	21/07/20 08:03	Reinspection Photo	Load JPG	
32	21/07/20 08:03	Reinspection Photo	Load JPG	
33	21/07/20 08:03	Reinspection Photo	Load JPG	
34	21/07/20 08:03	Reinspection Photo	Load JPG	
35	21/07/20 08:03	After Repair Photo	Load JPG	
36	21/07/20 08:03	After Repair Photo	Load JPG	
37	21/07/20 08:03	After Repair Photo	Load JPG	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/20 11:56	TP ESTIMATE - MARKED	 Load PDF	
2	31/01/20 11:56	TP GIA REPORT	 Load PDF	
3	10/02/20 17:28	LETTER TO OI	 Load PDF	
4	11/08/20 10:04	LOD	 Load PDF	
5	09/09/20 11:03	Authorisation to Act	 Load PDF	
6	09/09/20 11:03	GIA SEARCH	 Load PDF	
7	09/09/20 11:03	Release Voucher	 Load PDF	
8	09/09/20 11:03	RENTAL RECEIPT	 Load PDF	
9	09/09/20 11:03	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/01/20 15:18	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKG923U (Insd veh)	Model:	NISSAN NV200 1.5 (M)
	GBH3510J (TP veh)		
Date of Accident:	17/01/2020		

Global Sum Settlement	:	☒ [X]	Yes	☐ []	No	
Repair Estimate	:	\$				22,058.05
Final Repair Cost	:	\$				4,550.00
Loss of Use	:	\$				days at \$0.00 per day
Rental (if any)	:	\$				3 days
LTA / GIA Search Fee	:	\$				
Others:	:	\$				
	:	\$				
Final Settlement Sum (GLOBAL SUM)	:	\$				4,550.00

Is Third Party Workshop GIA Registered?				☐ []	YES	☒ [X]	NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u>:				Agreed Liability _____ 100 _____ (%)				
B) For <u>GIA Registered Workshop</u>:				BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%)				Assessed Liability (*): _____ 0 _____ (%)				
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>								
Remarks _____ _____								

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:	\$ 4,550.00
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

09 Sep
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20001184/GBA3S2

Date: 09/09/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900078753
Claimant Vehicle No :	GBH3510J	Insured Vehicle No :	SKG923U
Date of Loss:	17/01/2020	Nature of Claim:	TP
		Claim No:	2975361581SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH3510J	Engine No:	K9KE628D423610
Make & Model:	NISSAN NV200, 1.5 (M)	Chassis No:	VSKYBAM20Z0157042
Reg. Date:	11/05/2018 (Man. Year: 2017)	Odometer:	28393 km
Colour:	Silver		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,065.00	3,282.70	12,782.30	79.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,550.00	1,790.00	2,760.00	60.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,615.00	5,072.70	15,542.30	75.39
Approved Total (Overridden) (S\$)		4,050.00		
(S\$)	20,615.00	4,050.00	16,565.00	80.35
+ GST 7.00/7.00% (S\$)	1,443.05	283.50	1,159.55	80.35
Nett Amount (S\$)	22,058.05	4,333.50	17,724.55	80.35
+ Car Rental (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,575.50		
Global Sum Settlement (S\$)		4,550.00		

INSPECTION

Date of Assignment:	17/01/2020	
Date Inspected:	17/01/2020	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR DOOR HINGE	Not Necessary	225.20 FN	*- FN
2	1		*REAR DOOR LOCK	Not Necessary	182.30 FN	*- FN
3	1		*REAR DOOR LH	Buckled	1,926.50 FN	*1,545.00 FN
4	1		*REAR DOOR CENTRE GARNISH LH	Not Necessary	312.00 FN	*- FN
5	1		*REAR DOOR INNER BOARD LH	Not Necessary	356.80 FN	*- FN
6	1		*REAR DOOR RH	Repair	1,895.20 FN	*- FN
7	1		*REAR DOOR INNER BOARD RH	Not Necessary	325.10 FN	*- FN
8	2		*REAR DOOR HINGE RH	Not Necessary	225.20 FN	*- FN
9	1		*REAR DOOR RUBBER	Not Necessary	215.50 FN	*- FN
10	2		*REAR FENDER	Not Necessary	3,597.00 FN	*- FN
11	1		*REAR FLOOR BOARD PANEL	Not Necessary	1,835.50 FN	*- FN
12	1		*REAR BUMPER	Deformed	628.50 FN	*628.50 FN
13	1		*REAR BUMPER INNER SPONGE	Cracked	115.60 FN	*98.50 FN
14	2		*REAR BUMPER SIDE BRACKET	Not Necessary	238.40 FN	*- FN
15	1		*REAR BUMPER REFLECTOR	N/s Cracked	85.00 FN	*42.50 FN
16	1		*REAR END PANEL (OUTER)	Dented / Buckled	765.50 FN	*345.00 FN
17	1		*REAR END PANEL (INNER)	Dented / Buckled	958.20 FN	*485.10 FN
18	2		*REAR BUMPER REFLECTOR	Repeated	127.20 FN	*- FN
19	1		*REAR DOOR EMBLEM (DCI)	Not Necessary	73.10 FN	*- FN
20	1		*REAR DOOR EMBLEM (NV 200)	Necessary	100.70 FN	*87.50 FN
21	1		*REAR DOOR EMBLEM LOGO	Necessary	70.90 FN	*70.90 FN
22	2		*REAR NUMBER PLATE LAMP	Not Necessary	140.40 FN	*- FN
23	1		*REAR BOOT RUBBER	Not Necessary	258.50 FN	*- FN
24	1		*REAR BOOT RUBBER TOP GARNISH	Not Necessary	142.00 FN	*- FN
25	2		*REAR TAIL LAMP	Not Necessary	729.00 FN	*- FN
26	1		*REAR SPARE TYRE CARRIER	Not Necessary	395.20 FN	*- FN
27	1		*REAR EXHAUST PIPE	Not Necessary	825.50 FN	*- FN
28	2		*REAR EXHAUST RUBBER	Not Necessary	70.00 FN	*- FN
29	4		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	26.00 FS	*- FS
30	20		*REAR DOOR INNER COVER BOARD CLIPS	Not Necessary	130.00 FS	*- FS
31	1		*REAR DOOR STICKER (70KM/H)	Necessary	25.00 FS	*10.00 FS
32	1		*REAR DOOR STICKER (6 PAX)	Necessary	25.00 FS	*10.00 FS
33	4		*REAR TAIL LAMP CLIPS	Not Necessary	26.00 FS	*- FS
34	2		*REAR WINDSCREEN SEALNT	Necessary 1Pc Only	120.00 FS	*40.00 FS
35	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
36	2		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
37	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	450.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	17,747.00	3,613.00
- Nett Item Discount on N Items 10.00/10.00% (\$)	1,682.00	330.30
Total Parts (\$)	16,065.00	3,282.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING.	New	180.00	30.00
2	TUFF KOTE.	New	180.00	60.00
3	REMOVE AND REFIX REAR FLOOR MAT ETC.	New	100.00	0.00
4	REMOVE AND REFIX REAR WINDSCREEN L & R.	New	250.00	100.00
5	REMOVE AND REPLACE REVERSE SENSOR.	New	160.00	40.00
6	REMOVE AND REPLACE EXHAUST PIPE.	New	160.00	0.00
7	REMOVE AND REFIX REAR CARPET ETC.	New	120.00	60.00
8	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING.	New	1,800.00	800.00
9	TO SPRAY PAINTING AND ETC.	New	1,600.00	700.00
Gross Labour Cost (S\$)			4,550.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >