

陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2


AIGAsia Insured's Veh No : GY1150D
Date of Accident : 16 January 2020

Messrs BIS Motoring Pte Ltd

Date : 04 February 2020

Estimate To Repair SMC5653M - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7208448

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
* 01	1 pc	front bumper	\$ 668.00 ✓
* 02	8 ps	front bumper clip @ \$5.00	\$ 40.00 ✓ 25 ✓
03	1 pc	front bumper centre	\$ 0.00
04	1 pc	front bumper reinforcement	\$ 389.00
* 05	2 ps	headlamp @ \$1558.00	\$ 3,116.00 ✓ ✓
* 06	1 pc	front bumper centre grille	\$ 159.00 ✓ ✓
* 07	1 pc	rear bumper	\$ 576.00 ✓ ✓
* 08	2 ps	rear bumper clip @ \$5.00	\$ 10.00 ✓ 5 ✓
* 09	2 ps	rear bumper centre garnish @ \$84.00	\$ 168.00 ✓ ✓
* 10	1 pc	rear bumper lower <i>lip</i>	\$ 189.00 ✓ ✓
11	2 ps	rear bumper side retainer @ \$25.00	\$ 50.00
12	1 pc	rear bumper top bracket	\$ 5.00
* 13	4 set 2	rear bumper reverse sensor @ \$162.00	\$ 648.00 324 ✓
14	2 ps	rear bumper reverse sensor holder @ \$5.00	\$ 10.00
* 15	1 pc	n/s rear bumper reflector	\$ 119.00 ✓
* 16	1 pc	rear bumper reinforcement	\$ 367.00 ✓
17	1 pc	rear bumper bracket lower	\$ 5.00
* 18	1 pc	rear bumper reinforcement bracket <i>1/1 only</i>	\$ 159.00 ✓ ✓
* 19	1 pc	rear end panel	\$ 453.00 ✓ ✓
* 20	1 pc	rear end panel top garnish	\$ 71.00 ✓ ✓
* 21	1 pc	tailgate	\$ 1,088.00 ✓ ✓
* 22	1 pc	tailgate lock	\$ 109.00 ✓ ✓
23	1 pc	tailgate lock inner garnish	\$ 0.00
* 24	1 pc	rear boot weatherstrip	\$ 131.00 ✓ ✓
25	1 pc	rear boot tools compartment	\$ 0.00
26	1 pc	rear boot tools compartment floor board top	\$ 0.00
27	1 pc	rear boot tools compartment floor board top	\$ 0.00
* 28	1 pc	n/s taillamp	\$ 357.00 ✓ ✓
* 29	1 pc	tailgate outer chrome moulding	\$ 95.00 ✓ ✓
* 30	1 pc	tailgate outer garnish	\$ 135.00 ✓
31	1 pc	tailgate keyless switch	\$ 88.00
32	1 pc	tailgate keyless switch antenna	\$ 79.00
33	1 pc	tailgate wiper motor	\$ 254.00
34	1 pc	tailgate wiper arm	\$ 38.00
35	2 ps	rear license plate lamp @ \$111.00	\$ 222.00
36	1 pc	Caren lettering	\$ 64.00
* 37	1 pc	C & C emblem	\$ 29.00 ✓ ✓
* 38	1 pc	CRDI lettering	\$ 29.00 ✓ ✓



陳林峰有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GY1150D
Date of Accident : 16 January 2020

Messrs BIS Motoring Pte Ltd

Date : 04 February 2020

Supplementary To Repair SMC5653M - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7208448

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
* 01	2 ps	tailgate lamp @ \$773.00	\$ 1,546.00
* 02	1 pc	front support panel top garnish	\$ 65.00
* 03	1 pc	front bumper absorber foam	\$ 68.00
		Less 10 %	\$ 1,679.00
			\$ 167.90
		Total	\$ 1,511.10
			\$ 1,511.10

600 ✓



陳林峰峰私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GY1150D
Date of Accident : 16 January 2020

Messrs BIS Motoring Pte Ltd

Date : 04 February 2020

Estimate To Repair SMC5653M - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7208448

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
* 39	1 pc	KIA logo	\$ 76.00 ✓
		10%	\$ 9,996.00
<u>SPECIAL NETT ITEMS</u>			
* 40	1 pc	rear licence plate	\$ 30.00 25 ✓
* 41	1 pc	front licence plate	\$ 30.00 25 ✓
	1 pc	windscreen primer	\$ 50.00
* 43	1 set	windscreen sealant	\$ 60.00 40 ✓
* 44	1 pc	windscreen inner seal	\$ 80.00 70 ✓
			\$ 250.00
<u>LABOUR & MISC. CHARGES</u>			
01		To rust-proofing of the affected areas.	\$ 300.00 30 ✓
02		To perform water seepage test, windnoise and test-drive.	\$ 80.00 50 ✓
03		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 100.00 60 ✓
04		To reinstall of rear bumper parking sensor.	\$ 240.00 30 ✓
05		To check electrical lighting concerned. → (part and labor)	\$ 80.00 60 ✓
06		To remove and refit rear windscreen glass.	\$ 150.00 166 ✓
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,400.00 1100 ✓
08		Putty and spray painting of the affected portion.	\$ 1,600.00 1000 ✓
			\$ 3,950.00
		parts 9187	
		parts less 10%	
		8262.90	
		special net	110
		labor 2430	
		10802.90	
		4/5 less 20%	
		total 8642.32	
		2/5 net → \$8650	
			\$ 14,196.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GY1150D
Date of Accident : 16 January 2020

Messrs BIS Motoring Pte Ltd

Date : 17 January 2020

Estimate To Repair SMC5653M - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7208448

S/No	Quantity	Description	Amount
<u>SPECIAL NETT ITEMS</u>			
36	1 pc	rear licence plate ✓ <i>SCR</i>	\$ 30.00 25
37	1 pc	front licence plate ✓ <i>SCR</i>	\$ 30.00 25
38	1 pc	Caren lettering X	\$ 0.00
39	1 pc	C & E Emblem ✓ <i>new</i>	\$ 0.00
40	2 pc	CRDI lettering @ \$.00 ✓ <i>new</i>	\$ 0.00
41	1 pc	KIA logo ✓ <i>new</i>	\$ 0.00
42	1 pc	windscreen primer X (not use)	\$ 0.00
43	1 set	windscreen sealant (rear) ✓ <i>new</i>	\$ 60.00 40
44	1 pc	windscreen inner seal ✓ <i>new</i>	\$ 80.00 27
			\$ 200.00
<u>LABOUR & MISC. CHARGES</u>			
01		To rust-proofing of the affected areas. ✓	\$ 300.00 30
02		To perform water seepage test, windnoise and test-drive. ✓	\$ 80.00 50
03		To transfer of bootlid fittings, attachments and perform water seepage test. ✓	\$ 100.00 60
04		To reinstall of rear bumper parking sensor. ✓	\$ 240.00 30
05		To check electrical lighting concerned. → (1st and 2nd) ✓	\$ 80.00 60
06		To remove and refit rear windscreen glass. ✓	\$ 150.00 100
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,400.00 1100
08		Putty and spray painting of the affected portion.	\$ 1,600.00 1000
			\$ 3,950.00
Total <i>8 day</i>			\$ 4,150.00

Handwritten notes:
 H/S report
 without pengaduan.
 Passenger side front
 Hock ANN
 P3311883
 Hock ANN@klicar.com
 17/1/20
 2.30pm
 Passenger side
 H. ANN
 Hock
 3.30pm



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : GY1150D
Date of Accident : 16 January 2020

Messrs BIS Motoring Pte Ltd

Date : 17 January 2020

Estimate To Repair SMC5653M - KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis No : KNAHU815VJ7208448

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front bumper ✓ C.R.A	\$ 0.00
02	8 ps	front bumper clip @ \$.00 ✓ all	\$ 0.00
03	1 pc	front bumper centre x (with paper)	\$ 0.00
04	1 pc	front bumper reinforcement x (R)	\$ 0.00
05	2 ps	headlamp @ \$.00 LH ✓ C.R.A RH ✓ S.C.R	\$ 0.00
06	1 pc	front bumper centre grille ✓ S.C.R	\$ 0.00
07	1 pc	rear bumper ✓ cut	\$ 0.00
08	2 ps	rear bumper clip @ \$.00 ✓ all	\$ 0.00
09	2 ps	rear bumper centre @ \$.00 ✓ garnish ✓ C.R.A	\$ 0.00
10	1 pc	rear bumper lower lip ✓ S.C.R	\$ 0.00
11	2 ps	rear bumper side retainer @ \$.00 x (S.C.R)	\$ 0.00
12	1 pc	rear bumper top bracket x (R)	\$ 0.00
13	2 ps	rear bumper reverse sensor holder @ \$.00 x (S.C.R)	\$ 0.00
14	1 pc	n/s rear bumper reflector ✓ C.R.A LH	\$ 0.00
15	1 pc	rear bumper reinforcement ✓ B.T	\$ 0.00
16	1 pc	rear bumper bracket lower x (S.C.R)	\$ 0.00
17	1 pc	rear bumper reinforcement bracket LH only ✓ B.T	\$ 0.00
18	1 pc	rear end panel ✓ B.T	\$ 0.00
19	1 pc	rear end panel top garnish x (S.C.R) ✓ B.T	\$ 0.00
20	1 pc	tailgate ✓ B.T	\$ 0.00
21	1 pc	tailgate lock ✓ Jm	\$ 0.00
22	1 pc	tailgate lock inner garnish x (S.C.R)	\$ 0.00
23	1 pc	rear boot weatherstrip ✓ C.R.A	\$ 0.00
24	1 pc	rear boot tools compartment x (S.C.R)	\$ 0.00
25	1 pc	rear boot tools compartment floor board top x (S.C.R)	\$ 0.00
26	1 pc	rear boot tools compartment floor board top x (S.C.R)	\$ 0.00
27	1 pc	n/s tailamp ✓ C.R.A RH only	\$ 0.00
28	1 pc	n/s tailamp outer chrome moulding ✓ S.C.R	\$ 0.00
29	1 pc	tailgate outer garnish ✓ B.R. - Guo Ent.	\$ 0.00
30	1 pc	tailgate keyless switch x (S.C.R)	\$ 0.00
31	1 pc	tailgate keyless switch antenna x (S.C.R)	\$ 0.00
32	1 pc	tailgate wiper motor x (S.C.R)	\$ 0.00
33	1 pc	tailgate wiper actuator x (S.C.R)	\$ 0.00
34	2 ps	rear license plate lamp @ \$.00 x (S.C.R)	\$ 0.00
	2 ps	tailgate lamp ✓ C.R.A	\$ 0.00
	1 pc	front support panel top garnish ✓ C.R.A	
	1 pc	front bumper absorber form. ✓ C.R.A	
<u>SPECIAL NETT ITEMS</u>			
35	1 set	rear bumper reverse sensor ✓ short (centre only)	\$ 0.00