



陳林摩呀私人有限公司  
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GY1150D

Date of Accident : 16 January 2020

Messrs BIS Motoring Pte Ltd

Date : 04 February 2020

Estimate To Repair SMC5653M - KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis No : KNAHU815VJ7208448

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
* 01	1 pc	front bumper CRA	\$ 668.00 ✓
* 02	8 ps	front bumper clip @ \$5.00 NEC	\$ 40.00 ✓ 25 ✓
03	1 pc	front bumper centre X NN	\$ 0.00
04	1 pc	front bumper reinforcement X (R)	\$ 389.00
* 05	2 ps	headlamp @ \$1558.00 L/H CRA R/H SCR ✓	\$ 3,116.00 ✓
* 06	1 pc	front bumper centre grille SCR	\$ 159.00 ✓
* 07	1 pc	rear bumper CUT	\$ 576.00 ✓
* 08	2 ps	rear bumper clip @ \$5.00 NEC	\$ 10.00 ✓ 5 ✓
* 09	2 ps	rear bumper centre garnish @ \$84.00 CRA	\$ 168.00 ✓
* 10	1 pc	rear bumper lower lip SCR	\$ 189.00 ✓
11	2 ps	rear bumper side retainer @ \$25.00 X SVC	\$ 50.00
12	1 pc	rear bumper top bracket X (R)	\$ 5.00
* 13	4 set 2	rear bumper reverse sensor @ \$162.00 SHORT (CENTRE ONLY)	\$ 648.00 324 ✓
14	2 ps	rear bumper reverse sensor holder @ \$5.00 X SVC	\$ 10.00
* 15	1 pc	n/s rear bumper reflector CRA L/H	\$ 119.00 ✓
* 16	1 pc	rear bumper reinforcement BT	\$ 367.00 ✓
17	1 pc	rear bumper bracket lower X SVC	\$ 5.00
* 18	1 pc	rear bumper reinforcement bracket 1/4 only BT	\$ 159.00 ✓
* 19	1 pc	rear end panel BT	\$ 453.00 ✓
* 20	1 pc	rear end panel top garnish BT	\$ 71.00 ✓
* 21	1 pc	tailgate BT	\$ 1,088.00 ✓
* 22	1 pc	tailgate lock JAM	\$ 109.00 ✓
23	1 pc	tailgate lock inner garnish X SVC	\$ 0.00
* 24	1 pc	rear boot weatherstrip CRA	\$ 131.00 ✓
25	1 pc	rear boot tools compartment X SVC	\$ 0.00
26	1 pc	rear boot tools compartment floor board top X SVC	\$ 0.00
27	1 pc	rear boot tools compartment floor board top X SVC	\$ 0.00
* 28	1 pc	tailamp CRA R/H ONLY	\$ 357.00 ✓
* 29	1 pc	tailgate outer chrome moulding SCR	\$ 95.00 ✓
* 30	1 pc	tailgate outer garnish BR	\$ 135.00 ✓
31	1 pc	tailgate keyless switch X SVC	\$ 88.00
32	1 pc	tailgate keyless switch antenna X SVC	\$ 79.00
33	1 pc	tailgate wiper motor X SVC	\$ 254.00
34	1 pc	tailgate wiper arm X SVC	\$ 38.00
35	2 ps	rear license plate lamp @ \$111.00 X SVC	\$ 222.00
36	1 pc	Caren lettering X NN	\$ 64.00
* 37	1 pc	C & C emblem NEC	\$ 29.00 ✓
* 38	1 pc	CRDI lettering NEC	\$ 29.00 ✓



陳林隆摩私人有限公司  
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GY1150D  
Date of Accident : 16 January 2020

Messrs BIS Motoring Pte Ltd

Date : 04 February 2020


Estimate To Repair SMC5653M - KIA CARENS 1.7 DCT DIESEL 5DR FWD  
Chassis No : KNAHU815VJ7208448

S/No	Quantity	Description	Amount	
<u>LIST ITEMS</u>				
* 39	1 pc	KIA logo NEC	\$ 76.00	✓
		10%	\$ 9,996.00	
<u>SPECIAL NETT ITEMS</u>				
* 40	1 pc	rear licence plate SCR	\$ 30.00	25 ✓
* 41	1 pc	front licence plate SCR	\$ 30.00	25 ✓
42	1 pc	windscreen primer X NOT USE	\$ 50.00	
* 43	1 set	windscreen sealant (REAR) NEC	\$ 60.00	40 ✓
* 44	1 pc	windscreen inner seal NEC	\$ 80.00	70 ✓
			\$ 250.00	
<u>LABOUR &amp; MISC. CHARGES</u>				
01		To rust-proofing of the affected areas.	\$ 300.00	30 ✓
02		To perform water seepage test, windnoise and test-drive.	\$ 80.00	50 ✓
03		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 100.00	60 ✓
04		To reinstall of rear bumper parking sensor.	\$ 240.00	30 ✓
05		To check electrical lighting concerned. → (Part and Run)	\$ 80.00	60 ✓
06		To remove and refit rear windscreen glass.	\$ 150.00	166 ✓
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,400.00	1100 ✓
08		Putty and spray painting of the affected portion.	\$ 1,600.00	1000 ✓
			\$ 3,950.00	
		parts 9187		
		parts less 10%		
		8262.90		
		Spe nett 110		
		labour 2430		
		10802.90		
		4/5 less 20%		
		total 8642.32		
		2/5 part → \$8650		
			\$ 14,196.00	
			15,707.10#	

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



陳林峰摩私人有限公司  
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GY1150D  
Date of Accident : 16 January 2020

Messrs BIS Motoring Pte Ltd

Date : 04 February 2020

Supplementary To Repair SMC5653M - KIA CARENS 1.7 DCT DIESEL 5DR FWD  
Chassis No : KNAHU815VJ7208448

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
* 01	2 ps	tailgate lamp @ \$773.00 CRA	\$ 1,546.00 ✓ 600 ✓
* 02	1 pc	front support panel top garnish CRA	\$ 65.00 ✓
* 03	1 pc	front bumper absorber foam CRA	\$ 68.00 ✓
		Less 10 %	\$ 1,679.00
			\$ 167.90
		Total	\$ 1,511.10
			\$ 1,511.10