

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Jan 2020 Edit Reg		17 Jan 2020 00:00 Edit Adj Rpt	S\$8,650.00 Edit Estimates	S\$8,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	MHL ENTERPRISES PTE. LTD., Co. Reg. No.: 200718029R								
Main Claimant:	BIS MOTORING PTE LTD								
Vehicle Reg. No.:	SMC5653M	Date of Loss:	16/01/2020 08:00 - :59 [18 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4390495009SG	Policy/Cover Note No.:	0100487625 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	GY1150D	Policy No. (Claimant):							
		Excess:							
Repairer:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6, 539365 Defu Lane - Tel: 6858 5151								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 30/01/2020]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG_EXPRESS (10/06/2020): Alert - Adj Mandate Approved (S\$9257.50) - SMC5653M - Claim Handler: Loh, Chee-H... 									
ALL ASSOCIATED TASKS <input type="checkbox"/>									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMC5653M (4390495009SG)**
[GY1150D]
TP
BIS MOTORING PTE LTD
Jan 16 2020 8:00AM
[MHL ENTERPRISES PTE. LTD.]
Tan Lim Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser <input type="checkbox"/>	
Letters/Correspondences										1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown						<input checked="" type="checkbox"/>	Edit		
Photos/Images										3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	23/01/20 11:01	Chassis Number						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
2	23/01/20 11:04	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
3	23/01/20 11:04	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
4	23/01/20 11:04	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
5	23/01/20 11:04	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
6	23/01/20 11:04	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
7	23/01/20 11:04	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
8	23/01/20 11:04	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
9	23/01/20 11:04	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
10	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
11	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
12	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
13	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
14	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
15	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
16	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
17	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
18	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
19	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
20	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
21	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
22	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
23	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
24	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
25	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
26	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
27	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
28	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
29	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
30	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
31	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
32	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
33	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
34	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
35	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
36	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	
37	23/01/20 11:05	General View						<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
39	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
40	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
41	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
42	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
43	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
44	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
45	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
46	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
47	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
48	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
49	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
50	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
51	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
52	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
53	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
54	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
55	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
56	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
57	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
58	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
59	23/01/20 11:05	General View		<input checked="" type="checkbox"/>
60	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
61	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
62	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
63	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
64	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
65	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
66	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
67	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
68	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
69	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
70	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
71	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
72	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
73	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
74	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
75	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
76	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
77	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
78	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
79	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
80	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
81	23/01/20 11:06	General View		<input checked="" type="checkbox"/>
82	23/01/20 11:06	Reinspection Photo		<input checked="" type="checkbox"/>
83	23/01/20 11:06	Reinspection Photo		<input checked="" type="checkbox"/>
84	23/01/20 11:06	Reinspection Photo		<input checked="" type="checkbox"/>
85	23/01/20 11:06	Reinspection Photo		<input checked="" type="checkbox"/>
86	23/01/20 11:06	Reinspection Photo		<input checked="" type="checkbox"/>
87	23/01/20 11:06	Reinspection Photo		<input checked="" type="checkbox"/>
88	23/01/20 11:06	Reinspection Photo		<input checked="" type="checkbox"/>
89	23/01/20 11:06	Reinspection Photo		<input checked="" type="checkbox"/>
90	23/01/20 11:06	Reinspection Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
91	23/01/20 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	23/01/20 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	23/01/20 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	23/01/20 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	23/01/20 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	23/01/20 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	23/01/20 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	23/01/20 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	23/01/20 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	23/01/20 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	23/01/20 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	23/01/20 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	23/01/20 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	23/01/20 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	23/01/20 11:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	23/01/20 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	23/01/20 11:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
144	23/01/20 11:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
145	23/01/20 11:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
146	23/01/20 11:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
147	23/01/20 11:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
148	21/02/20 09:33	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
149	21/02/20 09:33	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
150	21/02/20 09:33	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
151	21/02/20 09:33	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
152	21/02/20 09:33	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
153	21/02/20 09:33	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
154	21/02/20 09:33	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/01/20 10:23	TP ESTIMATE-MARKED	Load PDF	
2	21/01/20 10:23	TP GIA REPORT	Load PDF	
3	12/02/20 09:47	LETTER TO OI	Load PDF	
4	05/06/20 17:39	GIA SEARCH	Load PDF	
5	05/06/20 17:39	LOD	Load PDF	
6	10/06/20 10:16	Repair Bill	Load PDF	
7	10/06/20 10:16	Authorisation to Act	Load PDF	
8	07/07/20 10:28	Release Voucher	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/01/20 15:10	OI GIA REPORT	Load PDF	
2	21/05/20 10:02	TP GIA	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid gray; height: 40px; width: 100%;"></div> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>
--

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	GY1150D (Insd veh)	Model:	KIA CARENS 1.7 D DCT 5DR FWD (A)
	SMC5653M (TP veh)		
Date of Accident:	16/01/2020		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:\$		16,806.60
Final Repair Cost	:\$		9,255.50
Loss of Use	:\$		days at \$0.00 per day
Rental (if any)	:\$		days
LTA / GIA Search Fee	:\$		2.00
Others:	:\$		0.00
	:\$		
Final Settlement Sum	:\$		9,257.50
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	:\$	9,257.50
2)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

07 Jul
2020

Date

**Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/
Bill (if any)**

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20001185/HKS3S2**Date:** 07/07/2020**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0100487625
Claimant Vehicle No :	SMC5653M	Insured Vehicle No :	GY1150D
Date of Loss:	16/01/2020	Nature of Claim:	TP
		Claim No:	4390495009SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC5653M	Engine No:	D4FDJH553000
Make & Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Chassis No:	KNAHU815VJ7208448
Reg. Date:	10/07/2018 (Man. Year: 2018)	Odometer:	134626 km
Colour:	Beige		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	COMFORT 68 6 mm	Rear Left Side:	COMFORT 68 6 mm
Front Right Side:	COMFORT 68 6 mm	Rear Right Side:	COMFORT 68 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,757.10	8,372.90	3,384.20	28.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,950.00	2,430.00	1,520.00	38.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,707.10	10,802.90	4,904.20	31.22
Approved Total (Overridden) (S\$)		8,650.00		
(S\$)	15,707.10	8,650.00	7,057.10	44.93
+ GST 7.00/7.00% (S\$)	1,099.50	605.50	494.00	44.93
Nett Amount (S\$)	16,806.60	9,255.50	7,551.10	44.93
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,257.50		

INSPECTION

Date of Assignment:	17/01/2020		
Date Inspected:	17/01/2020	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	8.0 days		

Adjuster: LEE HOCK ANN**Manager:** Khanchna Pothuraj*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	668.00 F	*668.00 FL
2	1		*FRONT BUMPER CLIP 8pcs	Necessary	40.00 F	*25.00 FL
3	1		*FRONT BUMPER CENTRE (NPA)	Not Necessary	0.00 F	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	389.00 F	*- FL
5	2		*HEADLAMP	N/s Cracked / O/s Scratched	3,116.00 F	*3,116.00 FL
6	1		*FRONT BUMPER CENTRE GRILLE	Scratched	159.00 F	*159.00 FL
7	1		*REAR BUMPER	Cut	576.00 F	*576.00 FL
8	2		*REAR BUMPER CLIP	Necessary	10.00 F	*5.00 FL
9	2		*REAR BUMPER CENTRE GARNISH	Cracked	168.00 F	*168.00 FL
10	1		*REAR BUMPER LOWER LIP	Scratched	189.00 F	*189.00 FL
11	2		*REAR BUMPER SIDE RETAINER	Serviceable	50.00 F	*- FL
12	1		*REAR BUMPER TOP BRACKET	Repair	5.00 F	*- FL
13	4		*SET REAR BUMPER REVERSE SENSOR	Shorted 2sets Only	648.00 F	*324.00 FL
14	2		*REAR BUMPER REVERSE SENSOR HOLDER	Serviceable	10.00 F	*- FL
15	1		*N/S REAR BUMPER REFLECTOR	Cracked	119.00 F	*119.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	367.00 F	*367.00 FL
17	1		*REAR BUMPER BRACKET LOWER	Serviceable	5.00 F	*- FL
18	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Bent	159.00 F	*159.00 FL
19	1		*REAR END PANEL	Bent	453.00 F	*453.00 FL
20	1		*REAR END PANEL TOP GARNISH	Bent	71.00 F	*71.00 FL
21	1		*TAILGATE	Bent	1,088.00 F	*1,088.00 FL
22	1		*TAILGATE LOCK	Jammed	109.00 F	*109.00 FL
23	1		*TAILGATE LOCK INNER GARNISH (NPA)	Serviceable	0.00 F	*- FL
24	1		*REAR BOOT WEATHERSTRIP	Cracked	131.00 F	*131.00 FL
25	1		*REAR BOOT COMPARTMENT (NPA)	Serviceable	0.00 F	*- FL
26	1		*REAR BOOT TOOLS COMPARTMENT FLOOR BOARD TOP (NPA)	Serviceable	0.00 F	*- FL
27	1		*REAR BOOT TOOLS COMPARTMENT FLOOR BOARD TOP (NPA)	Serviceable	0.00 F	*- FL
28	1		*RH TAILLAMP	Cracked	357.00 F	*357.00 FL
29	1		*TAILGATE OUTER CHROME MOULDING	Scratched	95.00 F	*95.00 FL
30	1		*TAILGATE OUTER GARNISH	Broken	135.00 F	*135.00 FL
31	1		*TAILGATE KEYLESS SWITCH	Serviceable	88.00 F	*- FL
32	1		*TAILGATE KEYLESS SWITCH ANTENNA	Serviceable	79.00 F	*- FL
33	1		*TAILGATE WIPER MOTOR	Serviceable	254.00 F	*- FL
34	1		*TAILGATE WIPER ARM	Serviceable	38.00 F	*- FL
35	2		*REAR LICENCE PLATE LAMP	Serviceable	222.00 F	*- FL
36	1		*CAREN LETTERING	Not Necessary	64.00 F	*- FL
37	1		*C&C EMBLEM	Necessary	29.00 F	*29.00 FL
38	1		*CRDI LETTERING	Necessary	29.00 F	*29.00 FL
39	1		*KIA LOGO	Necessary	76.00 F	*76.00 FL
40	1		*REAR LICENCE PLATE	Scratched	30.00 FS	*25.00 FS
41	1		*FRONT LICENCE PLATE	Scratched	30.00 FS	*25.00 FS
42	1		*WINDSCREEN PRIMER	Not Use	50.00 FS	*- FS
43	1		*SET WINDSCREEN SEALANT (REAR)	Necessary	60.00 FS	*40.00 FS
44	1		*WINDSCREEN INNER SEAL	Necessary	80.00 FS	*20.00 FS
45	2		*TAILGATE LAMP	Cracked	1,391.40 F	*600.00 FL
46	1		*FRONT SUPPORT PANEL TOP GARNISH	Cracked	58.50 F	*65.00 FL
47	1		*FRONT BUMPER ABSORBER FOAM	Cracked	61.20 F	*68.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 11,757.10 9,291.00
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 918.10

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
Total Parts (\$)						11,757.10	8,372.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	300.00	30.00
2	TO PERFORM WATER SEEPAGE TEST, WINDNOISE AND TEST-DRIVE.	New	80.00	50.00
3	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	100.00	60.00
4	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	New	240.00	30.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	80.00	60.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	New	150.00	100.00
7	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	1,400.00	1,100.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	1,600.00	1,000.00
			Gross Labour Cost (\$)	3,950.00
				2,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >