



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GY1150D  
Date of Accident : 16 January 2020

Messrs BIS Motoring Pte Ltd

Date : 17 January 2020

Estimate To Repair SMC5653M - KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis No : KNAHU815VJ7208448

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper ✓ CRA	\$ 0.00
02	8 ps	front bumper clip @ \$.00 ✓ all	\$ 0.00
03	1 pc	front bumper centre x (with bumper)	\$ 0.00
04	1 pc	front bumper reinforcement x (R)	\$ 0.00
05	2 ps	headlamp @ \$.00 LH ✓ CRA RH ✓ SCR	\$ 0.00
06	1 pc	front bumper centre grille ✓ SCR	\$ 0.00
07	1 pc	rear bumper ✓ cut	\$ 0.00
08	2 ps	rear bumper clip @ \$.00 ✓ all	\$ 0.00
09	2 ps	rear bumper centre @ \$.00 → Garnish ✓ CRA	\$ 0.00
10	1 pc	rear bumper lower lip ✓ SCR	\$ 0.00
11	2 ps	rear bumper side retainer @ \$.00 x (suc)	\$ 0.00
12	1 pc	rear bumper top bracket x (R)	\$ 0.00
13	2 ps	rear bumper reverse sensor holder @ \$.00 x (suc)	\$ 0.00
14	1 pc	n/s rear bumper reflector ✓ CRA LH	\$ 0.00
15	1 pc	rear bumper reinforcement ✓ BT	\$ 0.00
16	1 pc	rear bumper bracket lower x (suc)	\$ 0.00
17	1 pc	rear bumper reinforcement bracket LH only ✓ BT	\$ 0.00
18	1 pc	rear end panel ✓ BT	\$ 0.00
19	1 pc	rear end panel top garnish x (suc) ✓ BT	\$ 0.00
20	1 pc	tailgate ✓ BT	\$ 0.00
21	1 pc	tailgate lock ✓ Jm	\$ 0.00
22	1 pc	tailgate lock inner garnish x (suc)	\$ 0.00
23	1 pc	rear boot weatherstrip ✓ CRA	\$ 0.00
24	1 pc	rear boot tools compartment x (suc)	\$ 0.00
25	1 pc	rear boot tools compartment floor board top x (suc)	\$ 0.00
26	1 pc	rear boot tools compartment floor board top x (suc)	\$ 0.00
27	1 pc	n/s tailamp ✓ CRA RH only	\$ 0.00
28	1 pc	n/s tailamp outer chrome moulding ✓ SCR	\$ 0.00
29	1 pc	tailgate outer garnish x (not use)	\$ 0.00
30	1 pc	tailgate keyless switch x (suc)	\$ 0.00
31	1 pc	tailgate keyless switch antenna x (suc)	\$ 0.00
32	1 pc	tailgate wiper motor x (suc)	\$ 0.00
33	1 pc	tailgate wiper actuator x (suc)	\$ 0.00
34	2 ps	rear license plate lamp @ \$.00 x (suc)	\$ 0.00
	2 ps	supp tailgate lamp ✓ CRA	\$ 0.00
	1 ps	front support panel top garnish ✓ CRA	
	1 pc	front bumper absorber form. ✓ CRA	
		<u>SPECIAL NETT ITEMS</u>	
35	1 set	rear bumper reverse sensor ✓ short (centre only)	\$ 0.00



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GY1150D  
Date of Accident : 16 January 2020

Messrs BIS Motoring Pte Ltd

Date : 17 January 2020

Estimate To Repair SMC5653M - KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis No : KNAHU815VJ7208448

S/No	Quantity	Description	Amount
<b>SPECIAL NETT ITEMS</b>			
36	1 pc	rear licence plate ✓ <i>scr</i>	\$ 30.00 <i>25</i>
37	1 pc	front licence plate ✓ <i>scr</i>	\$ 30.00 <i>25</i>
38	1 pc	Caren lettering X	\$ 0.00
39	1 pc	C & E emblem ✓ <i>me</i>	\$ 0.00
40	2 pc	CRDI lettering @ \$.00	\$ 0.00
41	1 pc	KIA logo ✓ <i>me</i>	\$ 0.00
42	1 pc	windscreen primer X (not use)	\$ 0.00
43	1 set	windscreen sealant (rear) ✓ <i>me</i>	\$ 60.00 <i>40</i>
44	1 pc	windscreen inner seal ✓ <i>me</i>	\$ 80.00 <i>20</i>
			\$ 200.00
<b>LABOUR &amp; MISC. CHARGES</b>			
01		To rust-proofing of the affected areas. ✓	\$ 300.00 <i>30</i>
02		To perform water seepage test, windnoise and test-drive. ✓	\$ 80.00 <i>50</i>
03		To transfer of bootlid fittings, attachments and perform water seepage test. ✓	\$ 100.00 <i>60</i>
04		To reinstall of rear bumper parking sensor. ✓	\$ 240.00 <i>30</i>
05		To check electrical lighting concerned. → (Fit and Rev) ✓	\$ 80.00 <i>60</i>
06		To remove and refit rear windscreen glass. ✓	\$ 150.00 <i>100</i>
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. → (Fit and Rev)	\$ 1,400.00 <i>1100</i>
08		Putty and spray painting of the affected portion. → (Fit and Rev)	\$ 1,600.00 <i>1000</i>
			\$ 3,950.00
Total			\$ 4,150.00

Total

*7 Day*  
*H/S report*  
*urgent pengurusan*  
*resurvey after paint*  
*Hock ANN*  
*P3311883*  
*Hock ANN@lkkauto.com*  
*17/1/20*  
*2.30pm*

*Resurvey telan*  
*H. ANN*  
*Lkk*  
*3.30pm*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: