

Date: 20/01/2020
 Vehicle No: SLD8433T
 Model: HONDA VEZEL
 Chassis: RU11109088-2015
 Reg.Year: 2016

Third Party Insurer: AIG
 Third Party Veh No: SMN5157X
 Date of Accident: 18/01/2020

*NOT Authorized
 1/1 Pump @ ?
 Respray After Paint 11 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>Bu</i> \$972.40
2	REAR TAILGATE "VEZEL" EMBLEM	1		<i>Ne</i> \$45.80
3	REAR TAILGATE PULL HANDLE	1		<i>Ne</i> \$42.60
4	REAR TAILGATE INNER LOCK	1		<i>Ne</i> \$136.00
5	REAR TAILGATE RUBBER	1		<i>Deform</i> \$198.00
6	REAR TAILGATE INNER TRIM	1		<i>Bu</i> \$278.60
7	REAR TAILGATE INNER TRIM CLIPS	10	\$6.60	<i>Ne</i> \$66.00
8	REAR WINDSCREEN RUBBER	1		<i>Ne</i> \$74.40
9	REAR END PANEL	1		<i>Bu</i> \$478.90
10	REAR END PANEL UPPER COVERING	1		<i>Dr</i> \$208.80
11	REAR END PANEL UPPER COVERING CLIPS	6	\$6.50	<i>Ne</i> \$39.00
12	REAR SPARE TYRE PANEL UPPER BOARD COVER	1		<i>Deform</i> \$590.80
13	REAR SPARE TYRE PANEL UPPER TRAY COVER	1		<i>Bu</i> \$492.60
14	REAR TOOL KIT TRAY BOX FOAM	1		\$273.50
15	REAR TRUNK LID INNER SIDE TRAIL COVERING RH	1		\$426.40
16	REAR BUMPER	1		<i>Bu</i> \$787.90
17	REAR BUMPER CLIPS	8	\$5.80	<i>Ne</i> \$46.40
18	REAR BUMPER REFLECTOR RH	1		<i>CM</i> \$153.60
19	REAR SIDE BUMPER RH	1		<i>Bu</i> \$161.10
20	REAR SIDE BUMPER BRACKET RH	1		\$45.90
21	REAR TAIL LAMP RH	1		<i>mg/cm</i> \$487.50
22	REAR UNDER COVER ASSY	1		\$157.30
23	REAR EXHAUST PIPE	1		<i>Bu</i> \$922.50
24	REAR QUARTER PANEL RH	1		<i>Bu</i> \$770.00
25	REAR QUARTER PANEL INNER LINER RH	1		\$174.44
26	REAR QUATER PANEL INNER LINER CLIPS RH	4	\$6.20	\$24.80
27	REAR WHEEL ARCH EXTENTION COVER RH	1		<i>Dr</i> \$186.00
28	REAR FLOOR PANEL	1		REPAIR
SUB TOTAL				\$8,241.24
LESS 20%				-\$1,648.25
PARTS TOTAL				\$6,592.99

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>Ne</i> \$80.00
2	REAR BUMPER REVERSE SENSOR	1		<i>Ne</i> \$350.00

Date: 20/01/2020
Vehicle No: SLD8433T
Model: HONDA VEZEL
Chassis: RU11109088-2015
Reg.Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SMN5157X
Date of Accident: 18/01/2020

3	REAR END PANEL JOINT SEALANT	1		<i>rec</i> \$30.00 ✓
4	REAR FLOOR PANEL INSULATION PADDING	1		\$250.00 7
			S/N TOTAL	\$710.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST REAR ACCIDENT AREAS & ETC. 1400
\$1,600.00

LABOUR CHARGES TO REMOVE, REFIX, REPLACE REAR WINDSCREEN SEALANT, REAR WINDSCREEN GLASS, REAR WINDSCREEN RUBBER & ETC. TO EFFECT REPLACE OF REAR TAILGATE & ETC. 120
\$150.00

LABOUR CHARGES TO REMOVE, REPLACE, REFIX REAR EXHAUST PIPE, REAR EXHAUST PIPE HANGER & ETC. \$120.00 60

LABOUR CHARGES TO REMOVE, REPLACE REAR BUMPER REVERSE SENSOR & ETC. \$80.00 50

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. \$120.00 60

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR TAILGATE, REAR END PANEL, REAR FLOOR PANEL, REAR SIDE BUMPER RH, REAR QUARTER PANEL & ETC. 1000
\$1,600.00

TO TUFF KOTE & UNDERSEAL MATERIALS. \$200.00 90

TO CHECK WIRING & CENTRAL LOCKING SYSTEM & ETC. \$80.00 20

		LABOUR TOTAL	\$3,950.00
ONG		TOTAL	\$11,252.99

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: