

not Afford  
1/5 \$ 6000 /  
Hdny.

20 January 2020

REG NO.: SKA 9159 G

MAKE/MODEL: MERCEDES BENZ C200 WDD204042

### ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

| QTY | DESCRIPTION                                           | AMT(\$)                |
|-----|-------------------------------------------------------|------------------------|
|     | <u>LIST ITEMS</u>                                     |                        |
| 1   | Rear boot lid 506500 1675.12                          | \$ 2,200.00 ✓          |
| 2   | Rear boot hinges 17                                   | \$ <del>270.00</del> X |
| 1   | Rear boot inner trim 17                               | \$ 385.00 X            |
| 1   | Rear boot inner lock 7w1                              | \$ 295.00 ✓            |
| 1   | Rear boot logo nu                                     | \$ 58.00 ✓             |
| 1   | Rear boot weather strip 7w1                           | \$ 185.00 ✓            |
| 1   | Rear boot "CGI" emblem nu                             | \$ 58.00 ✓             |
| 1   | Rear boot "C200" emblem nu                            | \$ 62.00 ✓             |
| 1   | Rear boot "C&C" emblem nu                             | \$ 68.00 ✓             |
| 2   | Rear taillamps 0/5 CNA 635.10                         | \$ 1,670.00 /PC        |
| 2   | Rear taillamp side garnishes 17                       | \$ 250.00 X            |
| 1   | Rear end panel 2                                      | \$ 1,248.00 X          |
| 1   | Rear end panel inner garnish nu                       | \$ 165.00 X            |
| 1   | Rear bumper D/S 1461.32                               | \$ 1,885.00 ✓          |
| 2   | Rear bumper brackets CNA                              | \$ 172.00 ✓            |
| 1   | Rear bumper clip (1 set) nu 50.00                     | \$ 80.00 ✓             |
| 1   | Rear bumper inner sponge N/S                          | \$ 162.00 X            |
| 1   | Rear bumper reinforcement 2nd 615.00                  | \$ 817.00 ✓            |
| 2   | Rear bumper stays 17                                  | \$ 136.00 X            |
| 2   | Rear bumper side retainers em                         | \$ 170.00 ✓            |
| 4   | Rear bumper PDC sensors chkd 235 x 2 = 470            | \$ 1,540.00 2PCS       |
| 1   | Rear bumper tow hook cover 17                         | \$ 28.00 X             |
| 1   | Rear bumper centre chrome moulding nu 168.30          | \$ 325.00 ✓            |
| 2   | Rear bumper side chrome mouldings nu 118 x 2 = 236.00 | \$ 392.00 ✓            |
| 1   | Rear bumper inner frame pad 17                        | \$ 285.00 X            |
| 1   | Control module for park assistant kit N/S             | \$ 345.00 X            |
| 1   | Rear floor board 17                                   | \$ 310.00 X            |
| 1   | Rear exhaust silencer 17                              | \$ 1,655.00 X          |
| 2   | Rear exhaust mountings 17                             | \$ 136.00 X            |
| 1   | Rear exhaust chrome tail pipe nu                      | \$ 285.00 X            |
|     |                                                       | \$ 15,637.00           |
|     | Less 10%                                              | \$ 1,563.70            |
|     |                                                       | \$ 14,073.30           |

2- 6378.84  
107  
5740.94

S/N

LABOUR CHARGES

|   |                                                              |    |          |      |
|---|--------------------------------------------------------------|----|----------|------|
| 1 | To remove, replaced damaged lamps and check up rear wiring.  | \$ | 80.00    | 30   |
| 2 | To remove and refit inner garnishes.                         | \$ | 150.00   | 80   |
| 3 | To remove and refit rear reverse sensor.                     | \$ | 150.00   | 50   |
| 4 | To transfer boot lid mechanism and wiring assembly.          | \$ | 120.00   | 60   |
| 5 | To remove, refit and replace exhaust silencer and mountings. | \$ | 150.00   | 17 2 |
| 6 | To apply undercoating.                                       | \$ | 150.00   | 50   |
| 7 | Panel beating.                                               | \$ | 1,400.00 | 700  |
| 8 | To re-spray painting on the affected areas.                  | \$ | 1,200.00 | 800  |
|   |                                                              | \$ | 3,400.00 |      |

GRAND TOTAL :

\$ 17,473.30

7510.95  
200  
6008

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: