

ASS. REC. BY:

REF: CS/MSG 20001192/Kt B

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Crystal Lu

of MSG

Date/Time: 20.1.2020 4:15p.m

Estimated Cost:

Bill to:

OD (TP/VIS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SBY 61T

Insured: SLU 24024

at Workshop n/s: S Thrift Automotive

Tel: 62841542

of BIK 8 Sun ming Industrial Estate #01-64/6L

Policy No: 29114156

Claim No: 617996

Sum Insured:

Excess:

Make of Veh:

D.O.A 17.1.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 20.1.2020 4:20p.m

Person Contacted: Yan zhung

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SBY 61T - X
	SLU 24024 - X
29/1	LI Rep 8 4150k email & confirmed (red: 6049.20: 61%)

Summer Lee (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Monday, 20 January, 2020 4:15 PM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned

ACCIDENT INVOLVING SBY61T & SLU2402H (GRAB) ON 17-1-2020. O REF: JEQ/200095/0120/S3

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,
Crystal Lee
Admin Officer, Claims Services (In-House Survey)
D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Winnie Chua <pingping_chua@sg.msig-asia.com>
Sent: Monday, 20 January 2020 3:38 PM
To: Sim Teo Koon <tk_sim@juseq.com.sg>
Cc: Helene Phua <helene_phua@sg.msig-asia.com>; Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Subject: FW: ACCIDENT INVOLVING SBY61T & SLU2402H (GRAB) ON 17-1-2020. O REF: JEQ/200095/0120/S3

Hi,

Thank you for your selection.

We will proceed to appoint/assign Kenneth Kong (LKK Auto Consultants Pte Ltd) via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]

Sent: Monday, 20 January 2020 2:22 PM

To: Winnie Chua <pingping_chua@sg.msig-asia.com>

Cc: Helene Phua <helene_phua@sg.msig-asia.com>; 'S Three Automotive' <admin@sthreeautomotive.com.sg>

Subject: RE: ACCIDENT INVOLVING SBY61T & SLU2402H (GRAB) ON 17-1-2020. O REF: JEQ/200095/0120/S3

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sirs,

We refer to your email.

Our client is agreeable to appoint **Kenneth Kong (LKK Auto Consultants Pte Ltd)** as a single joint expert.

Please be informed that our client's motor vehicle is available for inspection at the under-stated workshop: -

S THREE AUTOMOTIVE RECOVERY PTE LTD

Blk 8 Sin Ming Industrial Estate #01-64/66,

Singapore 575643

Tel: 6284 1542; Fax: 6487 5315

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)

JusEquity Law Corporation.

Tel: 6506 6065, Fax: 6536 9339

E-mail: tk_sim@juseq.com.sg

From: Winnie Chua [mailto:pingping_chua@sg.msig-asia.com]

Sent: 20 January 2020 13:37

To: Sim Teo Koon <tk_sim@juseq.com.sg>

Cc: Helene Phua <helene_phua@sg.msig-asia.com>

Subject: FW: ACCIDENT INVOLVING SBY61T & SLU2402H (GRAB) ON 17-1-2020. O REF: JEQ/200095/0120/S3

Hi,

We refer to your email/faxed dated 20/01/2020.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) **MSIG In-House Surveyors**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Xing Guo Qiang	6) Chow Bo Xiong
2) Kenneth Kong	7) Siew Meng Hui
3) Marcus Chua	8) Daniel Chan
4) Ng You Han	9) Victor Png
5) Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- (a) ***Fast lane settlement is not applicable for cases that liability is in dispute***
- (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]

Sent: Monday, 20 January 2020 11:00 AM

To: Motor Survey <motorsurvey@sg.msig-asia.com>

Subject: ACCIDENT INVOLVING SBY61T & SLU2402H ON 17-1-2020. O REF: JEQ/200095/0120/S3

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sirs,

Please refer to our notice of accident.

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)

JusEquity Law Corporation

133 New Bridge Road #10-03, Chinatown Point,

Singapore 059413

Tel: 6506 6065 / 6536 9339

Fax: 6536 5368

E-mail: tk_sim@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/01/2020 15:56
Date Of Accident	17/01/2020 08:10
Exact Location Of Accident	HAVELOCK RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBY61T
Insured/Policyholder	
Name Of Registered Owner	PHILIP TEO CHOON HIEN
NRIC No	SXXXX080Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92226161
Alternative Phone No	OTHERS-NOPHONE

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5084364933-03
Cover Note Number	

Driver

Name of Driver	PHILIP TEO CHOON HIEN
NRIC No	SXXXX080Z
Date Of Birth	03/12/1974
Occupation	OUTDOOR
Date Of Driving Pass	17/11/1994
Driving Experience	25 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92226161
Fax Number	
Contact Number	OTHERS-NOPHONE
Email Address	NOEMAIL

Address	42 WESTWOOD TERRACE
Postcode	648625
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU2402H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the EIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CITY AUTO PTE LTD
 511 G Serangoon Road
 #01-4040-61, Serangoon City
 Singapore 550511
 Tel: 6453 4251 Fax: 6453 7844
 (Claims Services)


 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/PIA No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While driving straight along the road I got vehicle B suddenly cut into my lane abruptly from the left lane and stalled the front left portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name
 ID No./Phone No.:

CITY AUTO FTE LTD
 Blk 2 2nd Floor, Room
 #01-55/56/57/58/59/60/61/62
 Singapore 110543
 Tel: 6353 4241 Fax: 6353 7543
 (Caring Without)

Work Order: R036262
 VIN: SBY61T
 Year: 17
 Date: 21.1.20 12:02



SBY61T

53

Factory Japan 2019.0.2 : Honda : Shuttle : GP7

Front : Left

Actual	Before	Specified Range
-2°22'	-2°21'	-1°00' 1°00'
6°05'	6°05'	4°00' 6°00'
0°16'	0°18'	-0°09' 0°09'
14°00'	13°59'	
11°38'	11°38'	

Front : Right

Actual	Before	Specified Range
-0°11'	-0°11'	-1°00' 1°00'
6°41'	6°41'	4°00' 6°00'
-0°03'	-0°03'	-0°09' 0°09'
12°00'	12°00'	
11°50'	11°50'	

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-2°12'	-2°10'	-1°00' 1°00'
0°23'	0°23'	
2°00'	1°58'	
0°14'	0°15'	-0°17' 0°17'

Rear : Left

Actual	Before	Specified Range
-1°44'	-1°43'	-2°45' -0°45'
0°08'	0°08'	0°00' 0°17'

Rear : Right

Actual	Before	Specified Range
-1°28'	-1°29'	-2°45' -0°45'
0°01'	0°01'	0°00' 0°17'

Camber
 Toe

Rear

Cross Camber
 Total Toe
 Thrust Angle
 Axle Offset

Actual	Before	Specified Range
-0°15'	-0°14'	-1°00' 1°00'
0°09'	0°09'	0°00' 0°34'
0°04'	0°04'	
0mm	0mm	

Not Withheld
 61 Sony @ 4150/-
 Repair After Paint



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO :
 ATTN : MOTOR CLAIM DEPT. T/P VEH. NO. : SLU2402H

ESTIMATE REPORT 1st QUOTATION JOB NO :
 OWNER'S PARTICULAR
 NAME : PHILIP TEO CHOON HIEN CONTACT :
 ADDRESS :
 LICENSE NO. : SBY61T CHASSIS NO :
 MAKE / MODEL : HONDA SHUTTLE ENGINE NO :
 OWNER'S INSURER : NTUC
 JOB-CODE : TP S/A : ACCIDENT DATE : 17-Jan-20

CLAIM DETAIL

MATERIALS	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR. DISP	REV. PRICE
1 FRONT BUMPER 1050	CM 1.00	1050.00	20.00	840.00	Y	✓
2 FRONT BUMPER FOG LAMP LOWER COVER RH	Sm 2.00	76.00	20.00	60.80	Y	X
3 FRONT BUMPER FOG LAMP UPP COVER RH	Sm 2.00	56.00	20.00	44.80	Y	X
4 FRONT BUMPER TOW COVER	Sm 1.00	22.00	20.00	17.60	Y	X
5 FRT BUMPER BRACKET RH	Sm 1.00	48.00	20.00	38.40	Y	X
6 FRT BUMPER SIDE RETAINER RH	Sm 1.00	13.00	20.00	10.40	Y	X
7 FRT BUMPER REINFORCEMENT	R 1.00	320.00	20.00	256.00	Y	X
8 FRT BUMPER LOWER GRILLE CENTRE	Sm 1.00	115.00	20.00	92.00	Y	X
9 HEADLAMP LED RH 2128.70	Sm 1.00	2300.00	20.00	1840.00	Y	✓
10 HEADLAMP CHROME MOULDING RH	Sm 1.00	228.50	20.00	182.80	Y	X
11 FRONT FENDER HYBRID LOGO RH	Sm 1.00	38.00	20.00	30.40	Y	✓
12 FRT FENDER RH	R 1.00	435.00	20.00	348.00	Y	X
13 FRT FENDER INNER SHIELD RH	CM 1.00	110.00	20.00	88.00	Y	✓
14 FRONT SHOCK ABSORBER RH 420	B 1.00	420.00	20.00	336.00	Y	X
15 FRONT KNUCKLE ARM RH 360	B 1.00	385.00	20.00	308.00	Y	X
16 FRONT KNUCKLE BEARING RH	Sm 1.00	185.00	20.00	148.00	Y	X
17 FRONT LOWER ARM RH 290.20	D 1.00	345.00	20.00	276.00	Y	X
18 ROCKER SPOILER RH	Sm 1.00	1050.00	20.00	840.00	Y	X
19 FRONT RIM COVER RH	Sm 1.00	220.00	20.00	176.00	Y	X
20 WING MIRROR RH	Sm 1.00	695.00	20.00	556.00	Y	X

TOTAL (PARTS): 8111.50 6489.20

SPECIAL NETT ITEM

1 FRT BUMPER CLIPS (1 SET)	Sm 1.00	80.00	0.00	80.00	Y	505m
2 FRONT RIM RH	D 1.00	500.00	0.00	500.00	Y	4005m
3 FRONT TYRE RH	Sm 1.00	380.00	0.00	380.00	Y	X

4	FRONT FENDER INNER SHIELD CLIPS RH	<i>na</i> 1.00	80.00	0.00	80.00	Y	<u>50.00</u>
5	ROCKER SPOILER CLIPS	<i>na</i> 1.00	120.00	0.00	120.00	Y	<u>X</u>
6	FRONT NUMBER PLATE	<i>na</i> 1.00	50.00	0.00	50.00	Y	<u>X</u>
TOTAL (PARTS) :			1210.00		1210.00		

LABOUR

1	STRENGTHEN & PANEL BEAT ACCIDENT AREA	1.00	1200.00	0.00	1200.00	Y	<u>400</u>
2	SPRAY PAINTING ON AFFECTED AREA	1.00	1200.00	0.00	1200.00	Y	<u>400</u>
3	RESPRAY TUFF KOTE ON ACCIDENT AREAS	<i>na</i> 1.00	120.00	0.00	120.00	Y	<u>X</u>
4	CHECK & REPAIR WIRING SYSTEM	1.00	80.00	0.00	80.00	Y	<u>200</u>
5	R&R REAR SUSPENSION LH	1.00	380.00	0.00	380.00	Y	<u>1800</u>
6	CONDUCT FULL WHEEL ALIGNMENT	1.00	120.00	0.00	120.00	Y	<u>600</u>
			3100.00		3100.00		

TOTAL PARTS & LABOUR 12421.50 10799.20

EXCESS : : \$S _____

NO. OF DAY : 4 days

RE-SURVEY : ~~BEFORE~~ / AFTER PAINTING

~~PART BY PART~~ OR LUMP-SUM : \$S _____

DATE OF SURVEY : 21 / 1 / 2020

SURVEY BY : Kenneth

CONTACT NO : 96910663

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature: _____
Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20001192/KTF3N2
Date: 05/02/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756
Claimant Vehicle No :	SBY61T	Insured Vehicle No :	SLU2402H
Date of Loss:	17/01/2020	Nature of Claim:	TP
		Claim No:	617996

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBY61T	Engine No:	LEB4247663
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71030866
Reg. Date:	21/09/2016 (Man. Year: 2016)	Odometer:	105975 km
Colour:	Metallic Green		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,699.20	4,165.52	3,533.68	45.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	1,060.00	2,040.00	65.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,799.20	5,225.52	5,573.68	51.61
Approved Total (Overridden) (S\$)		4,150.00		
(S\$)	10,799.20	4,150.00	6,649.20	61.57
+ GST 7.00/7.00% (S\$)	755.94	290.50	465.44	61.57
Nett Amount (S\$)	11,555.14	4,440.50	7,114.64	61.57

INSPECTION

Date of Assignment:	21/01/2020	S Three Automotive & Recovery Pte Ltd - Sin Ming (HQ) BLK 8 SIN MING IND EST #01-64/66 Singapore 575643
Date Inspected:	21/01/2020 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Feb 2020)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBY61T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,050.00 FL	*1,050.00 FL
2	2		*FRONT BUMPER FOG LAMP LOWER COVER RH	Serviceable	76.00 FL	*- FL
3	2		*FRONT BUMPER FOG LAMP UPP COVER RH	Serviceable	56.00 FL	*- FL
4	1		*FRONT BUMPER TOW COVER	Serviceable	22.00 FL	*- FL
5	1		*FRT BUMPER BRACKET RH	Serviceable	48.00 FL	*- FL
6	1		*FRT BUMPER SIDE RETAINER RH	Serviceable	13.00 FL	*- FL
7	1		*FRT BUMPER REINFORCEMENT	Repair	320.00 FL	*- FL
8	1		*FRT BUMPER LOWER GRILLE CENTRE	Serviceable	115.00 FL	*- FL
9	1		*HEADLAMP LED RH	Cut	2,300.00 FL	*2,128.70 FL
10	1		*HEADLAMP CHROME MOULDING RH	Serviceable	228.50 FL	*- FL
11	1		*FRONT FENDER HYBRID LOGO RH	Necessary	38.00 FL	*38.00 FL
12	1		*FRT FENDER RH	Repair	435.00 FL	*- FL
13	1		*FRT FENDER INNER SHIELD RH	Cracked	110.00 FL	*110.00 FL
14	1		*FRONT SHOCK ABSORBER RH	Bent	420.00 FL	*420.00 FL
15	1		*FRONT KNUCKLE ARM RH	Bent	385.00 FL	*360.00 FL
16	1		*FRONT KNUCKLE BEARING RH	Necessary	185.00 FL	*185.00 FL
17	1		*FRONT LOWER ARM RH	Distorted	345.00 FL	*290.20 FL
18	1		*ROCKER SPOILER RH	Serviceable	1,050.00 FL	*- FL
19	1		*FRONT RIM COVER RH	Serviceable	220.00 FL	*- FL
20	1		*WING MIRROR RH	Serviceable	695.00 FL	*- FL
21	1		*SET FRT BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
22	1		*FRONT RIM RH	Dented	500.00 FS	*400.00 FS
23	1		*FRONT TYRE RH	Serviceable	380.00 FS	*- FS
24	1		*FRONT FENDER INNER SHIELD CLIPS RH	Necessary	80.00 FS	*50.00 FS
25	1		*ROCKER SPOILER CLIPS	Not Necessary	120.00 FS	*- FS
26	1		*FRONT NUMBER PLATE	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,321.50	5,081.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,622.30	916.38
Total Parts (\$\$)	7,699.20	4,165.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRENGTHEN & PANEL BEAT ACCIDENT AREA	New	1,200.00	400.00
2	SPRAY PAINTING ON AFFECTED AREA	New	1,200.00	400.00
3	RESPRAY TUFF KOTE ON ACCIDENT AREAS	New	120.00	0.00
4	CHECK & REPAIR WIRING SYSTEM	New	80.00	20.00
5	R&R REAR SUSPENSION LH	New	380.00	180.00
6	CONDUCT FULL WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (S\$)			3,100.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >