



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2003163
INV Date 15/04/2020
Reference CS/SMO20001203/Avd3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. SLL 4939K
Insured Veh. FBJ 4474M
Claim No. CMTD2000336/GPL
Policy No.
Accident Date 20/01/2020
Inspection Date 17/02/2020

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20001203/Avd3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 15-04-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBJ 4474M	Veh. Inspected	SLL 4939K
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2000336/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	20/01/2020
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C200	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WDD2050422R252815	Colour	GREY
	Odometer	119429	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R18	MICHELIN	6 mm
	L/H Front Tyre	245/40 R18	MICHELIN	6 mm
	R/H Rear Tyre	245/40 R18	MICHELIN	6 mm
	L/H Rear Tyre	245/40 R18	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/01/2020	Inspection Date	17/02/2020
	Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 4939K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,887.60	1,545.00
1	REAR BUMPER LOWER GRILLE	CUT	390.50	390.50
2	REAR BUMPER SIDE HOLDER @\$62.70	NECESSARY	125.40	125.40
1	REAR BUMPER LH SIDE GARNISH	NOT NECESSARY	36.30	-
1	REAR BUMPER LOWER COVER	DEFORMED	302.50	302.50
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	750.20	-
1	REAR BUMPER SPONGE	NOT NECESSARY	149.60	-
2	REAR BUMPER BRACKET @\$64.90	NOT NECESSARY	129.80	-
1	SET REAR BUMPER CLIPS	NECESSARY	66.00	30.00
1	REAR LH LAMP	CUT	738.10	738.10
1	REAR LH EXHAUST PIPE	NOT NECESSARY	1,742.40	-
1	REAR LH EXHAUST CHROME	CUT	435.60	277.00
1	REAR LH EXHAUST PIPE MOUNTING	NOT NECESSARY	52.80	-
1	REAR LH EXHAUST PIPE CHROME TOP GARNISH	NOT NECESSARY	77.00	-
1	REAR LH EXHAUST PIPE TOP COVER	NOT NECESSARY	203.50	-
1	REAR LH EXHAUST PIPE SIDE COVER	NOT NECESSARY	148.50	-
1	REAR LH LAMP LOWER GARNISH	NOT NECESSARY	278.30	-
	LESS 10% DISCOUNT		-751.41	-340.85
			6,762.69	3,067.65
	<u>SPECIAL NETT ITEMS</u>			
4	REAR REVERSE SENSOR @\$198.00 (SN)	DAMAGED (1 PC ONLY)	792.00	198.00
			792.00	198.00
	<u>LABOUR</u>			
	REMOVE & REINSTALL EXHAUST PIPE.	NOT NECESSARY	200.00	-
	REMOVE & REINSTALL REVERSE SENSOR.		280.00	60.00
	REMOVE & REINSTALL BOOTLID INNER GARNISH.	NOT NECESSARY	200.00	-
	REMOVE & REPLACE & REPAIR CONSISTENT TO THE ACCIDENT.		1,200.00	300.00
	RESPRAY PAINTING.		1,100.00	300.00

Report Ref No. CS/SMO20001203/Avd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.	NOT NECESSARY	100.00	-
			3,080.00	660.00
GRAND TOTAL			10,634.69	3,925.65
RECOMMENDED COST OF REPAIRS				3,925.65

Report Ref No. CS/SMO20001203/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 4939K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 4939K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01 -25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

