

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 26880

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0077/2020/NS
Date	:	20-Jan-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SGK 671 Y

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Tong Wei Wei
Address	:	293A Bukit Batok St 21 #29-504 Singapore 651293
Telephone	:	(HP) +65 90925905
Type of Claim	:	Third Party Claims
Policy No.	:	1900079990
Vehicle No	:	SBA 3113 J
Model Code	:	Audi Q2 1.0 TFSI S Tronic
Model / Year	:	26/3/2019
Engine No	:	CHZ C27505
Chassis No	:	WAUZZZGA1KA040615
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	17-Jan-20
Place of Accident	:	AYE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SBA 3113]

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N	\$ 280.00	✓
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.		\$ 1,200.00 500	
3	TP respray rear bumper.		\$ 1,000.00 550	
4	To carry out diagnostic check.	S/N	\$ 192.00	✓
TOTAL LABOUR CHARGES		:	<u><u>\$ 2,672.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBA 3113]

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>Regis</i>	\$ 1,108.00	+
2	REAR BUMPER FIXING PARTS <i>neu</i>	\$ 73.00	+
3	REAR BUMPER SPOILER - LH <i>del d.</i>	\$ 268.00	✓
4	REAR BUMPER TOWING EYE COVER <i>neu</i>	\$ 41.00	+
5	REAR LIGHT REFLECTOR - LH / RH <i>neu</i>	2 \$ 56.00	+
6	REAR BUMPER CARRIER <i>neu</i>	\$ 517.00	+
7	REAR BUMPER HOLDING STRAP - LH / RH <i>neu</i>	2 \$ 24.00	+
8	REAR BUMPER GUIDE SECTION - LH / RH <i>neu</i>	2 \$ 102.00	+
9	REAR PARKING AID SENSOR - INNER <i>neu</i>	2 TBC	✓
10	REAR PARKING AID SEAL RING	4 \$ 14.00	+
11	REAR WHEEL COVER - LH / RH <i>del</i>	2 \$ 320.00	✓
12	SUNDRIES <i>?</i>	\$ 200.00	?

TOTAL SPARE PARTS CHARGES

: \$ 2,723.00

TOTAL LABOUR CHARGES

: \$ 2,672.00

GRAND TOTAL

: \$ 5,395.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Admin Lij
Surveyed Date : 21/01/20
Authorised Date :
Excess Cost :
Liability :
Remarks : not authorised, 03 days.

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant