

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 26880

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0077/2020/NS
Date	:	20-Jan-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : **SGK 671 Y**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Tong Wei Wei
Address	:	293A Bukit Batok St 21 #29-504 Singapore 651293
Telephone	:	(HP) +65 90925905
Type of Claim	:	Third Party Claims
Policy No.	:	1900079990
Vehicle No	:	SBA 3113 J
Model Code	:	Audi Q2 1.0 TFSI S Tronic
Model / Year	:	26/3/2019
Engine No	:	CHZ C27505
Chassis No	:	WAUZZZGA1KA040615
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	17-Jan-20
Place of Accident	:	AYE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SBA 3113]

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N	\$ 280.00 ✓	✓
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.		\$ 1,200.00 500 ✓	✓
3	TP respray rear bumper.		\$ 1,000.00 550 ✓	✓
4	To carry out diagnostic check.	S/N	\$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		:	<u>\$ 2,672.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Steve 26/2/20

Material List for Accident Vehicle Regn No. SBA 3113]

S/N	Parts Description	y/long/welder 20/02	Damaged Parts & Prices	
			S/Nett	Remarks
1	REAR BUMPER Regis	BR	\$ ✓ 1,108.00	+ 886.40
2	REAR BUMPER FIXING PARTS	new	\$ 73.00	x
3	REAR BUMPER SPOILER - LH	del	\$ ✓ 268.00	✓ 214.00
4	REAR BUMPER TOWING EYE COVER	new	\$ 41.00	x
5	REAR LIGHT REFLECTOR - LH / RH	new	2 \$ 56.00	x
6	REAR BUMPER CARRIER	new	\$ 517.00	x
7	REAR BUMPER HOLDING STRAP - LH / RH	3 new	2 \$ 24.00	x
8	REAR BUMPER GUIDE SECTION - LH / RH		2 \$ 102.00	x
9	REAR PARKING AID SENSOR - INNER	2 new	2 TBC	✓
10	REAR PARKING AID SEAL RING		4 \$ 14.00	x
11	REAR WHEEL COVER - LH / RH	del	2 \$ ✓ 320.00	✓ 256.00
12	SUNDRIES ? not nec		\$ 200.00	X

TOTAL SPARE PARTS CHARGES

: \$ 2,723.00

TOTAL LABOUR CHARGES

: \$ 2,672.00

GRAND TOTAL

: \$ 5,395.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan Lij
Surveyed Date : 21/01/20
Authorised Date :
Excess Cost :
Liability :
Remarks : not authorised, 03 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant