

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 26629

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0067/2020/NS
Date : 17-Jan-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

4 days - ok - jb - 27 Jun 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Rajan Praburam
Address : 143 Serangoon Avenue 3
#14-01
Singapore 556121
Telephone : HP +65 91849073
Type of Claim : Own Damage Claims
Policy No. : 1900247429
Vehicle No : **SJW 4392 C**
Model Code : Audi A4 Sedan 2.0 TFSI 8W
Model / Year : Nov-19
Engine No : CVK 087255
Chassis No : WAUZZZF44KA113388
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Jan-20
Place of Accident : The Springbloom Condo

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJW 4392 C

S/N Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To dismantle front bumper, rhs front fender and rhs headlight. To renew rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00	\$ 1,250.00
3	To respray front bumper and rhs front fender.	\$ 2,000.00	\$ 550.00
4	To carry out diagnostic checks.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 5,122.00	\$ 2,472.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJW 4392 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT FENDER - RH	\$ 722.00	\$ 577.60
2	FRONT FENDER ATTACHMENT PARTS	\$ 190.00	
3	FRONT FENDER CLOSING ELEMENT - RH	\$ 47.00	
4	FRONT FENDER BRACKET - RH	\$ 33.00	
5	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	\$ 46.00	
6	FRONT FENDER BRACE - RH	\$ 112.00	
7	WHEEL HOUSING LINER - RH	\$ 228.00	
8	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 219.00	
9	FRONT BUMPER GUIDE SECTION - RH	\$ 36.00	
10	WHEEL SPOILER - RH	\$ 69.00	
11	WHEEL SPOILER TRIM - RH	\$ 34.00	
12	STONE CHIP GUARD - RH	\$ 48.00	\$ 37.92
13	FENDER LEDGE COVER - RH	\$ 29.00	\$ 23.20
14	FENDER LEDGE TOP COVER - RH	\$ 21.00	\$ 16.72
15	LED HEADLIGHT - RH	\$ 7,321.00	\$ 5,856.80
16	SUNDRIES	\$ 200.00	\$ 23.84
TOTAL SPARE PARTS CHARGES		\$ 9,355.00	\$ 6,536.08
TOTAL LABOUR CHARGES		\$ 5,122.00	\$ 2,472.00
GRAND TOTAL		\$ 14,477.00	\$ 9,008.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant