

22/03/2002

ASS. REC. BY:

REF: CS/FWD 20001242

KT-359

Special Instruction:

Supervisor: Kohnath

ASSIGNMENT (Office)

From (Person): Vanessa Chan

of

FWD

Date/Time: 21 Jan. 2020 11.49 a.m.

Estimated Cost:

Bill to:

OD TP/WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKW 49407

Insured:

SLG 8254C

at Workshop m/s H C Auto

Tel:

94570679

of 160 S.M. Ming Drive #05-09

Policy No: PNPV2013-00012996-01

Claim No: 1202000003363

Sum Insured:

Excess:

D.O.A. 20. Jan. 2020

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 21.1.2020 D.00p.11

Person Contacted:

Joe

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKW 49407 - X
	SLG 8254 C - X
28/1 -	Revised 1A in merman
20/2	LI Sp & 2700 enot & carbon (red. 9400.92: 77%)

ASS. REC. BY:

REF:

FWD/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SKW 49407

Yr Regn:

10, 15.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Honda Vezel

c.c

1496

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

122268

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU1

1104260

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

20/1/20

D.O.I.

21/1/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 24 FEB 2020

Date/Time, File Pass to?

24/2 Typist

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

250

Transportation:

50

S - RS - SI

50 + 50

Fees

Others

10

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

2700/-

Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Tuesday, 21 January 2020 11:49 AM
To: 'admin-d@lkkauto.com'; 'admin-a@lkkauto.com'
Cc: eileen.bay@fwd.com; motorclaims.sg@fwd.com
Subject: PRE REPAIR SURVEY --- YOUR REF: SLG 8254 C --- ACCIDENT INVOLVING SKW 4940 J (#1) AND SLG 8254 C (#2) AND GBG 1097 D (#3) AND SKD 362 C (#4) ON 20 JANUARY 2020 ALONG LORNIE ROAD AT ABOUT 0945 HOURS

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.

Kindly upload all correspondence emails/documents sent to you into Merimen.

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Venessa Chan - SGUser

Sent: Tuesday, January 21, 2020 11:47 AM

To: 'Elaine Toh'

Cc: ylteam26@gmail.com; Motor Claims SG - SG Common

Subject: PRE REPAIR SURVEY --- YOUR REF: SLG 8254 C --- ACCIDENT INVOLVING SKW 4940 J (#1) AND SLG 8254 C (#2) AND GBG 1097 D (#3) AND SKD 362 C (#4) ON 20 JANUARY 2020 ALONG LORNIE ROAD AT ABOUT 0945 HOURS

Hi Elaine,

Thank you for your selection of LKK Auto Consultants Pte Ltd.
We will proceed to assign survey.

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Elaine Toh [<mailto:Elainetoh@visionlawllc.com>]

Sent: Tuesday, January 21, 2020 11:31 AM

To: Venessa Chan - SGUser

Cc: ylteam26@gmail.com; Motor Claims SG - SG Common; Eileen Bay - SGUser

Subject: RE: PRE REPAIR SURVEY --- YOUR REF: SLG 8254 C --- ACCIDENT INVOLVING SKW 4940 J (#1) AND SLG 8254 C (#2) AND GBG 1097 D (#3) AND SKD 362 C (#4) ON 20 JANUARY 2020 ALONG LORNIE ROAD AT ABOUT 0945 HOURS

Importance: High

Our Ref: SKW 4940 J (et)
WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to your email of 20 January 2020 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **LKK AUTO CONSULTANTS PTE LTD** as the Single Joint Expert for this matter.

Venue:

H C Auto Pte Ltd
160 Sin Ming Drive
#05-09 Sin Ming Auto City
Singapore 575722

Contact:

Mr. Joe @ 9457-0678 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.



FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

Appointed surveyor
(Name & Signature)

Date & Time of Inspection :

Regards,
Elaine Toh (Secretary)
VISION LAW LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 65342811 (Ext. 122) / Fax: 65356802

cc: SKW 4940 J – By fax: 64578287 only

From: venessa.chan@fwd.com [<mailto:venessa.chan@fwd.com>]

Sent: Monday, 20 January, 2020 5:11 PM

To: Elainetoh@visionlawllc.com

Cc: ylteam26@gmail.com; motorclaims.sg@fwd.com; eileen.bay@fwd.com

Subject: PRE REPAIR SURVEY --- YOUR REF: SLG 8254 C --- ACCIDENT INVOLVING SKW 4940 J (#1) AND SLG 8254 C (#2) AND GBG 1097 D (#3) AND SKD 362 C (#4) ON 20 JANUARY 2020 ALONG LORNIE ROAD AT ABOUT 0945 HOURS

WITHOUT PREJUDICE

Dear Elaine,

Refer to your email dated on 20.01.2020 of the PRI Notice of your client's vehicle SKQ4940J ,

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT APPRAISAL PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.


***Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.**

Best Regards,

Venessa Chan
Administrative Assistant, Claims



FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
E venessa.chan@fwd.com



From: Elaine Toh [<mailto:Elainetoh@visionlawllc.com>]

Sent: Monday, January 20, 2020 5:06 PM

To: Motor Claims SG - SG Common

Cc: ylteam26@gmail.com

Subject: PRE REPAIR SURVEY --- YOUR REF: SLG 8254 C --- ACCIDENT INVOLVING SKW 4940 J (#1) AND SLG 8254 C (#2) AND GBG 1097 D (#3) AND SKD 362 C (#4) ON 20 JANUARY 2020 ALONG LORNIE ROAD AT ABOUT 0945 HOURS

Importance: High

Our Ref: SKW 4940 J (et)
WITHOUT PREJUDICE

Dear Sir/Madam,

We are instructed by **TOMMIE LIM WEE HIANG** to notify you of a road traffic accident on 20 January 2020 at about 0945 hours along Lornie Road involving our client's vehicle registration number SKW 4940 J and vehicle registration number SLG 8254 C driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thank you.

Regards,

Elaine Toh (Secretary)

VISION LAW LLC

133 New Bridge Road

#18-01/02 Chinatown Point

Singapore 059413

Tel: 65342811 (Ext. 122) / Fax: 65356802

cc: SKW 4940 J – By fax: 64578287 only

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Address : 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments. Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Address : 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments. Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eileen Bay

Date: 28 Jan 2020

Preliminary Advice

Insured Vehicle No	: SLG8254C	Accident Date	: 20/01/2020
TP Vehicle No	: SKW4940J	Assignment Date	: 21/01/2020
Make	: HONDA ACCORD	Est. Duration of Repair	: 5.00
Date of Inspection	: 21/01/2020		
Inspection At	: HC AUTO PTE LTD (HQ) BLOCK 20 SECTOR A SIN MING IND. EST. #01-20 SINGAPORE 575678		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,100.92
Revised Amount	:S\$	3,135.00
Check Items (Estimated)	:S\$	3,180.80
Total	:S\$	6,315.80

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on WP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/01/2020 13:55
Date Of Accident	20/01/2020 09:45
Exact Location Of Accident	LORNIE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW4940J
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	TOMMIE LIM WEE HIANG (TOMMIE LIN WEIXIAN)
NRIC No	SXXXX866J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97475163
Alternative Phone No	OFFICE-97475163

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5113077772 (CLASSIC)
Cover Note Number	

Driver

Name of Driver	TOMMIE LIM WEE HIANG (TOMMIE LIN WEIXIAN)
NRIC No	SXXXX866J
Date Of Birth	27/02/1976
Occupation	INDOOR
Date Of Driving Pass	27/05/1996
Driving Experience	23 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97475163
Fax Number	
Contact Number	OFFICE-97475163
Email Address	NOEMAIL

Address	BLK 126 BISHAN STREET 12 #08-147
Postcode	S570126
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 20/01/2020 @ AROUND 0945HRS. I WAS TRAVELING ALONG FROM THOMSON TO LORNIE ROAD. FRONT VEHICLE STOPPED. I STOPPED AS WELL. MOMENTS LATER, MY CAR WAS PUSHED FORWARD. I STEPPED DOWN FROM THE CAR AND REALIZED A TOTAL OF 4 VEHICLES WERE INVOLVED IN THE ACCIDENT. I DID NOT EXCHANGE PARTICULARS AS I'M IN A RUSH. NO INJURIES.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG8254C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBG1097D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SKD862C
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC SIN MING VICOM LTD
385 SIN MING DRIVE (S) 575718


6697 5243 / 6455 5358
ZARIFAH MAJEED

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO GIA REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

IDAC SIN MING VICOM LTD

385 SIN MING DRIVE (S) 575718

6697 5243 / 6455 5358

ZARIFAH MAJEED

Reporting Centre Personnel's Signature

Name:

NRIC/ID No.:



H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date : 20 / 01 / 2020

ESTIMATE COSTS OF REPAIR

Mr Tommie Lim Wee Hiang

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

Dear Sir / Madam ,

Vehicle no. : SKW 4940 J - Honda Vezel 1.5X CVT
Accident date : 20-Jan-20

*Not work
61 Sing 82700h
Repair After Paint
4 days*

Quantity	Descriptions	Amount (S\$)
1	1 pc tail gate <i>1122-60</i>	\$ <i>B</i> 1,450.00 ✓
2	1 pc tail gate weather strip	\$ <i>Sm</i> 185.00 X
3	1 pc tail gate inner lock	\$ <i>n</i> 310.00 X
4	2 pcs tail gate hinge 1 @ 55.00	\$ <i>n</i> 110.00 X
5	2 pcs tail gate reflector 1 @ 350.00	\$ <i>Sm</i> 700.00 X
6	1 pc tail gate inner trim	\$ <i>Sm</i> 325.00 X
7	1 pc tail gate Honda logo	\$ <i>an</i> 27.65 X
8	1 pc tail gate ' VEZEL ' emblem	\$ <i>n</i> 55.00 ✓
9	1 pc rear end panel	\$ <i>n</i> 620.00 X
10	1 pc rear end panel inner garnish <i>184</i>	\$ <i>my n</i> 216.00 X
11	1 pc rear bumper fascia <i>745.30</i>	\$ <i>Ar</i> 1,120.00 ✓
12	2 pcs rear bumper side 1 @ 235.00	\$ <i>Sm</i> 470.00 X
13	2 pcs rear bumper bracket 1 @ 35.00	\$ <i>n</i> 70.00 X
14	2 pcs rear bumper side retainer 1 @ 32.00	\$ <i>Sm</i> 64.00 X
15	2 pcs rear bumper reflector 1 @ 160.50	\$ <i>Sm</i> 321.00 X
16	1 pc rear bumper buzzer	\$ <i>CMS</i> 95.00 ✓
17	2 pcs tail lamps 1 @ 650.00	\$ <i>Sm</i> 1,300.00 X
18	1 pc rear windscreen glass molding	\$ <i>n</i> 150.00 ✓
19	1 pc rear exhaust pipe	\$ <i>n</i> 650.00 X
20	2 pcs rear exhaust box aluminium cover	\$ <i>n</i> 145.00 X
21	1 pc rear spare tyre board	\$ <i>Sm</i> 280.00 X
		\$ 8,663.65
	Less 20 %	\$ 1,732.73
	Balance C/FD	\$ 6,930.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Balance B/FD (SKW 4940 J)

\$ 6,930.92

22	1 pc	rear no. plate
23	1 pc	rear panel inner seal
24	1 pc	rear windscreen inner seal
25	1 pc	rear windscreen inner gum
26	1 set	reverse sensor

\$	100.00	sn	X
\$	250.00	sn	X
\$	60.00	sn	30sn
\$	60.00	sn	40sn
\$	350.00	sn	200sn
\$	7,750.92		

Labour charges

\$ 1,800.00 500

To putty and spray painting

\$ 1,600.00 400

To check wiring

\$ 120.00 15

To transfer tail gate

\$ 120.00 60

Remove and refix rear windscreen glass

\$ 160.00 120

Refix reverse sensor

\$ 100.00 50

Remove and refix cushion seat, garnish, carpet & etc.

\$ 180.00 80

Remove and refix exhaust box

\$ 120.00 X

To re-seal anti rust

\$ 150.00 30

Plus : 7% GST

\$ 12,100.92

Sub_Total

\$ 847.06

\$ 12,947.98

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Jan 2020 Edit Reg		21 Jan 2020 00:00 Edit Adj Rpt	S\$2,700.00 Edit Estimates	S\$2,700.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Tan Chin Guan, ID: S8420074C		
Main Claimant:	TOMMIE LIM WEE HIANG (TOMMIE LIN WEIXIAN), ID: S7605866J		
Vehicle Reg. No.:	SKW4940J	Date of Loss:	20/01/2020 00:00 - :59 [50 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1202000003363	Policy/Cover Note No.:	PNPV2018-00012996-01 (Comprehensive) Coverage: 14/10/2019 - 13/10/2020
Vehicle Reg. No. (Insured):	SLG8254C	Policy No. (Claimant):	
		Excess:	
Repairer:	Hc Auto Pte Ltd (HQ) BLOCK 20 SECTOR A SIN MING IND. EST. #01-20, 575678 Sin Ming - Tel:		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 31/01/2020]		

[View All](#)[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKW4940J (1202000003363)
[SLG8254C]

TP

TOMMIE LIM WEE HIANG (TOMMIE LIN WEIXIAN)

Jan 20 2020 12:00AM

[Tan Chin Guan]

Hc Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

1 per page

☒

Assessment Reports			Thumbnail	Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
1	28/01/20 14:21	Adjuster Immediate Advice	Load HTM	<input checked="" type="checkbox"/>

3 per page

☒

Photos/Images			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	24/02/20 12:03	General View	Load JPG	<input checked="" type="checkbox"/>
2	24/02/20 12:03	General View	Load JPG	<input checked="" type="checkbox"/>
3	24/02/20 12:03	General View	Load JPG	<input checked="" type="checkbox"/>
4	24/02/20 12:03	General View	Load JPG	<input checked="" type="checkbox"/>
5	24/02/20 12:03	General View	Load JPG	<input checked="" type="checkbox"/>
6	24/02/20 12:03	General View	Load JPG	<input checked="" type="checkbox"/>
7	24/02/20 12:03	General View	Load JPG	<input checked="" type="checkbox"/>
8	24/02/20 12:03	General View	Load JPG	<input checked="" type="checkbox"/>
9	24/02/20 12:03	General View	Load JPG	<input checked="" type="checkbox"/>
10	24/02/20 12:03	General View	Load JPG	<input checked="" type="checkbox"/>
11	24/02/20 12:03	General View	Load JPG	<input checked="" type="checkbox"/>
12	24/02/20 12:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
13	24/02/20 12:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
14	24/02/20 12:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
15	24/02/20 12:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
16	24/02/20 12:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
17	24/02/20 12:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
18	24/02/20 12:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
19	24/02/20 12:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD20001242/KTF3S2
Date: 25/02/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00012996-01
 Claimant Vehicle No: SKW4940J Insured Vehicle No: SLG8254C
 Date of Loss: 20/01/2020 Nature of Claim: TP Claim No: 1202000003363

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW4940J Engine No: L15B4024263
 Make & Model: HONDA VEZEL, 1.5 (A) Chassis No: RU11104260
 Reg. Date: 30/10/2015 (Man. Year: 2015) Odometer: 122268 km
 Colour: Metallic Silver
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Goodyear 8 mm Rear Left Side: Goodyear 8 mm
 Front Right Side: Goodyear 8 mm Rear Right Side: Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,750.92	2,151.52	5,599.40	72.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,350.00	1,235.00	3,115.00	71.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,100.92	3,386.52	8,714.40	72.01
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	12,100.92	2,700.00	9,400.92	77.69
+ GST 7.00/7.00% (S\$)	847.06	189.00	658.06	77.69
Nett Amount (S\$)	12,947.98	2,889.00	10,058.98	77.69

INSPECTION

Date of Assignment: 21/01/2020
 Date Inspected: 21/01/2020 Inspected At: HC Auto Pte Ltd
 160 SIN MING DRIVE
 #05-09 SIN MING AUTOCITY
 SINGAPORE 575722
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

Adjuster Report

2/25/2020

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Feb 2020)	
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SKW4940J)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,450.00 FL	*1,122.60 FL
2	1		*TAIL GATE WEATHER STRIP	Serviceable	185.00 FL	*- FL
3	1		*TAIL GATE INNER LOCK	Repair	310.00 FL	*- FL
4	2		*TAIL GATE HINGE	Repair	110.00 FL	*- FL
5	2		*TAIL GATE REFLECTOR	Serviceable	700.00 FL	*- FL
6	1		*TAIL GATE INNER TRIM	Serviceable	325.00 FL	*- FL
7	1		*TAIL GATE HONDA LOGO	Not Necessary	27.65 FL	*- FL
8	1		*TAIL GATE VEZEL EMBLEM	Necessary	55.00 FL	*55.00 FL
9	1		*REAR END PANEL	Repair	620.00 FL	*- FL
10	1		*REAR END PANEL INNER GARNISH	Mtg Distorted	216.00 FL	*184.00 FL
11	1		*REAR BUMPER FASCIA	Buckled	1,120.00 FL	*745.30 FL
12	2		*REAR BUMPER SIDE	Serviceable	470.00 FL	*- FL
13	2		*REAR BUMPER BRACKET	Repair	70.00 FL	*- FL
14	2		*REAR BUMPER SIDE RETAINER	Serviceable	64.00 FL	*- FL
15	2		*REAR BUMPER REFLECTOR	Serviceable	321.00 FL	*- FL
16	1		*REAR BUMPER BUZZER	Cracked	95.00 FL	*95.00 FL
17	2		*TAIL LAMPS	Serviceable	1,300.00 FL	*- FL
18	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	150.00 FL	*150.00 FL
19	1		*REAR EXHAUST PIPE	Repair	650.00 FL	*- FL
20	2		*REAR EXHAUST BOX ALUMINIUM COVER	Repair	145.00 FL	*- FL
21	1		*REAR SPARE TYRE BOARD	Serviceable	280.00 FL	*- FL
22	1		*REAR NO. PLATE	Serviceable	100.00 FS	*- FS
23	1		*REAR PANEL INNER SEAL	Not Necessary	250.00 FS	*- FS
24	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
25	1		*REAR WINDSCREEN INNER GUM	Necessary	60.00 FS	*40.00 FS
26	1		*SET REVERSE SENSOR	Dented	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,483.65	2,621.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,732.73	470.38
Total Parts (\$\$)	7,750.92	2,151.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES.	New	1,800.00	500.00
2	TO PUTTY AND SPRAY PAINTING.	New	1,600.00	400.00
3	TO CHECK WIRING.	New	120.00	15.00
4	TO TRANSFER TAIL GATE.	New	120.00	60.00
5	REMOVE AND REFIX REAR WINDSCREEN GLASS.	New	160.00	120.00
6	REFIX REVERSE SENSOR.	New	100.00	50.00
7	REMOVE AND REFIX CUSHION SEAT, GARNISH, CARPET & ETC.	New	180.00	60.00
8	REMOVE AND REFIX EXHAUST BOX.	New	120.00	0.00
9	TO RE-SEAL ANTI RUST.	New	150.00	30.00
Gross Labour Cost (\$\$)			4,350.00	1,235.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >