

AUTOCLINIC PTE LTD

48 TOH GUAN ROAD EAST #02-136 Enterprise Hub Singapore 608586
TEL: 6686 2511 FAX: 6686 2509 Email: info@autoclinicgroup.com.sg
GST:201801145H RCB NO:201801145H

M/S : BUDDY TRANS SERVICES
12 JALAN BUKIT MERAH #03-5044

SINGAPORE 150012
TEL: 96268559
ATTN: Motor Claim Department

Your Ref No: -
Claim Type:
Accident Date: 04/09/2019

Estimate No: QUO1800014
Date: 19 Sep 2019
Policy No:
Veh Reg No: SLR7380U
Make/Model: TOYOTA COROLLA
AXIO 1.5X A
Chassis No: NRE1610020262
Engine No: 2NR8655546
Reg. Date: 25/08/2017

Estimate Repair Cost to Vehicle No : SLR7380U

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Others				
1 BOOT LID	0.00	1PC	685.80	
2 BOOT LID 'COROLLA' EMBLEM	0.00	1PC	39.20	
3 BOOT LID 'AXIO' EMBLEM	0.00	1PC	44.20	
4 BOOT LID LOGO	0.00	1PC	52.70	
5 BOOT LID OUTER CHROME	0.00	1PC	298.10	
6 TAIL LAMP	0.00	1PC	318.65	
7 TAIL LAMP SIDE CLIP	0.00	2PC	4.20	
8 REAR END PANEL	0.00	1PC	602.10	
9 REAR BUMPER FASCI	0.00	1PC	559.70	
10 REAR BUMPER N/S SIDE RETAINER S	0.00	1PC	42.90	
11 REAR BUMPER N/S SIDE RETAINER L	0.00	1PC	50.85	
12 LESS 25% DISCOUNT FOR ITEM #1 TO #12	0.00	1PC	-674.60	
13 REAR BUMPER REVERSE SENSOR SET	0.00	1PC	200.00	
14 REAR NUMBER PLATE WITH BOX	0.00	1PC	50.00	
15 TO REMOVE ROOF LINING, FRONT AND REAR SEATS, TRIM BOARD AND CARPET	0.00	1PC	60.00	
16 TO APPLY UNDERSEALING	0.00	1PC	60.00	
17 TO PUTTY AND SPRAY REPLACED PARTS	0.00	1PC	600.00	
18 TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS	0.00	1PC	600.00	
				3,598.00

Total S\$ 3,598.00

Add GST @ 7% 251.86

Total Amount payable S\$ 3,849.86

TOTAL: SINGAPORE DOLLAR THREE THOUSAND EIGHT HUNDRED FORTY NINE AND CENTS EIGHTY SIX ONLY

For AUTOCLINIC PTE LTD



AUTHORISED SIGNATURE