



AUTOCLINIC PTE LTD

48 TOH GUAN ROAD EAST #02-136 Enterprise Hub Singapore 608586
TEL: 6686 2511 FAX: 6686 2509 Email: info@autoclinicgroup.com.sg
GST: 201801145H RCB NO: 201801145H

M/S : BUDDY TRANS SERVICES
12 JALAN BUKIT MERAH #03-5044

SINGAPORE 150012
TEL: 96268559
ATTN: Motor Claim Department

Your Ref No: -
Claim Type:
Accident Date: 04/09/2019

Estimate No: QUO1800014
Date: 19 Sep 2019
Policy No:
Veh Reg No: SLR7380U
Make/Model: TOYOTA COROLLA
AXIO 1.5X A
Chassis No: NRE1610020262
Engine No: 2NR8655546
Reg. Date: 25/08/2017

Estimate Repair Cost to Vehicle No : SLR7380U

Description	U/Price	Quantity	Cost	Amount
			SS	SS
Others				
1 BOOT LID	0.00	1PC	685.80	✓
2 BOOT LID INNER LOCK	0.00	1PC	94.30	X
3 BOOT LID RUBBER	0.00	1PC	189.30	X
4 BOOT LID 'COROLLA' EMBLEM	0.00	1PC	39.20	—
5 BOOT LID 'AXIO' EMBLEM	0.00	1PC	44.20	—
6 BOOT LID LOGO	0.00	1PC	52.70	—
7 BOOT LID OUTER CHROME	0.00	1PC	298.10	—
8 TAIL LAMP	0.00	2PC	637.30	✓ + 318.65
9 TAIL LAMP SIDE CLIP	0.00	2PC	4.20	✓
10 TAIL LAMP CORNER PANEL	0.00	2PC	159.20	X
11 REAR END PANEL	0.00	1PC	602.10	X
12 REAR END PANEL TOP GARNISH	0.00	1PC	218.60	X
13 REAR SPARE TYRE BOARD	0.00	1PC	390.70	X
14 REAR SPARE TYRE PANEL	0.00	1PC	687.80	X
15 REAR BUMPER FASCIA	0.00	1PC	559.70	✓
16 REAR BUMPER SIDE RETAINER S	0.00	2PC	85.80	✓ + 42.90
17 REAR BUMPER SIDE RETAINER L	0.00	2PC	101.70	✓ + 50.85
18 REAR BUMPER BRACKET	0.00	2PC	92.80	X
19 REAR BUMPER REVERSE SENSOR SET	0.00	1PC	300.00	2000
20 REAR NUMBER PLATE WITH BOX	0.00	1PC	50.00	X
21 TO REMOVE ROOF LINING, FRONT AND REAR SEATS, TRIM BOARD AND CARPET	0.00	1PC	80.00	601
22 TO APPLY UNDERSEALING	0.00	1PC	100.00	601
23 TO PUTTY AND SPRAY REPLACED PARTS	0.00	1PC	900.00	600h
24 TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS	0.00	1PC	1,000.00	600h
				8,454.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7373.50

**AUTOCLINIC PTE LTD**

48 TOH GUAN ROAD EAST #02-136 Enterprise Hub Singapore 608586
TEL: 6686 2511 FAX: 6686 2509 Email: info@autoclinicgroup.com.sg
GST:201801145H RCR NO:201801145H

M/S : BUDDY TRANS SERVICES
12 JALAN BUKIT MERAH #03-5044

SINGAPORE 150012

TEL: 96268559

ATTN: Motor Claim Department

Your Ref No: -

Claim Type:

Accident Date: 04/09/2019

Estimate No: QUO1800014

Date: 19 Sep 2019

Policy No:

Veh Reg No: SLR7380U

**Make/Model: TOYOTA COROLLA
AXIO 1.5X A**

Chassis No: NRE1610020262

Engine No: 2NR8655546

Reg. Date: 25/08/2017

Estimate Repair Cost to Vehicle No : SLR7380U

Total	S\$ 8,454.50
Lump Sum Less 25%	-2,113.63
Total Amount payable	S\$ 6,340.87
Include GST @ 7% For 5,926.05 = \$414.82	

TOTAL: SINGAPORE DOLLAR SIX THOUSAND THREE HUNDRED FORTY AND CENTS EIGHTY SEVEN ONLY

For AUTOCLINIC PTE LTD



AUTHORISED SIGNATURE