

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 25938

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0071/2020/NS
Date : 17-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : M/S Pinn Brokerage Pte Ltd
Address : 6 Peach Garden
#03-08
Singapore 437606
Telephone : HP +65 90190914
Type of Claim : Own Damage Claims
Policy No. : 1700083195-02v1
Vehicle No : **SKA 9788 R**
Model Code : Audi Q7 2.0 TFSI QU
Model / Year : Dec-17
Engine No : CYR 046187
Chassis No : WAUZZZ4M3JD002167
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Jan-20
Place of Accident : Overhead Bridge Of Newton Circus (To Bukit Timah)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKA 9788 R

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, front bumper spoiler and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,250.00 600	
3	To respray front bumper, front bumper spoiler, lhs front fender and both front wheel arch trims.	\$ 4,000.00 1000	Bumper 600 Wheel Arc x 02 = 400
4	To carry out diagnostic check.	\$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 6,922.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKA 9788 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Del'd</i>	\$ 2,317.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 420.00	✗
3	FRONT BUMPER AIR GUIDE - LH <i>new</i>	\$ 63.00	✗
4	FRONT BUMPER END CAP - LH <i>new</i>	\$ 34.00	✗
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>new</i>	\$ 261.00	✗
6	FRONT BUMPER GRILLE - LOWER CENTRE <i>Del'd.</i>	\$ 194.00	✓
7	FRONT BUMPER UNDERRUN BAR <i>Del'd</i>	\$ 759.00	✓
8	FRONT BUMPER CLOSING ELEMENT <i>new</i>	\$ 198.00	✗
9	FRONT SPOILER - LH <i>Rept</i>	\$ 199.00	✗
10	FRONT BUMPER SPOILER - LH OUTER <i>Rept</i>	\$ 41.00	✗
11	RADIATOR GRILLE <i>Crash'd</i>	\$ 2,327.00	✓
12	RADIATOR GRILLE COVER ?	\$ 65.00	?
13	RADIATOR GRILLE INNER COVER ?	\$ 58.00	?
14	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Missing</i>	\$ 280.00	✓
15	FRONT BUMPER END CAP - LH ?	\$ 31.00	?
16	FRONT DEFLECTOR - LH INNER ?	\$ 56.00	?
17	FRONT BUMPER FOSM FILLER PIECE <i>new</i> ?	\$ 161.00	✗ ?
18	FRONT BUMPER CARRIER <i>new</i> ?	\$ 817.00	✗ ?
19	FRONT BUMPER SUPPORT - LH / RH <i>new</i>	2 \$ 68.00	✗
20	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	\$ 41.00	✗
SUB TOTAL SPARE PARTS CHARGES		: \$ 8,390.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKA 9788 R

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
21	SIGHT SHIELD	\$	123.00	+
22	CAUTION SIGN STICKER	NEC \$	13.00	+
23	HORN BRACKET - LH LOW TONE	\$	213.00	+
24	FRONT PARKING AID SENSOR - INNER / OUTER	3	TBC	+
25	FRONT PARKING AID SEAL RING	4	\$ 14.00	+
26	HEADLIGHT MOUNTING - LH	\$	112.00	+
27	LED HEADLIGHT - LH	\$	9,356.00	+
28	LIFT CYLINDER - LH / RH	2	\$ 374.00	+
29	HEADLIGHT HOSE	\$	92.00	X
30	RADIATOR AIR GUIDE - LH OUTER	\$	43.00	+
31	ADDITIONAL RADIATOR BRACKET	\$	123.00	+
32	RADIATOR AIR GUIDE - LH / RH	2	\$ 54.00	+
33	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 80.00	+
34	FRONT WHEEL COVER - LH / RH	2	\$ 1,080.00	✓
35	FRONT NO PLATE	S/N \$	40.00	✓
36	SUNDRIES	\$	400.00	?

TOTAL SPARE PARTS CHARGES	:	\$ 20,507.00
TOTAL LABOUR CHARGES	:	\$ 6,922.00
GRAND TOTAL	:	\$ 27,429.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lj*
Surveyed Date : *21/01/20.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *not authorised, 03 days.*

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant