

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP :27179

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0078/2020/NS
Date : 20-Jan-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Choo Weng Tang Keith
Address : 7 Jalan Manis
Singapore 329242
HP +65 93667536
Telephone : Own Damage Claims
Type of Claim : 1900260525
Policy No. : **SMR 2173 Y**
Vehicle No : Audi A4 Sedan 2.0 TFSI S TRONIC
Model Code : Dec-19
Model / Year : CVK 086728
Engine No : WAUZZZF40KA108608
Chassis No : -
Mileage : -
Date In : Johnny Boo / Allan Wu
Estimated By : 18-Jan-20
Accident Date : Gantry Of Link At Ang Mo Kio
Place of Accident :

Premium Automobiles

Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMR 2173 Y

<u>S/N Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1 To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2 To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00 500	
3 To respray front bumper.	\$ 900.00 550	
4 To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES	: \$ <u>2,622.00</u>	

Telefax

Material List for Accident Vehicle Regn No. SMR 2173 Y

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Repis</i>	\$ 2,068.00	✓
2	FRONT BUMPER FIXING PARTS	\$ 553.00	+
3	FRONT BUMPER GRILLE - CENTRE <i>3 new</i>	\$ 185.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 198.00	+
5	RADIATOR GRILLE <i>Culed.</i>	\$ 1,254.00	✓ 1003.20
6	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	\$ 127.00	+
7	FRONT BUMPER CARRIER <i>3 new</i>	\$ 757.00	+
8	FRONT BUMPER FOAM FILLER PIECE	\$ 117.00	+
9	FRONT BUMPER COVER	\$ 120.00	+
10	CAUTION SIGN STICKER <i>3 new</i>	NEC \$ 13.00	+
11	AIRCON STICKER	NEC \$ 7.00	+
12	LOCK CARRIER BRACKET - LH <i>3 new</i>	\$ 129.00	+
13	FRONT BUMPER SIPPORIT - LH / RH	\$ 54.00	+
14	FRONT PARKING AID SENSOR - INNER / OUTER <i>3 new</i>	2 \$ TBC	+
15	FRONT PARKING AID SEAL RING	2 \$ 14.00	+
16	HORN - LH HIGH TONE	4 \$ 38.00	+
17	RADIATOR AIR GUIDE - LH	\$ 27.00	+
18	RADIATOR INNER DUCT - LH <i>2</i>	\$ 12.00	+
19	RADIATOR AIR GUIDE - UPPER <i>new</i>	\$ 15.00	+
20	RADIATOR AIR GUIDE - LOWER	\$ 21.00	+
21	FRONT NO PLATE <i>Best</i>	S/N \$ 40.00	✓
22	SUNDRIES <i>Not new.</i>	\$ 200.00	? X
		\$ 5,949.00	
		\$ 2,622.00	
		\$ 8,571.00	

TOTAL SPARE PARTS CHARGES
TOTAL LABOUR CHARGES
GRAND TOTAL

All charges are not inclusive of GST.
 Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adam L
: 21/01/21
:
:
:
:
: Not Authorised, 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant