

801\*7+  
30\*+  
27\*1+  
1,820\*9+  
589\*+  
193\*+  
350\*1+  
390\*7+  
161\*9+  
430\*1+  
794\*5+  
1,080\*5+  
=

8,669\*50\*

8,669\*50x

80\*%

5,335\*60\*

400\*+

1,200\*+

1,610\*+

80\*+

220\*+

80\*+

30\*+

600\*+

600\*+

1,610\*+

5,335\*6+

1,600\*+

1,610\*+

8,545\*60\*

8,545\*60x

80\*%

8,836\*48\*

# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM\_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

ALG

ROLINE

ve 6

20/01/2020

TP ALG  
khunchoa.

01/2020

ost for vehicle no: SLR3315K HONDA VEZEL 1.5 X A '17

S: RU11115721

|    |                                             | U/price | Amount     |      |
|----|---------------------------------------------|---------|------------|------|
|    | Imper <i>del</i>                            |         | \$801.70   | ✓    |
|    | Imper Clip <i>new</i>                       | \$6.50  | \$65.00    | ✓    |
|    | Imper Lower <i>new</i>                      |         | \$351.00   | ✓    |
|    | 'H Bumper Side Retainer <i>new</i>          |         | \$27.10    | ✓    |
|    | 'H Bumper Fog Lamp <i>new</i>               |         | \$327.70   | +    |
|    | 'H Bumper Fog Lamp Cover <i>new</i>         |         | \$45.00    | +    |
|    | 'H Head Lamp <i>2mled</i>                   |         | \$1,820.90 | ✓    |
|    | 'H Head Lamp Lower Bracket <i>2mled new</i> |         | \$65.00    | +    |
|    | 'H Fender <i>Dented</i>                     |         | \$589.00   | ✓    |
|    | 'H Fender Arch Protector <i>new</i>         |         | \$193.00   | ✓    |
|    | ille Outer <i>2</i>                         |         | \$386.00   | +    |
|    | ille Inner <i>new</i>                       |         | \$351.80   | +    |
|    | ille Emblem Logo <i>new</i>                 |         | \$34.70    | +    |
|    | ille Clip                                   | \$6.50  | \$52.00    | +    |
| 14 | 1 Front R/H Rim <i>cut</i>                  |         | \$850.00   | 4000 |
| 15 | 1 Front R/H Tyre <i>new</i>                 |         | \$450.00   | +    |
| 16 | 1 Front R/H Lower Arm <i>Bent</i>           |         | \$350.10   | 4    |
| 17 | 1 Front R/H Knuckle Arm <i>Damaged</i>      |         | \$390.70   | +    |
| 18 | 1 Front R/H Knuckle Arm Bearing <i>new</i>  |         | \$161.90   | 4    |
| 19 | 1 Front R/H Shock Absorber <i>Bent</i>      |         | \$430.10   | +    |
| 20 | 1 Front R/H Drive Shaft <i>new</i>          |         | \$1,019.20 | +    |
| 21 | 1 Front Steering Rack <i>new</i>            |         | \$1,801.70 | +    |
| 22 | 1 Front R/H Side Mirror Assy <i>cut</i>     |         | \$794.50   | +    |
| 23 | 1 Front R/H Door <i>Dented</i>              |         | \$1,080.50 | +    |

L/S = \$6800