

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

20/01/2020

NG KAH HWEE CAROLINE

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Alh.
khunchua.

Accident date: 17/01/2020

Estimated repair cost for vehicle no: SLR3315K HONDA VEZEL 1.5 X A '17

CHASSIS: RU11115721

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper <i>Delid</i>		\$801.70 ✓
2	10	Front Bumper Clip <i>neu</i>	\$6.50	\$65.00 <i>30</i>
3	1	Front Bumper Lower <i>neu</i>		\$351.00 <i>+</i>
4	1	Front R/H Bumper Side Retainer <i>neu</i>		\$27.10 ✓
5	1	Front R/H Bumper Fog Lamp <i>neu</i>		\$327.70 <i>+</i>
6	1	Front R/H Bumper Fog Lamp Cover <i>neu</i>		\$45.00 <i>+</i>
7	1	Front R/H Head Lamp <i>Emiled</i>		\$1,820.90 ✓
8	1	Front R/H Head Lamp Lower Bracket <i>Not neu</i>		\$65.00 <i>+</i>
9	1	Front R/H Fender <i>Dented</i>		\$589.00 ✓
10	1	Front R/H Fender Arch Protector		\$193.00 ✓
11	1	Front Grille Outer <i>2</i>		\$386.00 <i>+</i>
12	1	Front Grille Inner <i>neu</i>		\$351.80 <i>+</i>
13	1	Front Grille Emblem Logo <i>neu</i>		\$34.70 <i>+</i>
14	8	Front Grille Clip	\$6.50	\$52.00 <i>+</i>
15	1	Front R/H Rim <i>cut</i>		\$850.00 <i>400/60</i>
16	1	Front R/H Tyre <i>neu</i>		\$450.00 <i>+</i>
17	1	Front R/H Lower Arm <i>Bent</i>		\$350.10 <i>+</i>
18	1	Front R/H Knuckle Arm <i>Dang</i>		\$390.70 <i>+</i>
19	1	Front R/H Knuckle Arm Bearing <i>neu</i>		\$161.90 <i>+</i>
20	1	Front R/H Shock Absorber <i>Bent</i>		\$430.10 <i>+</i>
21	1	Front R/H Drive Shaft <i>neu</i>		\$1,019.20 <i>+</i>
22	1	Front Steering Rack <i>neu</i>		\$1,801.70 <i>+</i>
23	1	Front R/H Side Mirror Assy <i>cut</i>		\$794.50 <i>+</i>
24	1	Front R/H Door <i>Dented</i>		\$1,080.50 <i>+</i>

25	2	Front R/H Door Hinge <i>New</i>	\$45.80	\$91.60	*
26	1	Front R/H Door Inner Lock <i>New</i>		\$262.20	+
27	1	Front R/H Door Weatherstrip <i>New</i>		\$195.80	+
28	1	Front R/H Door Inner Trim Board <i>New</i>		\$650.70	+
29	10	Front R/H Door Inner Trim Board Clip <i>New</i>	\$6.50	\$65.00	+
30	1	Front R/H Door Window Motor & Regulator Assy <i>New</i>		\$382.90	+
* 31	1 set	Car Vinyl Wrap <i>New</i>		\$2,400.00 200 (SW)	

6669.50 S.N: 1600
533560

Subtotal :- \$16,486.80

Labour charges

To remove & refit front R/H door, glass, lock, weatherstrip, trim board, frame sticker & windown motor regulator assy

~~\$280.00~~ 80

To remove & refit front L/H undercarriage, drive shaft & steering rack

~~\$380.00~~ 220

To check wheel alignment

~~\$150.00~~ 80

To check wiring

~~\$100.00~~ 30

Tuff kote

\$150.00 *

Towing fee

1610 \$150.00 *

Panel beating

~~\$1,400.00~~ 600

Spray painting

~~\$1,400.00~~ 600

Subtotal :- \$4,010.00

Total:- \$20,496.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
H/S 20/01/20
06 days

total. 8545.60

H/S 68K.

68K