

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20001273/KGA3Q2

Date: 03/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLP402Y	Insured Vehicle No :	SHA7335M
Date of Loss: 19/01/2020	Nature of Claim:	TP Claim No: MCT20010443

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP402Y		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZRS049586
Reg. Date:	25/05/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU103559179
Colour:	Metallic Silver	Odometer:	222980 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,576.90	1,749.86	4,827.04	73.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,710.00	1,300.00	1,410.00	52.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,286.90	3,049.86	6,237.04	67.16
+ GST 7.00/7.00% (S\$)	650.08	213.49	436.59	67.16
Nett Amount (S\$)	9,936.98	3,263.35	6,673.63	67.16
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
		(S\$)	3,743.35	
Liabile Amount (50.00%) (S\$)		1,871.68		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,879.13		

INSPECTION

Date of Assignment:	21/01/2020	
Date Inspected:	21/01/2020 Inspected At:	Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259 Singapore 569536
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2020)
Parts: 144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP402Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT DOOR	Bent	1,121.75 FL	*1,121.75 FL
2	1		*LH FRONT DOOR HINGE TOP	Repair	78.30 FL	*- FL
3	1		*LH FRONT DOOR HINGE BOTTOM	Repair	78.30 FL	*- FL
4	1		*LH FRONT DOOR LOCK	Repair	470.33 FL	*- FL
5	1		*LH FRONT DOOR CATCH	Serviceable	43.95 FL	*- FL
6	1		*LH FRONT DOOR CHECKER	Serviceable	130.70 FL	*- FL
7	1		*LH FRONT DOOR WEATHERSTRIP	Serviceable	211.69 FL	*- FL
8	1		*LHF DOOR GLASS OUTER MOULDING	Serviceable	121.75 FL	*- FL
9	1		*LHF DOOR TRIM	Serviceable	866.70 FL	*- FL
10	1		*LHF POWER WINDOW MOTOR	Serviceable	661.98 FL	*- FL
11	1		*LHF POWER WINDOW REGULATOR	Serviceable	207.90 FL	*- FL
12	1		*LH REAR DOOR	Bent	1,211.40 FL	*1,211.40 FL
13	1		*LH REAR DOOR HINGE TOP	Repair	78.34 FL	*- FL
14	1		*LH REAR DOOR HINGE BOTTOM	Repair	78.34 FL	*- FL
15	1		*LH REAR DOOR LOCK	Repair	425.63 FL	*- FL
16	1		*LH REAR DOOR CATCH	Repair	37.80 FL	*- FL
17	1		*LH REAR DOOR CHECKER	Serviceable	126.70 FL	*- FL
18	1		*LH REAR DOOR WEATHERSTRIP	Serviceable	212.47 FL	*- FL
19	1		*LH REAR DOOR TRIM	Serviceable	856.90 FL	*- FL
20	1		*LHR DOOR GLASS OUTER MOULDING	Serviceable	107.80 FL	*- FL
21	1		*LHR POWER WINDOW MOTOR	Serviceable	671.48 FL	*- FL
22	1		*LHR POWER WINDOW REGULATOR	Serviceable	202.49 FL	*- FL
23	1		*LH SIDE SKIRT	Repair	721.50 FL	*- FL
24	10		*LH SIDE SKIRT CLIP	Not Necessary	45.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	8,769.20	2,333.15
- List Item Discount on L Items 25.00/25.00% (S\$)	2,192.30	583.29

Total Parts (S\$)	6,576.90	1,749.86
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNEEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (LHF DOOR ,LHR DOOR ,LHS SKIRT)	New	800.00	500.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (LHF DOOR ,LHR DOOR ,LHS SKIRT)	New	800.00	600.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE & REFIT DOOR TRIM ,DOOR GLASS ,WINDOW REGULATOR,DOOR LOCK TO ASSIST WORK LOAD }	New	300.00	120.00
5	TO REMOVE & REFIT LHF DOOR GLASS & LHR DOOR GLASS }	New	240.00	0.00
6	TO DO WHEEL ALIGNMENT	New	120.00	0.00
7	TO REMOVE & REFIT INNER SEAT & UPHOLSTERY TO ASSIT WORK LOAD	New	250.00	0.00
8	TO TUFF COAT	New	150.00	60.00
Gross Labour Cost (\$)			2,710.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >