

ndai - LKK



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Repair Estimates

SLP 402 Y

Not Authorized  
Resurvey B&Paint

Parts	(a) Cost / List Price Items	\$	<u>8,769.20</u>
	Plus/Less 25%	\$	<u>2,192.30</u>
	<b>Total of Cost / List</b>	\$	<u><u>6,576.90</u></u>
	(b) Nett Price Items		_____
	Less		_____
	<b>Total of Nett Item</b>		_____
	(c) Special Nett Items		_____
<b>Total Parts Cost</b>		\$	<u><u>6,576.90</u></u>
<b>Labour</b>		\$	<u><u>2,710.00</u></u>
<b>Total</b>		\$	<u><u>9,286.90</u></u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 21/1/20 at \_\_\_\_\_

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Le Date: 21/1/20



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

## Spare Parts

Vehicle No. :  
 Make & Model :  
 Chassis No. :

**SLP 402 Y**

TOYOTA PRIUS  
 JTDKB3FU103559179

Submit By :  
 Year Manufacture :  
 Engine No. :  
**Cost / List**

JENNY

2017

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front door	1	\$1,121.75		✓
2	LH front door hinge top	1	\$78.30		X
3	LH front door hinge bottom	1	\$78.30		X
4	LH front door lock	1	\$470.33		✓
5	LH front door catch	1	\$43.95		X
6	LH front door checker	1	\$130.70		X
7	LH front door weatherstip	1	\$211.69		X
8	LHF door glass outer moulding	SVC 1	\$121.75		X
9	LHF door trim	1	\$866.70		X
10	LHF power window motor	SVC 1	\$661.98		X
11	LHF power window regulator	SVC 1	\$207.90		X
12	LH rear door	1	\$1,211.40		✓
13	LH rear door hinge top	1	\$78.34		X
14	LH rear door hinge bottom	1	\$78.34		X
15	LH rear door lock	1	\$425.63		X
16	LH rear door catch	1	\$37.80		X
17	LH rear door checker	1	\$126.70		X
18	LH rear door weatherstip	1	\$212.47		X
19	LH rear door trim	1	\$856.90		X
20	LHR door glass outer moulding	1	\$107.80		X
21	LHR power window motor	SVC 1	\$671.48		X
22	LHR power window regulator	SVC 1	\$202.49		X
23	LH side skirt	R 1	\$721.50		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. : SLP 402 Y  
Make & Model : TOYOTA PRIUS  
Chassis No : JTDKB3FU103559179

Submit By : Carmen Lim  
Year Manufacture : 2017  
Engine No. : \_\_\_\_\_

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	LH side skirt clip NN	10	\$45.00		X
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

*Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.*



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : SLP 402 Y Submit By : Carmen Lim  
 Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (LHF DOOR,LHR DOOR,LHS SKIRT)	\$800.00	500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (LHF DOOR,LHR DOOR,LHS SKIRT)	\$800.00	600
3	To check Wiring	\$50.00	20
4	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$300.00	} 4 120
5	To remove & refit LHF door glass & LHR door glass	\$240.00	
6	To do wheel alignment	rr \$120.00	X
7	To remove & refit inner seat & upholstery to assist work load.	Not \$250.00	X
8	To tuff coat.	\$150.00	60/-

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.