

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6 #02-06 Autobay @ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST: 201300201N

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING, SINGAPORE 079120
 TEL: 64193000 FAX: 68357416
 ATTN: Motor Claim Department

Estimate No: EST2000022
Date: 21 Jan 2020
Veh Reg No: SLF8153R
Make/Model: TOYOTA WISH 1.8 CVT
Chasis No: JTDGG20W00J004876
Reg. Date: 13/09/2016
Your Ref No: SFD62D

Claim Type: Third Party
Accident Date: 18/01/2020
TP Veh Reg No: SFD62D

Asher.

Estimate Repair Cost to Vehicle No :SLF8153R

Quantity	Description	List Price SS	Amount SS
	List Price		
1	1 PC BONNET <i>Dented</i>	798.80	698.80
2	1 PC BONNET LOGO <i>Neu</i>	66.20	✓
3	2 PCS BONNET HINGE <i>Best</i>	163.40	✓
4	1 PC BONNET RUBBER <i>Neu</i>	38.80	+
5	1 PC BONNET TRIM <i>Neu</i>	390.50	+
6	4 PCS BONNET STOPPER MOUNTING <i>Neu</i>	80.00	+
7	1 PC BONNET LOCK <i>Dented</i>	164.60	✓
8	1 PC FRT BRACE PANEL <i>Neu Best</i>	81.10	✓
9	1 PC FRT SUPPORT PANEL <i>Buckled</i>	1,179.50	1092
10	1 PC FRT SUPPORT PANEL TRIM <i>Dented</i>	81.60	✓
11	1 PC FRT FENDER LH <i>Dented</i>	775.90	✓
12	1 PC FRT FENDER COWLING LH <i>horn</i>	150.70	✓
13	1 PC FRT FENDER RH <i>Buckled</i>	775.90	✓
14	1 PC FRT FENDER COWLING RH <i>Neu</i>	150.70	+
15	1 PC HEADLAMP LH <i>smashed</i>	1,285.70	✓
16	1 PC HEADLAMP RH <i>could</i>	1,285.70	✓
17	1 PC FRT LH RELAY <i>Neu</i>	168.60	✓
18	1 PC FRT GRILLE <i>could</i>	548.30	✓
19	1 PC HORN <i>Also Dented</i>	98.60	✓
20	1 PC FRT BUMPER <i>Distorted</i>	594.90	✓
21	1 PC FRT BUMPER REINFORCEMENT <i>Best</i>	275.20	✓
22	1 PC FRT BUMPER SPONGE <i>could</i>	81.10	✓
23	2 PCS FRT BUMPER SIDE RETAINER <i>Neu</i>	110.60	✓
24	1 PC AIR CONDENSER <i>Dented</i>	1,404.30	✓
25	2 PCS AIR CONDENSER SIDE GARNISH <i>Neu Dented</i>	123.00	✓
26	1 PC RADIATOR <i>Dented</i>	1,806.70	1682.70
27	2 PCS RADIATOR BRACKET <i>Neu</i>	70.40	+
28	1 PC RADIATOR TOP GARNISH <i>Neu</i>	169.90	+
29	1 PC RADIATOR SPARE TANK <i>could</i>	155.70	✓
30	1 PC RADIATOR FAN <i>Neu</i>	213.80	+

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST 201300201N

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING, SINGAPORE 079120
 TEL: 64193000 FAX: 68357416
 ATTN: Motor Claim Department

Estimate No: **EST2000022**
 Date: 21 Jan 2020
 Veh Reg No: **SLF8153R**
 Make/Model: TOYOTA WISH 1.8 CVT
 Chasis No: JTDGG20W00J004876
 Reg. Date: 13/09/2016
 Your Ref No: SFD62D

Claim Type: Third Party
 Accident Date: 18/01/2020
 TP Veh Reg No: SFD62D

Estimate Repair Cost to Vehicle No :SLF8153R

Quantity	Description	List Price	Amount
		SS	SS
31	1 PC RADIATOR FAN MOTOR <i>new</i>	496.80	+
32	1 PC AIRCON CONDENSER FAN <i>new</i>	213.80	+
33	1 PC AIR CONDENSER FAN MOTOR <i>new</i>	496.80	+
34	1 PC FRT FAN COWLING <i>could</i>	200.70	✓
35	1 PC RADIATOR UNDER COVER <i>from</i>	237.20	✓
36	1 PC AIR CLEANER ASSY <i>new</i>	887.60	+
37	1 PC AIR CLEANER U HOSE <i>new cut</i>	128.10	+
38	1 PC AIR CLEANER OUTER HOSE <i>new cut</i>	63.20	+
39	1 PC FRT FUSE BOX ASSEMBLY <i>could</i>	390.80	✓
40	1 PC FRT WIPER PANEL GARNISH <i>at</i>	583.20	-
41	1 PC FRT WINDSCREEN GLASS LH CORNER GARNISH <i>new</i>	36.30	+
42	1 PC FRT SHOCK ABSORBER LH	401.30	+
43	1 PC FRT SHOCK ABSORBER MOUNTING LH <i>new</i>	185.40	+
44	1 PC FRT KNUCKLE ARM LH	437.20	+
45	1 PC FRT WHEEL LH BEARING	119.40	+
46	1 PC FRT WHEEL HUB LH	179.90	+
47	1 PC FRT LOWER ARM LH	435.70	+
48	1 PC FRT DRIVE SHAFT LH	1,499.00	+
49	1 PC FRT LOWER ARM BALL JOINT LH <i>new</i>	179.90	+
50	1 PC STEERING RACK & PINION	1,650.70	+
51	1 PC FRT FOG LAMP LH <i>could</i>	261.70	✓
52	1 PC FRT FOG LAMP COVER LH <i>could</i>	75.80	✓
53	1 PC FRT FOG LAMP SIDE COVER LH <i>and</i>	68.90	✓
54	1 PC FRT FOG LAMP RH	261.70	+
55	1 PC FRT FOG LAMP COVER RH <i>new</i>	75.80	+
56	1 PC FRT FOG LAMP SIDE COVER RH <i>225</i>	68.90	+
1 pc	" engine mounting <i>and</i>	22,926.00	✓
1 pc	" " " crossmember <i>all new</i>	5,731.50	Less 25%
	Special Net		17,194.64
57	1 SET BONNET RUBBER CLIPS <i>new</i>	30.00	+
58	1 SET BONNET TRIM CLIPS <i>new</i>	48.00	+
1 pc	Front Battery <i>300 180</i>		+

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6 #02-06 Autobay @ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST: 201300201N

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING, SINGAPORE 079120
 TEL: 64193000 FAX: 68357416
 ATTN: Motor Claim Department

Estimate No: EST2000022
 Date: 21 Jan 2020
 Veh Reg No: SLF8153R
 Make/Model: TOYOTA WISH 1.8 CVT
 Chasis No: JTDGG20W00J004876
 Reg. Date: 13/09/2016
 Your Ref No: SFD62D

Claim Type: Third Party
 Accident Date: 18/01/2020
 TP Veh Reg No: SFD62D

Estimate Repair Cost to Vehicle No :SLF8153R

Quantity	Description	List Price	Amount
		SS	SS
59	1 SET FRT SUPPORT PANEL TRIM CLIPS <i>me</i>	40.00 30	
60	1 SET FRT FENDER COWLING CLIPS LH <i>me</i>	48.00 30	
61	1 SET FRT FENDER COWLING CLIPS RH <i>me</i>	48.00 +	
62	1 SET FRT GRILLE CLIPS <i>me</i>	40.00 30	
63	1 SET FRT BUMPER CLIPS <i>me</i>	48.00 30	
64	1 PC FRT NUMBER PLATE <i>Bent</i>	50.00 ✓	
65	1 SET AIR CONDENSER SIDE GARNISH CLIPS <i>me</i> 390	30.00 20	
66	1 SET FRT WIPER PANEL GARNISH CLIPS <i>me</i>	40.00 30	
67	1 PC FRT TYRE LH <i>3 new</i>	380.00 +	
68	1 PC FRT SPORTS RIM LH	850.00 +	
		1.652.00	1.652.00
	Labour		
69	1 TOWING	60.00 ✓	
70	1 TO CHECK WIRING	50.00 30	
71	1 TO REFILL AIRCON GAS	120.00 ✓	
72	1 TO REMOVE AND REFIT UNDERCARRIAGE	600.00 +	
73	1 TO CHECK WHEEL ALIGNMENT	120.00 +	
74	1 TO SPRAY UNDERSEAL	150.00 60	
75	1 (FRONT) TO SPRAY PAINTING	2200.00 1800	
76	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,800.00 1300	
77	1 TO TRANSFER FUSE AND WIRING	500.00 350	
78	1 TO RESET AND PROGRAMME	480.00 +	
		3520	7.080.00 7.080.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST 201300201N

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING, SINGAPORE 079120
 TEL: 64193000 FAX: 68357416
 ATTN: Motor Claim Department

Estimate No: **EST2000022**
 Date: 21 Jan 2020
 Veh Reg No: **SLF8153R**
 Make/Model: TOYOTA WISH 1.8 CVT
 Chasis No: JTDGG20W00J004876
 Reg. Date: 13/09/2016
 Your Ref No: SFD62D

Claim Type: Third Party
 Accident Date: 18/01/2020
 TP Veh Reg No: SFD62D

Estimate Repair Cost to Vehicle No :SLF8153R

Quantity	Description	List Price S\$	Amount S\$
		Total	S\$ 25,926.64
		Add GST @ 7%	1,814.86
		Total Amount Payable	S\$ 27,741.50

TOTAL: SINGAPORE DOLLAR TWENTY SEVEN THOUSAND SEVEN HUNDRED FORTY ONE AND CENTS FIFTY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

Adrian Li
 L/S 21/01/20

10 Days

total: 14526.70

L/S 11.6K:

11.6K
 10 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: