

INS. CASE OWNER:

KAREN TAN

CC4/FCI20001276/Fka3

LKK:

IDAC:

ASSIGNMENT

Surveyor:

RAM

DOI: 22/01/2020

Date / Time : 21/01/2020

Registered in Merimen:

X

Pre-assign / CCU / FTE


	Insured Vehicle No. :	SHB 4426Z	Claim No. :	D20000477MFSH
	Name of Insured :	COMFORT TRANSPORTATION PTE LTD	Policy No. :	D-20094922MFSH
	Insured Tel No. :	HP: _____	Make / Model :	HYUNDAI I40
	Excess Sec II :S\$	D.O.A : 16/01/2020 14:10	Place of Accident :	GUILLEMARD RD TWDS PAYA LEBAR RD B4 LOR 20 GEYLANG
Is driver the owner? (YES / ☒ NO) Nature of Accident : _____				
If NO, Driver Name / Age : ZULKIFLIE BIN A RAHIM				
Driver Tel No. : +65-92311819		(V/L: YES / NO)	OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO	
			Insured Liability : %	Final ? Yes / No

SLZ 76C


 INSRs:
WSP: EURO
Tel: SUCCESS
Liability: SERVICES
RMKS:


 INSRs:
WSP:
Tel:
Liability:
RMKS:


 INSRs:
WSP:
Tel:
Liability:
RMKS:


 INSRs:
WSP:
Tel:
Liability:
RMKS:


 INSRs:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
SLZ 76C	Non-Reporting ltr (1st):	
SHB 4426Z	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
PRELIMINARY ADVICE Date/Time: _____ Sent By: _____		
FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____		
Repair Cost: L/S S\$ 2,700	(4 days) Reduction: 91 %	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email ☐ Call ☐		
Final Liability: %	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lja :
Repair Cost: S\$		+ TP appoint lawyer
Loss of Rental (LOR): S\$	(days)	+ to submit WP
Loss of Use (LOU): S\$	(\$ x days)	
Loss of Income (LOI): S\$	(\$ x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]		
GIA/LTA Search S\$		1) Claim status: Normal/Reject/Private Settle
Medical: S\$		2) Report Format: WP
Disbursement: S\$	(e.g. Tow/ Independent)	3) Survey fee: \$ 550
Legal Cost S\$		
Total: S\$	Global Sum S\$:	
FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email ☐ Call ☐		
Payee 1: S\$	Name 1: _____	
Payee 2: (Strike if N.A.) S\$	Name 2: _____	
Payee 3: (Strike if N.A.) S\$	Name 3: _____	

COPY SENT

ASSIGNMENT

From: 22/01/2020

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLZ 76C

at Workshop n/s: Euro Success

at: 1 Kaki Bukit Ave 6 #02-03

Insured: Autobay

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh: Ah Huat @ 9828 9277

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 1wp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLZ 76C

Yr Regn: 22/03/2023

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MINI COOPER / 1.6M cc 1598

Colour: black A/C: Insured / Std / NI / NA

Sp. Reading: 102082 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 1/11/15/2020/62756

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/45 R17

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 16/01/2020 D.O.I: 22/1/2020

Survey held at: Euro Success

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

CRD \$ 28,796.57 (91%)

MV \$54832

PV \$17903

NV \$11929/=

L/S: \$2700/= with 4 repair days

confirm on 12/3/2020 Kelvin

Date/Time, File Path (o)

☐ : Prel. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Path (o)

2)

Add Fee: ☐ : Site Insp 15

☐ : Interview 15

☐ : Tech. Insp 15

☐ : Wheel and 15

Survey Fee:

Transportation:

3 x R/S 11

Head 150

Body 650

21/4/20

21 x 15 = 315

1707 315

\$50 x 3 = 150

86

721

Report Format:

Long. Sum / M/R: 15

Survey photos: 31

Re-Survey: 41

Aft repair: 6

EURO SUCCESS SERV PTE. LTD

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: SLZ76C

Model: MINI COOPER

QTY	List Items	Price \$
1	REAR WINDSCREEN WITH MOULDING <i>XNN</i>	1500.70
1	REAR TAILGATE <i>XNN</i>	2200.20
2	REAR TAILGATE LAMP L-R @425.2 <i>XNN</i>	850.40
1	REAR TAILGATE LOGO <i>XNN</i>	99.70
1	REAR TAILGATE INNER LOCK <i>XNN</i>	180.10
1	REAR TAILGATE INNER BOARD <i>XNN</i>	1350.50
1	REAR TAILGATE OUTER LOCK SWITCH <i>XNN</i>	456.90
1	REAR TAILGATE WEATHERSTRIP <i>XNN</i>	168.50
1	REAR TAILGATE WIPER MOTOR <i>XNN</i>	630.00
1	REAR TAILGATE NUM.PLATE LAMP GARNISH CHROME <i>XNN</i>	220.20
2	REAR L-R NUMBER PLATE LAMP @65.2 <i>XNN</i>	130.40
1	REAR EXHAUST BOX <i>X(R)</i>	2500.00
2	REAR L-R TAIL LAMP @421.8 <i>XNN</i>	843.60
2	REAR L-R TAIL LAMP PANEL @690.5 <i>XNN</i>	1381.00
2	REAR L-R TAIL LAMP BRACKET @220.6 <i>XNN</i>	441.20
1	REAR BUMPER <i>cut</i>	1550.70 <i>\$886</i>
1	REAR BUMPER TOWING COVER <i>XNN</i>	68.30
1	REAR BUMPER REINFORMENT <i>B7</i>	1950.50 <i>\$596</i>
2	REAR L-R BUMPER RETAINER @87.2 <i>XNN</i>	174.40
2	REAR BUMPER REFLECTOR L-R @86.4 <i>cut</i>	172.80 <i>\$140</i>
1	REAR BUMPER REFLECTOR GARNISH <i>cut</i>	90.70 <i>✓</i>
1	REAR END PANEL <i>XNN</i>	1390.99
1	REAR END PANEL INNER GARNISH <i>XNN</i>	490.50
1	REAR SPARE TYRE PANEL <i>XNN</i>	980.00
1	REAR SPARE TYRE COVER BOARD <i>XNN</i>	330.00
1	REAR SPARE TYRE SPONGE <i>XNN</i>	415.00
1	REAR SPARE TYRE PANEL LOWER GARNISH <i>XNN</i>	162.10
2	REAR FENDER L-R @1650.70 <i>XNN</i>	3301.40
2	REAR FENDER INNER PANEL L-R @1200.30 <i>XNN</i>	2400.60
2	REAR FENDER INNER TRIM BOARD L-R @280.70 <i>XNN</i>	561.40
2	REAR FENDER INNER TOP TRIM L-R @316.20 <i>XNN</i>	632.40
2	REAR FENDER INNER SHIELD L-R @160.50 <i>XNN</i>	321.00
TOTAL		\$27,946.19 <i>\$1712.7</i>
LESS 10%		\$2,794.62 <i>\$171.27</i>
TOTAL		\$25,151.57 <i>\$1541.43</i>
<u>Special Nett Items</u>		
1	REAR REVERSE CAMERA <i>XNN</i>	650.00
1 SET	REAR REVERSE SENSOR <i>cut</i>	750.00 <i>\$350</i>
1 SET	REAR BUMPER CLIPS <i>cut</i>	45.00 <i>✓</i>
2 SET	REAR FENDER INNER SHIELD CLIP <i>XNN</i>	90.00
		<i>\$395</i>

\$1,535.00

Labour Charges

TO CHECK REAR ELECTRICAL WIRING	80.00
TO REMOVE, REFIX REAR WINDSCREEN	180.00
TO REMOVE, REFIX REAR SEAT, INTERIOR TRIMS TO ASSIST REPAIR	150.00
TO REMOVE, REFIX REAR UNDERCARRIAGE	400.00
TO RESPRAY UNDERCOATING	500.00
TO RESPRAY PAINTING AND ETC	1500.00
PANEL BEATING, CUT, WELD REMOVE AND REPLACING ABOVE PARTS	2000.00
	\$4,810.00

\$1440

Total

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$31,496.57

\$3416.93

12/07/2020
89602778
all repair photo
L/S
L/S \$2700.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	670G
Vehicle Details	
Vehicle No.:	SLZ76C
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Feb 2020
Vehicle Make:	MINI
Vehicle Model:	JOHN COOPER WORKS HB 1.6 AT SR HID ABS
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	A561J360N18B16C
Chassis No.:	WMWSU92020T627566
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$33,005.00
Original Registration Date:	22 Mar 2013
First Registration Date:	22 Mar 2013
Transfer Count:	4
Actual ARF Paid:	\$38,207.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Mar 2023
PARF Rebate Amount:	\$24,834.00
Intended COE Rebate Details	
COE Expiry Date:	21 Mar 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$74,689.00
COE Rebate Amount:	\$23,069.00
Total Rebate Amount:	\$47,903.00

The information contained herein is correct as at 19 Feb 2020

OK

PARF: 16/1/2020

Residual value: 3 years 3 months 6 days (39.1)

Deprec: \$12500. \$1041 16/monthly

$39.1 \times \$1041.66 = \$40728.90 + \$19103.50$

$= \$59832.4$



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement

Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

2011 Mercedes C180K. Perfect For COE Renewal.



FINRF Value \$32k. Great For Short Term Drive Or Renew COE. New Taxes Before CNY. Direct Owner. [View Ad](#)



VALUE FOR MONEY

VALUE FOR TIME

A PEACE OF MIND

HOTLINE: 6741 9997

[View our Cars](#)

Browse by Category

Sort by Date Posted

20 results/page

6 vehicles

mini Cooper

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	mini Cooper	Any	Any	2013	Any	Any	Any	Available
	MINI Cooper S 1.6A Bayswater	\$51,800	\$13,570 /yr	01-Feb-2013	1,598 cc	89,000 km	Sports	Available
Low Mileage Done At 89000 Km Only Fully Serviced And Maintained By Mini Habitat. Bays Water Edition With Twin Sunroof And Premium Harmon Kardon Sound System.bank And In House Loan Available. Accident Free.								
Posted: 11-Feb-2020 Tags: 2013 MINI Cooper, 2013 mini cooper, MINI Cooper, mini cooper, MINI, Cooper, cooper, Used MINI								
	MINI Cooper 1.6A Baker Street	\$50,000	\$11,500 /yr	29-Jul-2013	1,598 cc	56,000 km	Hatchback	Available
Direct Owner. Special Mini Baker Street Edition. Extremely Low Mileage With Full Servicing Records. Parked In Condo Under Shelter. Interior Leather Conditioning And Cleaning With External Polish And Glass Coating Recently Done (Sep 2019). Road Tax Paid Till July 20...								
Posted: 09-Feb-2020 Tags: 2013 MINI Cooper, 2013 mini cooper, MINI Cooper, mini cooper, MINI, Cooper, cooper, Used MINI								
	MINI Cooper S Countryman 1.6A	\$61,800	\$12,850 /yr	29-Jul-2013	1,598 cc	-	Sports	Available
Well Maintained Unit By A MINI Lover. Serviced Regularly. Just Did Full Servicing. Perfect For Everyone.High Loan 80% Of The Car Price Available With Interest Rates From 2.28%. Trade In Welcome. Call Now To Book An Appointment To View This Beauty. Viewing Strictly...								
Posted: 03-Feb-2020 Tags: 2013 MINI Cooper, 2013 mini cooper, MINI Cooper, mini cooper, MINI, Cooper, cooper, Used MINI								
	MINI Cooper S Coupe 1.6A	\$68,288	\$17,570 /yr	29-Apr-2013	1,598 cc	65,000 km	Sports	Available
\$35k Worth Of Add On, Full Bucket Seats, Alcantara Steering Wheel, Diamond Coating Paint Works, Lightweight Wheels, Ferodo Ds2500 Brake Pads, Perfect For Future COE Renewal, Owner's Project Car, Only For Those That Know How To Appreciate, No Low Baller, No De...								
Posted: 31-Jan-2020 Tags: 2013 MINI Cooper, 2013 mini cooper, MINI Cooper, mini cooper, MINI, Cooper, cooper, Used MINI								
	Bastuck Sports Exhausts							
Bastuck Sports Exhausts for Mini R56 One / Cooper [Diesel]								
More info about this product.								
	MINI Cooper S 1.6A Bayswater	\$56,800	\$13,890 /yr	21-Mar-2013	1,598 cc	104,000 km	Sports	Available
Full Service Records With Eurokars. Optional Warranty Available! 1 Owner, Accident-Free. Harmon Kardon Sound System, Comfort Access, Start/Stop Button, Loan And Trade In Available! Consignment Unit! Call Us Now And Grab This Beauty! Call To Arrange Viewing!								
Prem Roy Motoring								
Posted: 08-Jan-2020 Tags: 2013 MINI Cooper, 2013 mini cooper, MINI Cooper, mini cooper, MINI, Cooper, cooper, Used MINI								
	MINI Cooper S 1.6A Bayswater	\$55,800	\$13,530 /yr	15-Mar-2013	1,598 cc	46,000 km	Sports	Available
One Owner, Low Mileage Done. No Dealers And Consignment Agents Please.								
Posted: 16-Dec-2019 Tags: 2013 MINI Cooper, 2013 mini cooper, MINI Cooper, mini cooper, MINI, Cooper, cooper, Used MINI								

MOTOR SURVEY ASSIGNMENT

Date	20-01-2020	Our Ref No. D20000477MFSH
Accident Date	16-01-2020	Claim Type. Third Party
Insured Vehicle	SHB4426Z	Third Party Vehicle. SLZ76C
Survey Location	1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY	
Contact Person.	AH HUAT	
Contact No.	6742 6231/ 9828 9277	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

12:49pm @ 21/1/2020
V: IM
P: Ah Huat

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	EURO SUCCESS SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	HIN TAT AUGUSTINE & PARTNERS	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 18 March 2020 11:32 AM
To: 'Karen Tan'; Mei Kwan (LKKAuto)
Cc: Admin A
Subject: RE: SURVEY ASSESSMENT - D20000477MFSH/1 // EXPRESS SETTLEMENT

Dear Ms. Karen,

We refer to the above matter and your e-mail below.

The Third party workshop (Mr. Ah Huat) confirmed that they are not doing direct settlement and the solicitors will be handling the third party claim.

As such, we will submit our WP accordingly.

Thank you.

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Karen Tan <karentan@msfirstcapital.com.sg>
Sent: Thursday, 12 March 2020 4:14 PM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Khanchna (LKK Auto) <khanchna@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D20000477MFSH/1 // EXPRESS SETTLEMENT

Dear Sirs/Madam,

We had already received the third party claim from the solicitors. Can the workshop still do direct settlement?

Pls advise.

Best Regards,

Karen Tan
Motor Claims Dept.
MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3582 | Fax No. : 6507 3849 | Company Regn. No. 195000106C
A Member of **MS&AD** INSURANCE GROUP

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Thursday, March 12, 2020 4:00 PM
To: Karen Tan <karentan@msfirstcapital.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Khanchna (LKK Auto) <khanchna@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D20000477MFSH/1 // EXPRESS SETTLEMENT

YOUR REF: D20000477MFSH
LKK REF: CC4/FCI20001276/Fka3

Dear Sir / Madam,

We refer to the above matter.

We had inspected TP vehicle SLZ 76C on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Please take note that the case handler in-charge is Khanchna and she can be contacted at DID: 6841 2360.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Tuesday, 21 January, 2020 12:51 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; Admin A <admin-a@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D20000477MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

~ Wishing you a Happy and Prosperous Lunar New Year ~



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Tuesday, 21 January 2020 12:12 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D20000477MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20001276/Fka3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-04-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4426Z	Veh. Inspected	SLZ 76C	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20000477MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	21/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	MINI COOPER 1.6 AT	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WMWSU92020T627566	Colour	BLACK	
Odometer	102082	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/45 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	205/45 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/45 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/45 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/01/2020	Inspection Date	22/01/2020	
Survey held at	EURO SUCCESS SERVICES PTE LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 76C

Qty	Description of Parts	Condition	Initial Surveyor (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN WITH MOULDING	NOT NECESSARY	1,500.70	-
1	REAR TAILGATE	NOT NECESSARY	2,200.20	-
2	REAR TAILGATE LAMP L-R @\$425.20	NOT NECESSARY	850.40	-
1	REAR TAILGATE LOGO	NOT NECESSARY	99.70	-
1	REAR TAILGATE INNER LOCK	NOT NECESSARY	180.10	-
1	REAR TAILGATE INNER BOARD	NOT NECESSARY	1,350.50	-
1	REAR TAILGATE OUTER LOCK SWITCH	NOT NECESSARY	456.90	-
1	REAR TAILGATE WEATHERSTRIP	NOT NECESSARY	168.50	-
1	REAR TAILGATE WIPER MOTOR	NOT NECESSARY	630.00	-
1	REAR TAILGATE NUM PLATE LAMP GARNISH CHROME	NOT NECESSARY	220.20	-
2	REAR L-R NUMBER PLATE LAMP @\$65.20	NOT NECESSARY	130.40	-
1	REAR EXHAUST BOX	TO REPAIR SEE LABOUR	2,500.00	-
2	REAR L-R TAIL LAMP @\$421.80	NOT NECESSARY	843.60	-
2	REAR L-R TAIL LAMP PANEL @\$690.50	NOT NECESSARY	1,381.00	-
2	REAR L-R TAIL LAMP BRACKET @\$220.60	NOT NECESSARY	441.20	-
1	REAR BUMPER	CUT	1,550.70	886.00
1	REAR BUMPER TOWING COVER	NOT NECESSARY	68.30	-
1	REAR BUMPER REINFORCEMENT	BENT	1,950.50	596.00
2	REAR L-R BUMPER RETAINER @\$87.20	NOT NECESSARY	174.40	-
2	REAR BUMPER REFLECTOR L-R @\$86.40	SCRATCHED	172.80	140.00
1	REAR BUMPER REFLECTOR GARNISH	CRACKED	90.70	90.70
1	REAR END PANEL	NOT NECESSARY	1,390.99	-
1	REAR END PANEL INNER GARNISH	NOT NECESSARY	490.50	-
1	REAR SPARE TYRE PANEL	NOT NECESSARY	980.00	-
1	REAR SPARE TYRE COVER BOARD	NOT NECESSARY	330.00	-
1	REAR SPARE TYRE SPONGE	NOT NECESSARY	415.00	-
1	REAR SPARE TYRE PANEL LOWER GARNISH	NOT NECESSARY	162.10	-
2	REAR FENDER L-R @\$1650.70	NOT NECESSARY	3,301.40	-
2	REAR FENDER INNER PANEL L-R @\$1200.30	NOT NECESSARY	2,400.60	-
2	REAR FENDER INNER TRIM BOARD L-R @\$280.70	NOT NECESSARY	561.40	-

Report Ref No. CC4/FCI20001276/Fka3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Initial Surveyor (\$)	Our Adjusted (\$)
2	REAR FENDER INNER TOP TRIM L-R @\$316.20	NOT NECESSARY	632.40	-
2	REAR FENDER INNER SHIELD L-R @\$160.50	NOT NECESSARY	321.00	-
	LESS 10% DISCOUNT		-2,794.62	-171.27
			25,151.57	1,541.43
	<u>SPECIAL NETT ITEMS</u>			
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	650.00	-
1	SET REAR REVERSE SENSOR (SN)	SCRATCHED	750.00	350.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	45.00	45.00
2	SET REAR FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	90.00	-
			1,535.00	395.00
	<u>LABOUR</u>			
	TO CHECK REAR ELECTRICAL WIRING.		80.00	80.00
	TO REMOVE,REFIX REAR WINDSCREEN.	NOT NECESSARY	180.00	-
	TO REMOVE,REFIX REAR SEAT ,INTERIOR TRIMS TO ASSIST REPAIR.	NOT NECESSARY	150.00	-
	TO REMOVE,REFIX REAR UNDERCARRIAGE.	NOT NECESSARY	400.00	-
	TO RESPRAY UNDERCOATING.		500.00	150.00
	TO RESPRAY PAINTING AND ETC.		1,500.00	450.00
	PANEL BEATING ,CUT ,WELD REMOVE AND REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR EXHAUST BOX .		2,000.00	800.00
			4,810.00	1,480.00
	GRAND TOTAL		31,496.57	3,416.43
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		0.00	2,700.00

Report Ref No. CC4/FCI20001276/Fka3q2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.