

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SJT4245K

No.	Qty	List Items				
1	1	Rear bumper	MSWB	\$ Bu	451.60	✓
2	2	Rear bumper reflector		\$	285.80	2x 142.90
3	2	Rear bumper inner side bracket		\$ Di	112.60	✓
4	2	Rear bumper side retainer		\$ Di	171.20	✓
5	2	Rear bumper corner retainer		\$ Di	86.00	✓
6	1 set	Rear bumper clips		\$ Bu	30.00	✓
7	1	Rear boot lid		\$ Bu	589.10	✓
8	1	Rear boot outer handle garnish		\$ Su	175.00	X
9	1	Rear boot centre "TOYOTA" logo		\$ Bu	48.10	✓
10	1	Rear boot LH "VIOS" emblem		\$ Bu	55.60	✓
11	1	Rear boot RH "E" emblem		\$ Bu	45.30	✓
12	2	Rear boot hinge		\$ R	128.00	X
13	1	Rear boot top lock		\$ Bu	121.35	✓
14	1	Rear boot lower lock catch		\$ R	41.40	X
15	1	Rear boot weatherstrip		\$ Cu	176.80	30% 88.40
16	2	Taillamp panel		\$ R	257.00	X
17	2	Taillamp C 297.60	my	\$ Cu	665.20	2x
18	1	Rear end panel		\$ R	575.00	✓
19	1	Rear end panel top garnish		\$ Bu	211.40	✓
20	1	Rear spare tyre panel		\$ R	682.50	X
21	1	Rear spare tyre top board		\$ Bu	139.50	✓
22	1	Rear compartment centre foam tray		\$ Su	167.50	X
23	2	Rear compartment top side board		\$ Su	96.00	X
24	1	Rear compartment RH foam tray		\$ Su	192.36	X
25	1	Rear compartment LH foam tray		\$ Su	154.35	X
26	2	Rear fender inner side trim		\$ Su	451.00	X
27	1 set	Rear fender inner side trim clips		\$ Bu	60.00	X
28	1	Rear exhaust silencer		\$ Bu	811.30	✓ 652.70
			hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed			
			Less 25%			
			Total:			
			Special Nett Items			
29	1 set	Reverse sensors		\$ Bu	250.00	200.00
30	1 set	Reverse camera		\$ Su	550.00	X
31	1	Rear number plate		\$ Su	50.00	X
32	1	Rear bumper lower skirting		\$ Cu	800.00	✓
33	1	Rear exhaust tail chrome pipe		\$ Bu	120.00	✓
34	1 set	Rear spare tyre/end panel sealant		\$ Bu	100.00	30.00
			Total:			
			Labour			
1		Labour Charges for remove/refit, cutting/welding and replacement of damages.		\$	1,300.00	700.00

2	To putty and spray Spray Paintings charges.	\$	1,200.00	900l
3	To check wirings and lightings.	\$	40.00	20l
4	To remove, refit reverses sensors & reverse camera.	\$	100.00	50l
5	To remove, refit rear boot lid fittings.	\$	80.00	50l
6	To remove, refit rear upholstery and attachments.	\$	150.00	60l
7	To remove, refit rear exhaust silencer.	\$	80.00	80l
8	To supply and apply anti rust treatment	\$	80.00	60l
Total :		\$	<u>3,030.00</u>	

Total Parts and Labour : \$ 10,060.72

10,135.72#