

↩ Reply all ✕ 🗑 Delete 🚫 Junk 🚫 Block ...

FWD REF: 1202000003210 // TP Veh: SHA3468P // DOA: 18/01/2020 //LKK REF: CC4/FWD20001283/Dpa3

HT

Hsiao Tong (LKKAUTO)

Sat 4/4/2020 7:44 PM

josey.loh@fwd.com ✕


Hi Josey,

We refer to your queries in Merimen.

According to surveyor, this model taxi is the newer Hyundai Ioniq model. Part prices checked with CDGE as this model is not sold in the public market. Part prices for newer design vehicles are no longer the same as compared to older days vehicles due to the lighter, higher strength material that body parts are made of; and also newer safety features that are found on new vehicles. Because of this less extensive damage may not necessarily translate to low repair cost.

Kindly let us have your mandate after review the matter.

Thanks.



Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108