

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 20-Jan-20

INSURANCE: _____

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA3468P

Description	Qty	List Price	Amount
Radiator Grille <i>distorted</i>	1 ✓	\$ 1,227.50	\$ 1,227.50
Front Bumper Cover <i>distorted</i> <i>photo</i> <i>monopoly broken</i>	1 ✓	\$ 418.30	\$ 418.30
Front Bumper Sponge/Absorber <i>new</i>	1 X	\$ 86.90	\$ 86.90
Front Bumper Reinforcement <i>new</i>	1 X	\$ 1,075.10	\$ 1,075.10
Front Bumper Grille (LH/RH) <i>new</i>	2 X	\$ 186.90	\$ 373.80
Front Bumper Bracket Top (LH/RH) <i>new</i>	2 X	\$ 35.00	\$ 70.00
Front Bumper Bracket (LH/RH) <i>new</i>	2 X	\$ 28.00	\$ 56.00
Front Bumper Side Bracket Support <i>new</i>	2 X	\$ 12.00	\$ 24.00
Front Bumper Clips 10 pcs <i>new</i>	1 ✓	\$ 22.00	\$ 22.00
Front Bumper Centre Grille <i>new</i>	1 X	\$ 318.80	\$ 318.80
Headlamp Support Panel Assy <i>new</i>	1 X	\$ 949.30	\$ 949.30
Headlamp <i>new</i> <i>distorted</i>	1 X	\$ 1,198.80	\$ 1,198.80
Boot Lid <i>Distorted</i> <i>St</i>	1 ✓	\$ 2,480.40	\$ 2,480.40
Boot Lid 'H' Emblem <i>new</i>	1 ✓	\$ 28.00	\$ 28.00
Emblem-Hybrid <i>new</i>	1 ✓	\$ 24.30	\$ 24.30
Emblem-Ionic <i>new</i>	1 ✓	\$ 31.30	\$ 31.30
Boot Lid Glass, Lower <i>new</i>	1 X	\$ 384.90	\$ 384.90
Rear Bumper <i>distorted</i> <i>photo</i> <i>broken</i>	1 ✓	\$ 459.40	\$ 459.40
Rear Bumper Reinforcement <i>crack</i>	1 X	\$ 294.80	\$ 294.80
Rear Bumper Reinforcement Bracket (LH/RH) <i>St</i> <i>Distorted</i>	2 X	\$ 138.10	\$ 276.20
Rear Bumper Centre Moulding Assy <i>distorted</i> <i>cut</i>	1 ✓	\$ 451.25	\$ 451.25
Rear Bumper Lower Centre Moulding Assy <i>new</i>	1 X	\$ 47.50	\$ 47.50
Rear Bumper Stay <i>new</i>	1 X	\$ 138.10	\$ 138.10
Rear Bumper Side Bracket (LH/RH) <i>new</i>	2 X	\$ 55.80	\$ 111.60
Rear Bumper Cover Clips <i>new</i>	1 ✓	\$ 22.00	\$ 22.00
Rear Bumper Under Centre <i>new</i>	1 X	\$ 53.85	\$ 53.85
Rear Bumper Side Under (LH/RH) <i>new</i>	2 X	\$ 33.10	\$ 66.20
Rear Bumper Reflector Lamp (LH/RH) <i>new</i>	2 X	\$ 31.90	\$ 63.80
Rear Bumper Fog Lamp <i>socket broken</i>	1 X	\$ 201.50	\$ 201.50
Rear Bumper Reserve Light (Parking Brake Light) <i>new</i>	1 X	\$ 257.10	\$ 257.10
Tail Lamp (LH/RH) <i>new</i>	2 X	\$ 870.40	\$ 1,740.80
Tail Lamp Quarter Panel (LH/RH) <i>new</i>	2 X	\$ 208.90	\$ 417.80
Rear Panel <i>Distorted</i>	1 X	\$ 532.00	\$ 532.00
Rear Panel Lower Panel <i>new</i>	1 X	\$ 39.40	\$ 39.40
Spare Tyre Holder <i>new</i>	1 X	\$ 223.10	\$ 223.10
Spare Tyre Panel <i>new</i>	1 X	\$ 892.50	\$ 892.50
Spare Tyre Flip Board <i>new</i>	1 X	\$ 338.80	\$ 338.80
Exhaust Pipe Insulator <i>new</i>	1 X	\$ 35.00	\$ 35.00
Exhaust Silencer <i>new</i>	1 X	\$ 943.50	\$ 943.50
Exhaust Pipe Hanger <i>new</i>	1 X	\$ 29.20	\$ 29.20
SUB TOTAL			\$ 16,404.80

6446.95
5157.56

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 22-Jan-20

INSURANCE: FWD

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 3468P

[illegible]

1 yan
Lkk Andro

6947-88

25394.32