

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 26256

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0062/2020/NS
Date	:	16-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No : SJP 6170 A

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street
#19-00 The Octagon
Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen
Tel: 6389 6541 - Fax: 6224 7175

Owner's Name	:	Mr Poh Bok Seng
Address	:	Blk 163 Tampines Street 12 #11-253 Singapore 521163
Telephone	:	HP +65 98301903
Type of Claim	:	Third Party Claim
Policy No.	:	1900002533
Vehicle No	:	SLR 198 B
Model Code	:	Q2 1.0 TFSI S TRONIC
Model / Year	:	Jan-19
Engine No	:	CHZ A93127
Chassis No	:	WAUZZZGA8KA001634
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	13-Jan-20
Place of Accident	:	Tampines St 31

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 198 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper and lower spoiler. Re-organise crash management components. Reinstall all parts removed.	\$ 1,200.00 ✓ 700	
3	To respray rear bumper.	\$ 1,000.00 ✓ 700	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 2,672.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 198 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>Rep's</i>	\$ 1,074.00	+
2	REAR BUMPER FIXING PARTS <i>neu</i>	\$ 70.00	+
3	REAR BUMPER SPOILER - LH <i>De l d</i>	\$ 259.00	✓
4	REAR BUMPER TOWING EYE COVER	\$ 39.00	+
5	REAR LIGHT REFLECTOR - RH	\$ 27.00	+
6	REAR BUMPER CARRIER	\$ 501.00	+
7	REAR BUMPER HOLDING STRAP - LH / RH	2 \$ 24.00	+
8	REAR BUMPER GUIDE SECTION - RH	\$ 49.00	+
9	REAR PARKING AID SENSOR - OUTER	\$ 231.00	✓
10	REAR PARKING AID SEAL RING	4 \$ 12.00	+
11	REAR WHEEL COVER - LH / RH <i>neu</i>	2 \$ 312.00	✓
12	TAIL LIGHT - RH	\$ 1,207.00	+
13	TAIL LIGHT TRIM - RH	\$ 27.00	+
14	SUNDRIES	\$ 200.00	?

TOTAL SPARE PARTS CHARGES

: \$ 4,032.00

TOTAL LABOUR CHARGES

: \$ 2,672.00

GRAND TOTAL

: \$ 6,704.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Admin 
Surveyed Date : 21/01/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , 032yr

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant