

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 26476

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0061/2020/NS
Date	:	16-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No : SJD 5220 T

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name	:	Mr Koh Kah Seng
Address	:	31 Rosewood Drive #12-28 Singapore 737922
Telephone	:	HP +65 92394587
Type of Claim	:	Third Party Claim
Policy No.	:	1800035099
Vehicle No	:	SLX 7254 U
Model Code	:	A4 Sedan 2.0 TFSI BW
Model / Year	:	Apr-18
Engine No	:	CVK 050553
Chassis No	:	WAUZZZF41JA073284
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	15-Jan-20
Place of Accident	:	Ang Mo Kio Blk 410 And Blk 416 Car Park

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 7254 U

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00 1400	1,750.00
3	To rep-spray front bumper and rhs front fender.	\$ 2,000.00 1400 ✓	✓
4	To carry out diagnostic checks	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$ 5,002.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 7254 U

S/N	Parts Description	G/W 27/1		Damaged Parts & Prices	
				S/Nett	Remarks
1	FRONT BUMPER <i>Rehnd</i>	\$	✓ 946.00	✓	
2	FRONT BUMPER FIXING PARTS <i>neu</i>	\$	258.00	+	
3	FRONT BUMPER SECURING STRIP <i>neu</i>	\$	32.00	+	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>neu</i>	\$	191.00	+	
5	FRONT BUMPER AIR GUIDE - RH	\$	56.00	+	
6	FRONT BUMPER AIR G UIDE GRILLE - RH <i>neu</i>	\$	123.00	+	
7	FRONT BUMPER GUIDE SECTION - RH	\$	34.00	+	
8	FRONT FENDER - RH <i>Dented</i>	\$	✓ 700.00	✓	699.50
9	FRONT FENDER ATTACHMENT PARTS <i>Not neu</i>	\$	183.00	X	
10	FRONT FENDER CLOSING ELEMENT - RH <i>neu</i>	\$	45.00	+	
11	FRONT FENDER BRACKET - RH <i>Not neu</i>	\$	32.00	X	
12	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH <i>Not neu</i>	\$	45.00	X	
13	FRONT WHEEL HOUSING LINER - RH <i>neu</i>	\$	220.00	+	
14	WHEE HOUSING LINER ATTACHMENT PARTS <i>neu</i>	\$	82.00	+	
15	WHEEL SPOILER <i>neu</i>		TBC	+	
16	WHEEL SPOILER TRIM - RH	\$	33.00	+	
17	STONE CHIP GUARD - RH <i>neu</i>	\$	✓ 46.00	✓	45.80
18	FENDER LEDGE COVER - RH <i>neu</i>	\$	28.00	?	✓ 27.80
19	FENDER LEDGE TOP COVER - RH <i>neu</i>	\$	21.00	?	✓ 20.20
20	LED HEADLIGHT - RH <i>Not neu</i> / CRA	\$	7,087.00	+	✓
21	SUNDRIES <i>neu</i>	\$	300.00	✓	18.00

TOTAL SPARE PARTS CHARGES : \$ 11,462.00

TOTAL LABOUR CHARGES *Steve* : \$ 5,002.00

GRAND TOTAL *10/3/20* : \$ 16,464.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 21/01/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

China Taiping Insurance (SG) Pte Ltd
105 Cecil Street
#19-00 The Octagon
Singapore 069534
Attn: Motor Claims Dept
Tel: 6389 6541 - Fax: 6224 7175

Estimate No. PA/TP/0061/2020/NS
Date 10-Mar-20
Service Advisor Glory Tan
Pages 1 of 1
Regn No SLX 7254 U
Model No A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Front fender brace RHS <i>BT</i>	\$ 112.00 ✓	111.50

TOTAL

\$ 112.00

For Premium Automobiles Pte Ltd

Steve
10/3/20

Authorised Signature