

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLS7372M

Chassis No : MRHFC1660HT000348

Model : CIVIC 1.5 TURBO VTIS YM2017

Owner's Name : TOH MING CHUAN

Ins Policy No. :

Date of Accident : 18/1/2020

Document No. : SQT20000326 Page 1

Date : 20. Jan 2020

Customer No. : WZI007

Svc Advisor : YOU PO SOON

Engine No : L15B72454968

Date | Time : 20. Jan 2020 12:01:45 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TOH MING CHUAN OWNER INSURER: AVIVA LTD ACC DATE: 18/1/2020 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INSURANCE TP VEH: SHD3173Z						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	20/2 1	617.20	✓ 25	462.90	32.40	495.30
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1 1	180.00	✓ 25	135.00	9.45	144.45
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1 1	11.50	X 25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1 1	11.50	X 25	8.62	0.60	9.22
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	cu 1	39.80	✓ 25	29.85	2.09	31.94
91505-TM8-003	CLIP,BUMPER	1 8	2.30	✓ 25	13.80	0.97	14.77
38387-TZ5-A01	ANTENNA ASSYL.F.	1 1	60.80	? 25	45.60	3.19	48.79
74940-SZW-003	BUZZER ASSYSMART	1 1	62.90	? 25	47.17	3.30	50.47
			Sum Item		751.56	52.60	804.16
BOSUN	SUNDRIES	1 1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1 1	180.00	120	180.00	12.60	192.60
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1 1	180.00	120	180.00	12.60	192.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1 1	480.00	120 X	480.00	33.60	513.60
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1 1	1300.00	560	1300.00	91.00	1391.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1 1	1100.00	450	1100.00	77.00	1177.00
			Sum Labor		3290.00	230.30	3,520.30

Printed on 20/1/2020 12:11:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLS7372M

Chassis No : MRHFC1660HT000348

Model : CIVIC 1.5 TURBO VTIS YM2017

Owner's Name : TOH MING CHUAN

Ins Policy No. :

Date of Accident : 18/1/2020

Document No. : SQT20000326 **Page** 2

Date : 20. Jan 2020

Customer No. : WZ1007

Svc Advisor : YOU PO SOON

Engine No : L15B72454968

Date | Time : 20. Jan 2020 12:01:45 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	mercus alt						
Date & Time	3/2/20 9am						
Excess							
Status	not settled						
Signature	take the repair only.						

Total Amount 4,041.56 282.90 4,324.46

Total (Inclusive of GST) 4,324.46

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 20/1/2020 12:11:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.