

TP Claims against NTUC Income: Follow-Through Survey

Date: 05/03/2020

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1080940-003	SMRT	SHD6457K	SMF2343L	17/01/2020	15:05	\$ 21,885.75
2	MT/1080907-002	SMRT	5HC4574Z	5KF2065M	19/01/2020	18:20	\$ 8,612.62
3							
4							
5							
6							
7							
8							

Oi Sun Pin (LKK Auto)

From: Oi Sun Pin (LKK Auto)
Sent: Thursday, 27 February, 2020 6:05 PM
To: 'Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)'
Subject: RE: SHD6457K

Hi Poh Suan,

Confirm the finalize amount \$9390.83. Repair day 6 days under part by part repair.

Thank you.

Best Regards,
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [<mailto:YeoPohsuan@smrt.com.sg>]
Sent: Tuesday, 18 February, 2020 5:08 PM
To: Oi Sun Pin (LKK Auto)
Cc: SUR; CS A Team
Subject: SHD6457K

Hi Sun Pin,

Attached herewith the repair estimate of SHD 6457K having Case No: TAX/01/20/2073.

There is no change to the approved amount of \$9,390.83 @ 6 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Sent: Tuesday, 18 February 2020 4:54 PM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: Scan Data from FX-D421D6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/01/2020 08:36
Date Of Accident	17/01/2020 15:05
Exact Location Of Accident	PIE TOWARDS CHANGI AIRPORT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6457K
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	1XXXXX369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	
Driver	
Name of Driver	WONG YOON MENG
NRIC No	SXXXX118H
Date Of Birth	18/12/1955
Occupation	OUTDOOR
Date Of Driving Pass	27/03/1975
Driving Experience	44 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 114
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? YES
 Foreign Vehicle Registration Number KV7020A (PRIVATE CAR)
 Number of vehicles (including own vehicle) involved in the accident 3
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : UNKNOWN
 GENDER: : FEMALE
 Passenger 2 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20200117/2172 ON THE 17/01/2020 AT ABOUT 1505 HRS, I WAS DRIVING MY TAXI (SHD6457K) ALONG THE MOST RIGHT LANE OF PIE EXPRESSWAY. I WAS FETCHING TWO PASSENGERS ON THE WAY HEADING TOWARDS CHANGI AIRPORT. AS I WAS DRIVING A FOREIGN VEHICLE (KV7020A) IN FRONT OF MY VEHICLE AND AFTER WHICH, THE SAID VEHICLE IN FRONT SLOW DOWN AND I SLOW DOWN AS WELL. AS I SLOW DOWN MY VEHICLE, THE VEHICLE (SMF2343L) BEHIND MY VEHICLE KNOCKED ONTO THE REAR OF MY VEHICLE AND IT CAUSED MY VEHICLE TO INCH FORWARD AND KNOCK ONTO THE REAR BUMPER OF VEHICLE (KV7020A). AFTER THE COLLISION, I GOT DOWN FROM MY VEHICLE TO TAKE PICTURES OF THE COLLISION AND I EXCHANGED PARTICULARS WITH THE OTHER DRIVERS AS WELL. THE TWO PASSENGERS OF MINE GOT DOWN FROM MY TAXI AND ARRANGED FOR THEIR OWN TRANSPORT AFTER WHICH, I WISH TO STATE THAT I AM NOT INJURED . THAT IS ALL.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TOO BIG
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMF2343L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

MUHAMMAD NASIR BIN KHALID

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

KV7020A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

LIM KHANG GHEE

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PRN No.:



**SINGAPORE
POLICE FORCE**



T/20200117/2172

1 of 4

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20200117/2172

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/01/2020 23:03		Video Report No.:		Station Diary No.: 110	
Informant's Particulars					
Name of Informant: WONG YOON MENG			Address: APT BLK 114 EDGEFIELD PLAINS #02-370 SINGAPORE 920114		
ID Type / ID No.: NRIC NO / S1147118H			Contact No.:		Mobile: 96925418
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 64	Date of Birth: 18/12/1955	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,2A,2,3,4,5		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 17/01/2020 15:05	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY Along PIE Expressway nearing ramp post 388 nearing to lamp post 388 Lamp Post Number: 388				
Weather: Cloudy		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
KV7020A	Car				Slightly Damaged	0
SHD6457K	Car				Slightly Damaged	2
SMF2343L	Car				Seriously Damaged	0



**SINGAPORE
POLICE FORCE**



T/20200117/2172

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

2 of 4

Report No. T/20200117/2172

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	Lim Kang Chee	ID No.	750327025481
Related Vehicle	KV7020A (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	WONG YOON MENG	ID No.	S1147118H
Related Vehicle	SHD6457K (Car)	Contact No.	96925418
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	Muhammad Nasir Bin Khalid	ID No.	S9025865F
Related Vehicle	SMF2343L (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 17/1/2020 at about 1505hrs, I was driving my taxi (SHD6457K) along the most right lane of PIE Expressway. I was fetching two passengers on the way heading towards Changi Airport.

As I was driving, there was a foreign vehicle (KV7020A) in front of my vehicle and after which, the said vehicle in front slow down and I slow down as well. As I slowed down my vehicle, the vehicle (SMF2343F) behind my vehicle knocked onto the rear of my vehicle and it caused my vehicle to inch forward and knock onto the rear bumper of vehicle (KV7020A).



**SINGAPORE
POLICE FORCE**



T/20200117/2172

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-8049999

3 of 4

Report No. T/20200117/2172

CONTINUATION OF REPORT

After the collision, I got down from my vehicle to take pictures of the collision and I exchanged particulars with the other drivers as well. The two passengers of mine got down from my taxi and arranged for their own transport after which, I wish to state that I am not injured. That is all.



**SINGAPORE
POLICE FORCE**



T/20200117/2172

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

4 of 4
Report No. T/20200117/2172

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 1 DARREL CHOO YU WEI	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 17/01/2020 23:03
Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP 66  Signature:  Singapore Police Force	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 369K

Vehicle Details

Vehicle No.: SHD6457K

Vehicle to be Exported: No

Intended Deregistration Date: 21 Jan 2020

Vehicle Make: TOYOTA

Vehicle Model: PRIUS HYBRID 1.8 CVT

Primary Colour: Maroon

Manufacturing Year: 2017

Engine No.: 2ZRS100588

Chassis No.: JTDKB3FU703573412

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$29,007.00

Original Registration Date: 01 Nov 2017

First Registration Date: 01 Nov 2017

Transfer Count: 0

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 31 Oct 2025

PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 31 Oct 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$33,596.00

COE Rebate Amount: \$24,260.00

Total Rebate Amount: \$28,010.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Jan 2020

OK



Case Details

Case Reference Number : TAX/01/20/2073 Company Type : SMRT Taxis Pte Ltd Insurance Company Name : NTUC Income Insurance Co-operative Ltd
 Type of Repair : Accident Repair Estimation ID : EST-10191-ID Accident Date and Time : 17/01/2020 07:05 AM
 Vehicle Registration Number : SHD5457K Assigned By : Taxi Claims Manager Team Vehicle Age(In Months) : 26

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Quantity	Surveyor Approval		Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	✓ CR4.
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Check	✗ SVC
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Check	✗ SVC
One Time Key In	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			COVER, FR BUMPER LH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	0	0	Check	✗ SVC
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace	✓ CR4.SN
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	1	25.00	Replace	✓ CR4.SN
One Time Key In	Main			EMBLEM ASSY FRONT	1	87.10	87.10	0.00	87.10	Replace	1	87.10	Replace	✓ MIS.SN
Total Spare Part Cost									17,826.75	Surveyor Total		4,714.80		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									17,826.75	Final Sur Total		4,714.80		

997.80

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation								Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Check	*X SVC
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	* / NEC
One Time Key In	Main			RETAINER, FR BUMPER, LH & RH	2	4.25	8.50	25.00	6.38	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.07	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			COVER ASSY, ENGINE UNDER CENTER SET	1	452.80	452.80	25.00	339.60	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			COVER, ENGINE UNDER CENTER	1	94.50	94.50	25.00	70.88	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	0	0	Check	*X SVC
One Time Key In	Main			UNIT, HEADLAMP, LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			UNIT, HEADLAMP, RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303.01	Replace	* / CRA 10%
One Time Key In	Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	0	0	Check	*X SVC
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	0	0	Check	*X SVC
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0	Check	*X SVC
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Not Give	*X SVC
One Time Key In	Main			EXTENSION SUB-ASSY, LH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	*X SVC

9067.40

Total Spare Part Cost	17,826.75	Surveyor Total	4,714.80
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	17,826.75	Final Sur Total	4,714.80

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantify	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			EXTENSION SUB-ASSY, RH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	*XSVU
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	0	0	Check	*XSVU
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	0	0	Check	*XSVU
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	1	239.10	Replace	* / BT
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	* / CRU.
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	11.00	25.00	8.25	Replace	0	0	Check	*XSVU
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 1	2	3.80	3.80	25.00	2.85	Replace	1	2.85	Replace	* / Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	3.80	25.00	2.85	Replace	1	2.85	Replace	* / Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	2	3.80	3.80	25.00	2.85	Replace	1	2.85	Replace	* / Nec
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Not Give	*XSVU
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give	*XSVU
One Time Key In	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check	*XSVU
One Time Key In	Main			SEAL, RR BUMPER, LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Check	*XSVU
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	* / Nec

164650

Total Spare Part Cost	17,826.75	Surveyor Total	4,714.80
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	17,826.75	Final Sur Total	4,714.80

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation					Surveyor Approval			
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.38	558.38	25.00	418.72	Replace	1	418.72	Replace	/ CRU
One Time Key In	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Give	X SVC
One Time Key In	Main			FILLER, RR BUMPER, LH	1	119.90	119.90	25.00	89.93	Replace	1	89.93	Replace	/ CRU
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace	/ MIS
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, RH	1	406.80	406.80	10.00	438.12	Replace	0	0	Check	X SVC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	/ NE SU
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	/ SU CRU
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Check	X SVC
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	1	175.73	Replace	/ CRU
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	1	166.95	Replace	/ CRU
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Check	X SVC
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0	Check	X SVC
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	438.10	438.10	10.00	394.29	Replace	0	0	Check	X SVC
One Time Key In	Main			SPARE TYRE PANEL, PAN, REAR FLOOR	1	564.80	564.80	25.00	423.60	Replace	0	0	Check	X SVC

3019-10

Total Spare Part Cost	17,826.75	Surveyor Total	4,714.80
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	17,826.75	Final Sur Total	4,714.80

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	1	279.20	279.20	25.00	209.40	Replace	0	0	Check	* X SVC
One Time Key In	Main			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	1	279.20	279.20	25.00	209.40	Replace	0	0	Check	* X SVC
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0	Repair	* X R.
One Time Key In	Main			TAILGATE TRIM , UPPER	1	50.50	50.50	25.00	37.88	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			TAILGATE TRIM , RH	1	92.10	92.10	25.00	69.07	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			TAILGATE TRIM , LH	1	92.10	92.10	25.00	69.07	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			TAILGATE TRIM , LOWER	1	218.50	218.50	25.00	163.88	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			TAILGATE BOARD ASSY	1	251.50	251.50	25.00	188.63	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	452.10	25.00	339.08	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			TAIL GATE LOCK COVER , BACK DOOR	1	25.30	25.30	25.00	18.98	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	24.90	25.00	18.67	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			EMBLEM SUB-ASSY REAR	1	46.30	46.30	25.00	34.72	Replace	1	34.73	Replace	* / N/A
One Time Key In	Main			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.23	Replace	* / N/A
One Time Key In	Main			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.23	Replace	* / N/A

2807.50

Total Spare Part Cost	17,826.75	Surveyor Total	4,714.80
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	17,826.75	Final Sur Total	4,714.80

BOM Type	Coating Type	Portion	SMRT Recommendation							Surveyor Approval				
			Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	• NEC SN
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	• Nec SN
One Time Key In	Main			PIPE ASSY, EXHAUST, TAIL	1	1,173.90	1,173.90	25.00	880.43	Replace	0	0	Not Give	• XSVR
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	1	0	Repair	• X R
One Time Key In	Main			HINGE ASSY, HOOD, RH	1	57.00	57.00	25.00	42.75	Replace	0	0	Check	• XSVR
One Time Key In	Main			HINGE ASSY, HOOD, LH	1	57.00	57.00	25.00	42.75	Replace	0	0	Check	• XSVR
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,322.10	1,322.10	25.00	991.58	Replace	0	0	Not Give	• XSVR
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	0.00	Replace	• Nec. SN
<p>3614.80</p> <p>Total Spare Part Cost 17,825.75</p>										<p>Surveyor Total 4,714.80</p>				
<p>Lump Sum Discount (%) 0.00</p>										<p>Lump Sum Dis (%) 0</p>				
<p>Final Spare Part Cost 17,826.75</p>										<p>Final Sur Total 4,714.80</p>				

Labour's Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	338.00	200	✓
2	Main	TO REPAIR REAR PORTION	507.00	300	✓
Total:			845.00 1505	500.00 400	

Spray Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	✓
Total:			378.00 3334	780.00 1080	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0	
3	Main	TO RESPRAY REAR BUMPER	378.00	200	✓
4	Main	TO RESPRAY BUMPER BEAM	180.00	0	
5	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	80	✓
6	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
7	Main	TO RESPRAY REAR PANEL	180.00	0	
8	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	✓
9	Main	TO RESPRAY RH RAIL ROOF SIDE	180.00	0	
10	Main	TO RESPRAY LH RAIL ROOF SIDE	180.00	0	
11	Main	TO REPSRAY FRONT HOOD	378.00	200	✓
12	Main	TO RESPRAY SPOILER	180.00	0	
Total:			2,754.00	780.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	✓
2	Main	TO REPLACE SUNDRY PARTS	100.00	20	✓
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	✓
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	✓
5	Main	TO WASH AND VACUUM	60.00	0	
Total:			460.00	90.00	

30672-70

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	17,826.75	4,714.80

Estimator Assessment(\$)

Surveyor Assessment(\$)

Total Labour Cost

845.00

600.00

Total Spray Painting

2,754.00

780.00

Other

460.00

90.00

Overall Total

21,885.75

6,084.80

Lump Sum Repair Option

Lump Sum Total

0.00

6,084.80

Surveyor Approved Amount

6,084.80

No of Repair Days*

7

6

5 days

Remarks

-

P/P Repair, before paint photo.

Surveyor Name

Sun Pin (LKK)

Signature

Save Clear

Survey Date

20/01/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Red party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLEMENTARY PARTS

Contractor:			
Accident Case Number	TAX 01/20/2013	Date of Collection	1 / 1
Vehicle No	SND 6457 K	Date of Request	22 10/1/2020
Vehicle Model	TOYOTA PRIUS 4	Number of Days to Extend (If any)	31 day

S/N	Part Number	Part Description	Quantity	Unit Price	
		BRACKET, FRONT BUMPER (NUMBER PART 6-AR(AUSH))	1pc		CR4
		GRILLE SUB ASSY	1pc		CRU
		REINFORCEMENT FRONT UPPER	1pc		BT
		ABSORBER, FRONT BUMPER	1pc		CR4
		SEAL, REAR BUMPER RH	1pc		CR4
		ANTENNA, ELECTRICAL KEY	1pc		ERA

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
Signature of person making this declaration
(to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

REQUEST FOR SUPPLEMENTARY PARTS

Contractor:		Date of Collection:	1 / 1
Accident Case Number:	TAX 01/30/2013	Date of Request:	22/10/2020
Vehicle No:	SND 6457 K	Number of Days to Be Had (If any):	31 days
Vehicle Model:	TOYOTA PRIUS 4		

S/N	Part Number	Part Description	Quantity	Unit Price	
		LENS & BODY, REAR COMBINATION LAMP RH	1pc		CRA
		PIPE ASSY, EXHAUST TAIL	1pc		BT
		TAILGATE WEATHERSTRIP	1pc		CT
	LABOUR	TO REPAIR REAR END PANEL		\$ 300	200
	LABOR	TO SPRAY REAR END PANEL		\$ 180	100
	LABOR	TO REPAIR ROOF PANEL SIDE LH		\$ 180	100

««Please submit photographs for damaged parts»»

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

RESERVED FOR SUPPLEMENTARY PARTS

Contractor:		Date of Collection:	1 / 1
Accident Case Number:	TAX 01/20/2013	Date of Request:	22/10/2020
Vehicle No:	SND 6457 K	Number of Days to Bring (If any):	31
Vehicle Model:	TOYOTA PRIUS 4		

S/N	Part Number	Part Description	Quantity	Unit Price
	LABOR TO	REPAIR ROOF PANEL SIDE RH		\$ 180
	LABOR TO	SPRAY ROOF PANEL SIDE LH		\$ 200
	LABOR TO	SPRAY ROOF PANEL SIDE RH		\$ 200

Please submit photographs for damaged parts

I, (Name) _____
 (Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
 Signature of person making this declaration
 [to be signed in front of an authorized witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

PG 3/3



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 81 Woodlands Industrial Park EA, Singapore
 FAX Number : 63420322
 Estimator Telephone Number : 69492923
 Accident Reporting Number : 6862272

Date Generated : 17/02/2020
 User ID : Pehhuan

Section A - Accident Details

Registration Number	SHD6457K
Case Reference Number	TAX/01/20/2073
Registration Date	1/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	WONG YOON MENG
Type of Accident	Head to Rear
Accident Date and Time	17/1/2020 3:05 PM
Accident Reported Date and Time	17/1/2020 4:29 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24105360
Special Instruction to ARC, if any	FRONT AND REAR PORTION DAMAGE
Prepared Date and Time	18/1/2020 12:22 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,505.00	\$900.00
Total Spray Cost	\$3,334.00	\$1,080.00
Total Spare Part Cost	\$20,395.71	\$7,320.83
Total Other Cost	\$460.00	\$90.00
TOTAL COST	\$25,694.71	\$9,390.83 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	6.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	23/01/2020 4:03 PM	23/01/2020 3:15 PM
Signature		
Remarks	Initial estimate = 7 days SUP = 1 days	P/P Repair, before paint photo.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 35 Woodlands Industrial Park East, Singapore
 FAX Number: 63683332
 Estimator Telephone Number: 68628233
 Accident Reporting Number: 68626272

Date Generated: 17/02/2020
 User ID: P01828

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-2002-0309	Invoice Number	
Quotation Date	15.02.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPLACE REAR END PANEL	\$300.00	\$200.00
TO REPAIR PANEL SIDE ROOF LH	\$180.00	\$100.00
TO REPAIR ROOF PANEL <i>RM</i>	\$180.00	\$100.00
TO REPAIR FRONT PORTION	\$338.00	\$200.00
TO REPAIR REAR PORTION	\$507.00	\$300.00
Total Labour	\$1,505.00	\$900.00

supp
supp
supp

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY PANEL SIDE ROOF LH	\$200.00	\$100.00
TO RESPRAY PANEL SIDE ROOF RH	\$200.00	\$100.00
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$80.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY RH RAIL ROOF SIDE	\$180.00	\$0.00
TO RESPRAY LH RAIL ROOF SIDE	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY SPOILER	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$3,334.00	\$1,080.00

supp
~~*supp*~~
supp

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$460.00	\$90.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 82	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace
		52115470 50	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Check

X

52116470 50	SUPPORT, FR BUMPER LH	0.00	\$62.30	0.00	\$0.00	Replace	Check	X
52127479 07	COVER, FR BUMPER RH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given	X
52128479 06	COVER, FR BUMPER LH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given	X
52114471 90	BRACKET, FR BUMPER	0.00	\$99.80	0.00	\$0.00	Replace	Check	X
	NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace	✓
	NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace	✓
75310470 60	EMBLEM ASSY FRONT	1.00	\$87.10	0.00	\$87.10	Replace	Replace	✓
53112472 40	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Check	X
	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	✓
52535500 60	RETAINER, FR BUMPER, LH & RH	0.00	\$8.50	0.00	\$0.00	Replace	Not Given	X
51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Not Given	X
51410470 20	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$452.80	0.00	\$0.00	Replace	Not Given	X
51447470 30	COVER, ENGINE UNDER CENTER	0.00	\$94.50	0.00	\$0.00	Replace	Not Given	X
53101470 80	GRILLE SUB-ASSY	0.00	\$335.60	0.00	\$0.00	Replace	Check	Y
81185478 91	UNIT, HEADLAMP, LH	0.00	\$2,558.90	0.00	\$0.00	Replace	Not Given	X
81145478 91	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	✓
81210470 20	LAMP ASSY, FOG, RH	0.00	\$910.20	0.00	\$0.00	Replace	Check	X
81220470 20	LAMP ASSY, FOG, LH	0.00	\$910.20	0.00	\$0.00	Replace	Check	X
52021471 10	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Check	X
52611471 40	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Not Given	X
52103470 10	EXTENSION SUB-ASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Check	Y
52102470 20	EXTENSION SUB-ASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Check	Y
52132470 10	REINFORCEMENT FRONT LOWER	0.00	\$236.50	0.00	\$0.00	Replace	Check	X
52618470 90	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Check	X
52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace	✓
52158478 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace	✓
52191470 30	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Check	X
52462470 30	PAD, RR BUMPER, RH & LH_1	1.00	\$3.80	25.00	\$2.85	Replace	Replace	✓
52462470 20	PAD, RR BUMPER, RH & LH_2	1.00	\$3.80	25.00	\$2.85	Replace	Replace	✓
52462470 10	PAD, RR BUMPER, RH & LH_3	1.00	\$3.80	25.00	\$2.85	Replace	Replace	✓
52575470 40	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given	X
52576470 40	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given	X
52591470 60	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Check	X
52592470 40	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Check	X
52161180 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	✓
52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$416.73	Replace	Replace	✓
52565479 00	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	Y
52566479 00	FILLER, RR BUMPER, LH	1.00	\$119.90	25.00	\$89.93	Replace	Replace	✓
52169470 20	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace	✓
81581470 10	LENS & BODY ASSY, RR BUMPER, RH	0.00	\$486.80	0.00	\$0.00	Replace	Check	X
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓
	SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	✓
58398470 80	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Check	X
58398470 30	COVER, REAR FLOOR UNDER, LH	1.00	\$234.30	25.00	\$175.73	Replace	Replace	✓
66259470 10	COVER, REAR FLOOR UNDER CENTER	1.00	\$222.60	25.00	\$166.95	Replace	Replace	✓



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 30 Woodlands Industrial Park St, Singapore
 Toll Number : 80009322
 Estimate Telephone Number : 80009323
 Accident Reporting Number : 8860307

Date Generated : 17/02/2020
 User ID : Pothusan

58307470 90	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Check	X
89997301 90	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Check	X
81551472 81	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$438.10	0.00	\$0.00	Replace	Check	X
58311471 30	SPARE TYRE PANEL, PAN, REAR FLOOR	0.00	\$564.80	0.00	\$0.00	Replace	Check	X
61017470 10	MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	0.00	\$279.20	0.00	\$0.00	Replace	Check	X
61018470 10	MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	0.00	\$279.20	0.00	\$0.00	Replace	Check	X
76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	100.00	\$0.00	Replace	Repair	K
64790470 80C0	TAILGATE TRIM, UPPER	0.00	\$50.50	0.00	\$0.00	Replace	Not Given	X
67937470 80C0	TAILGATE TRIM, RH	0.00	\$92.10	0.00	\$0.00	Replace	Not Given	X
67938470 80C0	TAILGATE TRIM, LH	0.00	\$92.10	0.00	\$0.00	Replace	Not Given	Y
67751471 10C0	TAILGATE TRIM, LOWER	0.00	\$218.50	0.00	\$0.00	Replace	Not Given	X
67750470 80C0	TAILGATE BOARD ASSY	0.00	\$251.50	0.00	\$0.00	Replace	Not Given	Y
69350470 50	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$452.10	0.00	\$0.00	Replace	Not Given	X
69321470 10	TAIL GATE LOCK COVER BACK DOOR	0.00	\$25.30	0.00	\$0.00	Replace	Not Given	X
89430520 50	TAIL GATE STRIKER ASSY, BACK DOOR	0.00	\$24.90	0.00	\$0.00	Replace	Not Given	Y
75403480 10	EMBLEM SUB-ASSY REAR	1.00	\$46.30	25.00	\$34.73	Replace	Replace	/
75441470 90	NAME PLATE (HYBRID), LUGGAGE	1.00	\$52.30	25.00	\$39.23	Replace	Replace	/
75442471 30	NAME PLATE (PRIUS), LUGGAGE	1.00	\$52.30	25.00	\$39.23	Replace	Replace	/
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	/
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	/
17430377 30	PIPE ASSY, EXHAUST, TAIL	0.00	\$1,173.90	0.00	\$0.00	Replace	Not Given	X
53301471 10	HOOD SUB-ASSY	1.00	\$938.40	100.00	\$0.00	Replace	Repair	K
53410471 30	HINGE ASSY, HOOD, RH	0.00	\$57.00	0.00	\$0.00	Replace	Check	X
53420471 30	HINGE ASSY, HOOD, LH	0.00	\$57.00	0.00	\$0.00	Replace	Check	X
76085479 16	SPOILER SUB-ASSY, REAR	0.00	\$1,322.10	0.00	\$0.00	Replace	Not Given	X
	SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace	/
Total			\$21,926.10		\$4,751.85			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52114-47140	BRACKET, FR BUMPER	1.00	\$110.40	25.00	\$82.80	Replace	Replace
		53101470 80	GRILLE SUB-ASSY	1.00	\$335.80	25.00	\$251.70	Replace	Replace
		52021471 10	REINFORCEMENT FRONT UPPER	1.00	\$891.10	25.00	\$518.33	Replace	Replace
		52611471 40	ABSORBER, FR BUMPER	1.00	\$70.30	25.00	\$52.73	Replace	Replace
		52561470 50	SEAL, RR BUMPER, RH	1.00	\$85.20	25.00	\$63.90	Replace	Replace
		89997301 00	ANTENNA, ELECTRICAL KEY	1.00	\$60.30	10.00	\$54.27	Replace	Replace
		81551472 81	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$438.10	10.00	\$394.29	Replace	Replace
		17430377 30	PIPE ASSY, EXHAUST, TAIL	1.00	\$1,173.90	25.00	\$880.43	Replace	Replace
		67881470 50	TAIL GATE WEATHERSTRIP, BACK	1.00	\$380.70	25.00	\$270.53	Replace	Replace
Total					3,325.60		2,568.98		

CR4
 CR4
 BT
 CR4
 CR4
 CRA 10%
 CRA 10%
 BT
 CMT

7320.83 /
 + 900.00 /
 + 1170.00 /
 9390.83 /

6 days



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20001289/Qyd3e2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 09-03-2020
Code: INC4	



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMF 2343L	Veh. Inspected	SHD 6457K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1080940-003	Excess (\$)	0.00
Assign From		Assign Date	20/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU703573412	Colour	MAROON
Odometer	291282	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	17/01/2020	Inspection Date	20/01/2020
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6457K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, FR BUMPER (DISC 25%)	CRUMPLED	495.50	371.63
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	REAR BUMPER REINFORCEMENT (DISC 25%)	BENT	318.80	239.10
1	COVER, RR BUMPER ASSY (DISC 25%)	CRUMPLED	423.90	317.93
2	PAD, RR BUMPER, RH & LH, 1 (DISC 25%)	NECESSARY	3.80	2.85
2	PAD, RR BUMPER, RH & LH, 2 (DISC 25%)	NECESSARY	3.80	2.85
2	PAD, RR BUMPER, RH & LH, 3 (DISC 25%)	NECESSARY	3.80	2.85
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	GUARD, RR BUMPER, LOWER (DISC 25%)	CRUMPLED	558.30	418.73
1	FILLER, RR BUMPER, LH (DISC 25%)	CUT	119.90	89.93
1	COVER, GUARD RR BUMPER LOWER (DISC 25%)	MISSING	14.80	11.10
1	COVER, REAR FLOOR UNDER, LH (DISC 25%)	CRUMPLED	234.30	175.73
1	COVER, REAR FLOOR UNDER CENTER (DISC 25%)	CUT	222.60	166.95
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.73
1	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.23
1	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.23
1	BRACKET, FR BUMPER (DISC 25%)	CRUMPLED	110.40	82.80
1	GRILLE SUB-ASSY (DISC 25%)	CRUMPLED	335.60	251.70
1	REINFORCEMENT FRONT UPPER (DISC 25%)	BENT	691.10	518.33
1	ABSORBER, FR BUMPER (DISC 25%)	CRUMPLED	70.30	52.73
1	SEAL, RR BUMPER, RH (DISC 25%)	CRUMPLED	85.20	63.90
1	PIPE ASSY, EXHAUST, TAIL (DISC 25%)	BENT	1,173.90	880.43
1	TAIL GATE WEATHERSTRIP, BACK (DISC 25%)	CUT	360.70	270.53
1	UNIT, HEADLAMP, RH (DISC 10%)	CRACKED	2,558.90	2,303.01
1	ANTENNA, ELECTRICAL KEY (DISC 10%)	CRACKED	60.30	54.27
1	LENS & BODY, REAR COMBINATION LAMP, RH (DISC 10%)	CRACKED	438.10	394.29
1	NUMBER PLATE (SN)	CRUMPLED	35.00	35.00
1	NUMBER PLATE FRAME (SN)	CRUMPLED	25.00	25.00

Report Ref No. NS/INC20001289/Qyd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 8315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EMBLEM ASSY FRONT (SN)	MISSING	87.10	87.10
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	CRUMPLED	180.00	180.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SEALANT SIKAFLEX (SN)	NECESSARY	37.00	37.00
1	SUPPORT, FR BUMPER RH	SERVICEABLE	76.90	-
1	SUPPORT, FR BUMPER LH	SERVICEABLE	82.30	-
1	COVER, FR BUMPER RH	SERVICEABLE	28.10	-
1	COVER, FR BUMPER LH	SERVICEABLE	28.10	-
1	BRACKET, FR BUMPER	SERVICEABLE	99.80	-
1	GRILLE, RADIATOR	SERVICEABLE	165.00	-
2	RETAINER, FR BUMPER, LH & RH	SERVICEABLE	8.50	-
1	COVER ASSY, ENGINE	SERVICEABLE	180.10	-
1	SET COVER ASSY, ENGINE UNDER CENTER	SERVICEABLE	452.80	-
1	COVER, ENGINE UNDER CENTER	SERVICEABLE	94.50	-
1	GRILLE SUB-ASSY	SERVICEABLE	335.60	-
1	UNIT, HEADLAMP, LH	SERVICEABLE	2,558.90	-
1	LAMP ASSY, FOG, RH	SERVICEABLE	910.20	-
1	LAMP ASSY, FOG, LH	SERVICEABLE	910.20	-
1	REINFORCEMENT FRONT UPPER	SERVICEABLE	691.10	-
1	ABSORBER, FR BUMPER	SERVICEABLE	70.30	-
1	EXTENSION SUB-ASSY, LH	SERVICEABLE	116.30	-
1	EXTENSION SUB-ASSY, RH	SERVICEABLE	116.30	-
1	REINFORCEMENT FRONT LOWER	SERVICEABLE	238.50	-
1	ABSORBER, FR BUMPER LOWER	SERVICEABLE	117.00	-
2	SEAL, RR BUMPER ARM, RH & LH	SERVICEABLE	11.00	-
1	RETAINER, RR BUMPER, RH	SERVICEABLE	112.70	-
1	RETAINER, RR BUMPER, LH	SERVICEABLE	111.50	-
1	SEAL, RR BUMPER, RH	SERVICEABLE	85.20	-
1	SEAL, RR BUMPER, LH	SERVICEABLE	85.20	-
1	FILLER, RR BUMPER, RH	SERVICEABLE	119.90	-
1	LENS & BODY ASSY, RR BUMPER, RH	SERVICEABLE	486.80	-

Report Ref No. NS/INC20001289/Qyd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	COVER, REAR FLOOR UNDER, RH	SERVICEABLE	169.50	-
1	END PANEL SUB-ASSY, BODY LOWER BACK	SERVICEABLE	629.80	-
1	ANTENNA, ELECTRICAL KEY	SERVICEABLE	60.30	-
1	LENS & BODY, REAR COMBINATION LAMP, RH	SERVICEABLE	438.10	-
1	SPARE TYRE PANEL, PAN, REAR FLOOR	SERVICEABLE	564.80	-
1	MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	SERVICEABLE	279.20	-
1	MEMBER SUB-ASSY, RAIL BOOT SIDE REAR LH	SERVICEABLE	279.20	-
1	TAILGATE TRIM, UPPER	SERVICEABLE	50.50	-
1	TAILGATE TRIM, RH	SERVICEABLE	92.10	-
1	TAILGATE TRIM, LH	SERVICEABLE	92.10	-
1	TAILGATE TRIM, LOWER	SERVICEABLE	218.50	-
1	TAILGATE BOARD ASSY	SERVICEABLE	251.50	-
1	TAIL GATE LOCK ASSY, BACK DOOR	SERVICEABLE	452.10	-
1	TAIL GATE LOCK COVER, BACK DOOR	SERVICEABLE	25.30	-
1	TAIL GATE STRIKER ASSY, BACK DOOR	SERVICEABLE	24.90	-
1	PIPE ASSY, EXHAUST, TAIL	SERVICEABLE	1,173.90	-
1	HINGE ASSY, HOOD, RH	SERVICEABLE	57.00	-
1	HINGE ASSY, HOOD, LH	SERVICEABLE	57.00	-
1	SPOILER SUB-ASSY, REAR	SERVICEABLE	1,322.10	-
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	TO REPAIR SEE LABOUR	891.20	-
1	HOOD SUB-ASSY	TO REPAIR SEE LABOUR	938.40	-
			25,338.70	7,320.83
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY AND HOOD SUB-ASSY.		1,505.00	900.00
	SPRAY PAINT.		3,334.00	1,080.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	30.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00

Report Ref No. NS/INC20001289/Qyd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			5,299.00	2,070.00
GRAND TOTAL			30,637.70	9,390.83
RECOMMENDED COST OF REPAIRS (CONFIRMED)				9,390.83

Report Ref No. NS/INC20001289/Qyd3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.