

SERVICE ESTIMATE

- C00001

SL: SERVICE SALES - PC

Ms Lee Ngee Lin
68 Jalan Mata Ayer
#05-18

Singapore 757487

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 20/01/2020

WIP No. . : 59962

Veh.In/Out:

*Tel.No. . : Mobile: 96882291

Reg.No. . : SKF6600S

Reg.date . : 16/04/2019

Mileage . : 0

Chassis No: 3PCMANJ55Z0551218

Closed by : Patricia Kueh Anak S

Svc Consultant :

Remarks : Ms Lee Ngee Lin

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER	0	1800.00	0		1,800.00	S
800	TO PUTTY SPRAYPAINT ON	0	1600.00	0		1,600.00	S
REAR BUMPER							
280	TO CHECK WIRING INCLUDE	0	405.00	0		405.00	S
RESETTING OF ALL ELECTRICAL MODULES							
	BUMPER SET-RR	1.0 EA	942.30			942.30	S
	REINF-BUMPER RR	1.0 EA	672.40			672.40	S
	FASCIA-REAR BUMPER,L	1.0 EA	628.10			628.10	S
	BRKT-RR BUMPER	1.0 EA	57.70			57.70	S

Gross Total. 6,105.50

Labour Total 3,805.00
Parts Total 2,300.50
Package Total 0.00

Net..... 6,105.50
GST @ 7.0% 427.39
Total..... 6,532.90
Paid..... 0.00
Please Pay.. 6,532.90

GST: S=StdRated; O=OutOfScope; Z=ZeroRated