

Sun Pin.

NTUC. NS/IN/ 20001294/94f3e2

## ASSIGNMENT

Form: Date: 21/01/2020

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SHC 45742

at Workshop n/s SMRT

of woodlands Depot

Insured: SKF 2065M

Policy No: 5107706888 (21/02/2019 - 07/05/2020)

Claims No: MT/1080907-002

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
| X   | X   |

Bal. or Market Value:

IDAC Accident Report: Consistent? - Yes or No

GIA / PR Soon: Consistent? - Yes or No

Est. Repairs: days Res.: Yes or No

Turn Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS<sup>up</sup>

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SHC 45742 Yr Regn: 10/09/2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

Truck / Trailer or

Make: Toyota Prius. C.C. 1790

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 552725 T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: JTDKN364X05748859

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wat luke.

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 19/01/2020 D.O.I. 21/01/2020

Survey held at SMRT

Des. of Damages: Frt / Rear / O/S (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                                  |
|-------------|-------------------------------------------------------|
|             | SHC 45742 - NA / 16/12/2019/14/11/11 DAB - 16/11/2011 |
|             | SKF 2065M - X                                         |
|             | Sun Pin,                                              |
|             | Pls see me.                                           |
|             | RECEIVED 05 MAR 2020                                  |
|             | Confirm with Poh Juan                                 |
|             | Finalize \$2,050 @ 4 days (L/S) (Red \$6562=62, 76%)  |

Date/Time, File Path to?

☐: Prel. Report

Days Of Repair: 4

11

☐: Final Report

Resurvey No. of Trip: 2

Date/Time, File Path to?

Survey Fee:

5/3/20 Typist

Add Fee: ☐: Site Insp 15

Transportation:

☐: Interview 15

S + FS 34

☐: Tech. Insp 15

Fines:

☐: (Total) 45

Other:

Report Format:

1 (mg 2m) / L/S: \$2050/-

TOTAL

160

eBaoTech

General Claim

Hello, RAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident   
Vehicle No. (For Motor)  Certificate Number

| Select                           | Policy No. | Certificate Number | Policyholder Name   | Policyholder NRIC | Product | Cover Type    | Vehicle No. | Insured Object | Commence Date | Expiry Date |
|----------------------------------|------------|--------------------|---------------------|-------------------|---------|---------------|-------------|----------------|---------------|-------------|
| <input checked="" type="radio"/> | S107706688 |                    | SULAIMAN BIN SALLEH | S1313566Z         | GPC     | drive CLASSIC | SKF2065M    | SKF2065M       | 22/02/2019    | 07/05/2020  |

TP Claims against NTUC Income: Follow-Through Survey

Date : 05/03/2020

| S/No | Income Reference | Claimant (Owner / Taxi Company) | Claimant Vehicle No. | Income Vehicle No. | Date of Accident | Time of Accident | Estimate     |
|------|------------------|---------------------------------|----------------------|--------------------|------------------|------------------|--------------|
| 1    | MT/1080940-003   | SMRT                            | SHD6457K             | SMF2343L           | 17/01/2020       | 15:05            | \$ 21,885.75 |
| 2    | MT/1080907-002   | SMRT                            | SHC4574Z             | SKF2065M           | 19/01/2020       | 18:20            | \$ 8,612.62  |
| 3    |                  |                                 |                      |                    |                  |                  |              |
| 4    |                  |                                 |                      |                    |                  |                  |              |
| 5    |                  |                                 |                      |                    |                  |                  |              |
| 6    |                  |                                 |                      |                    |                  |                  |              |
| 7    |                  |                                 |                      |                    |                  |                  |              |
| 8    |                  |                                 |                      |                    |                  |                  |              |

## Oi Sun Pin (LKK Auto)

---

**From:** Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>  
**Sent:** Thursday, 5 March, 2020 9:13 AM  
**To:** Oi Sun Pin (LKK Auto)  
**Cc:** SUR; CS A Team  
**Subject:** RE: SHC4574Z  
**Attachments:** img-305091636-0001.pdf

Hi,

Amount confirmed as per your recommendation, thanks.

Aside admin,

Please replace the attached estimate with the previous estimate, thanks.

Regards  
Poh Suan

-----Original Message-----

**From:** Oi Sun Pin (LKK Auto) [mailto:sunpin@lkkauto.com]  
**Sent:** Wednesday, 4 March 2020 6:17 PM  
**To:** Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)  
**Subject:** RE: SHC4574Z

Hi Poh Suan,

Confirm the finalize amount \$2,050. Repair day 4 days under lump sum repair.

Thank you.

Best Regards,  
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: [Sunpin@lkkauto.com](mailto:Sunpin@lkkauto.com) | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

**From:** Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]  
**Sent:** Tuesday, 25 February, 2020 2:18 PM  
**To:** Oi Sun Pin (LKK Auto)  
**Cc:** SUR; CS A Team  
**Subject:** FW: SHC4574Z

Hi Sun Pin,

FYA.

Thanks & Regards  
Poh Suan

-----Original Message-----

**From:** Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

## Oi Sun Pin (LKK Auto)

---

**From:** Oi Sun Pin (LKK Auto)  
**Sent:** Wednesday, 4 March, 2020 6:17 PM  
**To:** Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)  
**Subject:** RE: SHC4574Z

Hi Poh Suan,

Confirm the finalize amount \$2,050. Repair day 4 days under lump sum repair.

Thank you.

Best Regards,  
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: [Sunpin@lkkauto.com](mailto:Sunpin@lkkauto.com) | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [<mailto:YeoPohsuan@smrt.com.sg>]  
Sent: Tuesday, 25 February, 2020 2:18 PM  
To: Oi Sun Pin (LKK Auto)  
Cc: SUR; CS A Team  
Subject: FW: SHC4574Z

Hi Sun Pin,

FYA.

Thanks & Regards  
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)  
Sent: Tuesday, 18 February 2020 5:33 PM  
To: Oi Sun Pin (LKK Auto)  
Cc: SUR; CS A Team; Leong Chee kwong  
Subject: SHC4574Z

Hi Sun Pin,

Attached herewith the repair estimate of SHC 4574Z having Case No: TAX/01/20/2089.

There is no change to the approved amount of \$2,025 @ 4 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                             |
|----------------------------|---------------------------------------------|
| Date Of Report             | 20/01/2020 13:45                            |
| Date Of Accident           | 19/01/2020 18:20                            |
| Exact Location Of Accident | BEDOK NORTH AVE 3 JUNCTION BEDOK NORTH ST 2 |
| Country/State of Loss      | SINGAPORE                                   |

### DETAILS OF OWN VEHICLE

|                             |                    |
|-----------------------------|--------------------|
| Vehicle Registration Number | SHC4574Z           |
| <b>Insured/Policyholder</b> |                    |
| Name Of Registered Owner    | SMRT TAXIS PTE LTD |
| Co Reg No                   | 1XXXXX369K         |
| Email Address               | NOEMAIL            |
| Mobile Phone No             |                    |
| Alternative Phone No        | OFFICE-80000000    |

### Vehicle Particulars

|                                                                              |                    |
|------------------------------------------------------------------------------|--------------------|
| Manufacturer                                                                 | TOYOTA             |
| Model                                                                        | PRIUS TAXI-1.8 (A) |
| Exact Purpose for which vehicle was being used at time of accident           | HIRE AND REWARD    |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                 |
| If No, Please state action to be taken                                       | THIRD PARTY        |
| Vehicle Category                                                             | TAXI               |

### Insurance Company

|                           |                                |
|---------------------------|--------------------------------|
| Name of Insurance Company | MS FIRST CAPITAL INSURANCE LTD |
| Type Of Coverage          | THIRD PARTY FIRE AND/OR THEFT  |
| Fleet Policy              | YES                            |
| Policy Number             | D-19093197MFSH                 |
| Cover Note Number         |                                |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | GOMEZ AUGUSTIN        |
| NRIC No              | SXXXX927E             |
| Date Of Birth        | 02/08/1952            |
| Occupation           | OUTDOOR               |
| Date Of Driving Pass | 17/11/1971            |
| Driving Experience   | 48 YEARS AND 2 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-80000000  |
| Fax Number           |                       |
| Contact Number       |                       |
| Email Address        | NOEMAIL               |

PCL XL Error  
Subsystem:  
Error:  
Operator:  
Position:

I/O  
InputReadError  
LineRelPath  
63699

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                                                                                                                                                                                                                         |                                      |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|
| <b>Vehicle Owner Particulars</b>                                                                                                                                                                                        |                                      |
| Owner ID Type:                                                                                                                                                                                                          | Company                              |
| Owner ID:                                                                                                                                                                                                               | 369K                                 |
| <b>Vehicle Details</b>                                                                                                                                                                                                  |                                      |
| Vehicle No.:                                                                                                                                                                                                            | SHC4574Z                             |
| Vehicle to be Exported:                                                                                                                                                                                                 | No                                   |
| Intended Deregistration Date:                                                                                                                                                                                           | 22 Jan 2020                          |
| Vehicle Make:                                                                                                                                                                                                           | TOYOTA                               |
| Vehicle Model:                                                                                                                                                                                                          | PRIUS TAXI (SMRT)                    |
| Primary Colour:                                                                                                                                                                                                         | Maroon                               |
| Manufacturing Year:                                                                                                                                                                                                     | 2014                                 |
| Engine No.:                                                                                                                                                                                                             | 2ZR6132580                           |
| Chassis No.:                                                                                                                                                                                                            | JTDKN36UX05748859                    |
| Maximum Power Output:                                                                                                                                                                                                   | 100.0 kW (134 bhp)                   |
| Open Market Value:                                                                                                                                                                                                      | \$32,920.00                          |
| Original Registration Date:                                                                                                                                                                                             | 10 Sep 2014                          |
| First Registration Date:                                                                                                                                                                                                | 10 Sep 2014                          |
| Transfer Count:                                                                                                                                                                                                         | 0                                    |
| Actual ARF Paid:                                                                                                                                                                                                        | \$8,088.00                           |
| <b>Intended PARF Rebate Details</b>                                                                                                                                                                                     |                                      |
| PARF Eligibility:                                                                                                                                                                                                       | Yes                                  |
| PARF Eligibility Expiry Date:                                                                                                                                                                                           | 09 Sep 2022                          |
| PARF Rebate Amount:                                                                                                                                                                                                     | \$5,661.00                           |
| <b>Intended COE Rebate Details</b>                                                                                                                                                                                      |                                      |
| COE Expiry Date:                                                                                                                                                                                                        | 09 Sep 2022                          |
| COE Category:                                                                                                                                                                                                           | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):                                                                                                                                                                                                      | 8                                    |
| PQP Paid:                                                                                                                                                                                                               | \$50,704.00                          |
| COE Rebate Amount:                                                                                                                                                                                                      | \$16,684.00                          |
| <b>Total Rebate Amount:</b>                                                                                                                                                                                             | <b>\$22,345.00</b>                   |
| <b>Message</b>                                                                                                                                                                                                          |                                      |
| Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |                                      |

The information contained herein is correct as at 22 Jan 2020

OK



## Case Details

Case Reference Number :

TAX/01/20/2089

Type of Repair : Accident Repair

Vehicle Registration Number : SHC4574Z

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-10215-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 19/01/2020 10:20 AM

Vehicle Age(In Months) : 64

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

| SMRT Recommendation |              |         |                 |                               |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |            |
|---------------------|--------------|---------|-----------------|-------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|------------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                     | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks    |
| One Time Key In     | Main         |         |                 | BUMPER REAR                   | 1   | 458.60                  | 458.60         | 25.00  | 343.95          | Replace         | 1                 | 0                        | Repair         | *X R       |
| One Time Key In     | Main         |         |                 | BUMPER CLIPS                  | 10  | 2.10                    | 21.00          | 25.00  | 15.75           | Replace         | 0                 | 0                        | Not Give       | *X SVC     |
| One Time Key In     | Main         |         |                 | PIXEL STICKER                 | 2   | 60.00                   | 120.00         | 0.00   | 120.00          | Replace         | 2                 | 120.00                   | Replace        | * / Nec SN |
| One Time Key In     | Main         |         |                 | BUMPER REINFORCEMENT REAR     | 1   | 205.70                  | 205.70         | 25.00  | 154.27          | Replace         | 0                 | 0                        | Check          | *X SVC     |
| One Time Key In     | Main         |         |                 | ARM SUB-ASSY, RR BUMPER RH    | 1   | 139.60                  | 139.60         | 25.00  | 104.70          | Replace         | 0                 | 0                        | Check          | *X SVC     |
| One Time Key In     | Main         |         |                 | ARM SUB-ASSY, RR BUMPER LH    | 1   | 139.60                  | 139.60         | 25.00  | 104.70          | Replace         | 0                 | 0                        | Check          | *X SVC     |
| One Time Key In     | Main         |         |                 | ANTENNA,ELECTRICAL LOWER REAR | 1   | 157.40                  | 157.40         | 25.00  | 118.05          | Replace         | 0                 | 0                        | Not Give       | *X SVC     |
| One Time Key In     | Main         |         |                 | SENSOR REVERSE                | 1   | 180.00                  | 180.00         | 0.00   | 180.00          | Replace         | 0                 | 0                        | Not Give       | *X SVC     |
| One Time Key In     | Main         |         |                 | BUMPER SIDE RETAINER RR/LH    | 1   | 94.80                   | 94.80          | 25.00  | 71.10           | Replace         | 0                 | 0                        | Check          | *X SVC     |
| One Time Key In     | Main         |         |                 | BUMPER SIDE RETAINER RR/RH    | 1   | 94.80                   | 94.80          | 25.00  | 71.10           | Replace         | 0                 | 0                        | Not Give       | *X SVC     |

Total Spare Part Cost 6,256.78

Surveyor Total 855.07

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 5,005.42

Final Sur Total 684.06

| SMRT Recommendation |              |         |                 |                                |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |            |
|---------------------|--------------|---------|-----------------|--------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|------------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                      | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks    |
| One Time Key In     | Main         |         |                 | BUMPER SEAL, RR LH             | 1   | 88.90                   | 88.90          | 25.00  | 66.68           | Replace         | 0                 | 0                        | Check          | • X SVC    |
| One Time Key In     | Main         |         |                 | BUMPER SEAL, RR RH             | 1   | 65.70                   | 65.70          | 25.00  | 49.28           | Replace         | 0                 | 0                        | Not Give       | • X SVC    |
| One Time Key In     | Main         |         |                 | BUMPER LIP COVER RR/LH         | 1   | 72.20                   | 72.20          | 25.00  | 54.15           | Replace         | 0                 | 0                        | Not Give       | • X SVC    |
| One Time Key In     | Main         |         |                 | BUMPER LIP COVER RR/RH         | 1   | 118.10                  | 118.10         | 25.00  | 88.57           | Replace         | 0                 | 0                        | Not Give       | • X SVC    |
| One Time Key In     | Main         |         |                 | BUMPER LIP REAR                | 1   | 238.90                  | 228.90         | 25.00  | 171.68          | Replace         | 0                 | 0                        | Not Give       | • X SVC    |
| One Time Key In     | Main         |         |                 | UNDER COVER SUB-ASSY, RR FLOOR | 1   | 314.50                  | 314.50         | 25.00  | 235.88          | Replace         | 0                 | 0                        | Not Give       | • X SVC    |
| One Time Key In     | Main         |         |                 | UNDER COVER RR SHIELD          | 1   | 63.90                   | 63.90          | 25.00  | 47.92           | Replace         | 0                 | 0                        | Not Give       | • X SVC    |
| One Time Key In     | Main         |         |                 | DOOR RR/LH                     | 1   | 954.50                  | 954.50         | 25.00  | 715.88          | Replace         | 1                 | 0                        | Repair         | • X R      |
| One Time Key In     | Main         |         |                 | FENDER RR/LH                   | 1   | 766.80                  | 766.80         | 25.00  | 575.10          | Replace         | 1                 | 575.10                   | Replace        | • X / PD   |
| One Time Key In     | Main         |         |                 | SMRT LOGO                      | 1   | 7.80                    | 7.80           | 0.00   | 7.80            | Replace         | 1                 | 7.80                     | Replace        | • / Nec SN |
| One Time Key In     | Main         |         |                 | STICKER DECAL 65558888         | 1   | 21.60                   | 21.60          | 0.00   | 21.60           | Replace         | 1                 | 21.60                    | Replace        | • / Nec SN |
| One Time Key In     | Main         |         |                 | TAIL LAMP LH                   | 1   | 548.40                  | 548.40         | 10.00  | 493.56          | Replace         | 0                 | 0                        | Not Give       | • X SVC    |
| One Time Key In     | Main         |         |                 | TYRE                           | 1   | 126.74                  | 126.74         | 0.00   | 126.74          | Replace         | 0                 | 0                        | Not Give       | • X SVC    |
| One Time Key In     | Main         |         |                 | WHEEL DISC                     | 1   | 1,484.20                | 1,484.20       | 25.00  | 1,113.15        | Replace         | 1                 | 0                        | Repair         | • X R      |
| One Time Key In     | Main         |         |                 | WHEEL HUB REAR                 | 1   | 489.40                  | 489.40         | 25.00  | 367.05          | Replace         | 0                 | 0                        | Not Give       | • X SVC    |
| One Time Key In     | Main         |         |                 | CAP SUB-ASSY, WHEEL            | 1   | 174.10                  | 174.10         | 25.00  | 130.57          | Replace         | 1                 | 130.57                   | Replace        | • / SCH    |

Total Spare Part Cost 8,256.78

Surveyor Total 855.07

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 5,005.42

Final Sur Total 684.06

| SMRT Recommendation   |              |         |                 |                         |     |                         |                |        |                 | Surveyor Approval |                   |                          |                |         |
|-----------------------|--------------|---------|-----------------|-------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name               | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace   | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | MOULDING BODY, LH       | 1   | 673.60                  | 673.60         | 25.00  | 505.20          | Replace           | 0                 | 0                        | Not Give       | • XSVK  |
| One Time Key In       | Main         |         |                 | DOOR OUTER HANDLE RR/LH | 1   | 69.80                   | 69.80          | 25.00  | 52.35           | Replace           | 0                 | 0                        | Not Give       | • XSVK  |
| Total Spare Part Cost |              |         |                 |                         |     |                         |                |        | 6,256.78        | Surveyor Total    |                   | 855.07                   |                |         |
| Lump Sum Discount (%) |              |         |                 |                         |     |                         |                |        | 20.00           | Lump Sum Dis (%)  |                   | 20                       |                |         |
| Final Spare Part Cost |              |         |                 |                         |     |                         |                |        | 5,005.42        | Final Sur Total   |                   | 884.08                   |                |         |

#### Labour's Cost Detail

| S.No.  | Costing Type | Job Scope                 | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|---------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REPAIR LH REAR PORTION | 507.00                  | 400                     | /       |
| Total: |              |                           | 507.00                  | 400.00                  |         |

#### Spray Cost Detail

| S.No.  | Costing Type | Job Scope                        | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|----------------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO RESPRAY REAR BUMPER           | 378.00                  | 200                     | /       |
| 2      | Main         | TO RESPRAY BUMPER BEAM           | 180.00                  | 0                       |         |
| 3      | Main         | TO RESPRAY REAR FENDER LH        | 378.00                  | 200                     | /       |
| 4      | Main         | TO RESPRAY RIM                   | 180.00                  | 50                      | /       |
| 5      | Main         | TO RESPRAY REAR DOOR LH          | 378.00                  | 200                     | /       |
| 6      | Main         | TO RESPRAY ROCKER PANEL MOULDING | 180.00                  | 0                       |         |
| Total: |              |                                  | 1,674.00                | 650.00                  |         |

#### Other Cost Detail

| S.No.  | Costing Type | Job Scope                                       | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|-------------------------------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE) | 120.00                  | 30                      | /       |
| 2      | Main         | TO TEST AND REFIX REVERSE SENSOR SYSTEM         | 120.00                  | 0                       |         |
| 3      | Main         | TO REPLACE SUNDRY PARTS                         | 160.00                  | 20                      | /       |
| Total: |              |                                                 | 1,426.20                | 55.32                   |         |

| S.No. / Costing Type | Job Scope                                                   | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks              |
|----------------------|-------------------------------------------------------------|-------------------------|-------------------------|----------------------|
| 4 Main               | TO CHECK WIRING AND SYSTEM FUNCTION                         | 80.00                   | 0                       |                      |
| 5 Main               | TO WASH AND VACUUM                                          | 60.00                   | 0                       |                      |
| 6 Main               | TOWING CHARGE                                               | 84.00                   | 0                       |                      |
| 7 Main               | TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET) | 742.20                  | 445.32                  | 3pcs (L3-L4+R4) / nu |
| 8 Main               | TO DO WHEEL ALIGNMENT / TYRE BALANCING                      | 120.00                  | 60                      | /                    |
| Total:               |                                                             | 1,426.20                | 555.32                  |                      |

## Summary

|                          | Estimator Assessment(\$) | Surveyor Assessment(\$)                  |
|--------------------------|--------------------------|------------------------------------------|
| Total Spare Part Detail  | 5,005.41                 | 584.08                                   |
| Total Labour Cost        | 507.00                   | 400.00                                   |
| Total Spray Painting     | 1,574.00                 | 650.00                                   |
| Other                    | 1,426.20                 | 555.32                                   |
| Overall Total            | 8,612.62                 | 2,289.38                                 |
| Lump Sum Repair Option   |                          | ✓                                        |
| Lump Sum Total           | 8,600.00                 | 2,300.00                                 |
| Surveyor Approved Amount |                          | 2,300.00                                 |
| No of Repair Days*       | 5                        | 3 3 days                                 |
| Remarks                  | -                        | Lump Sum repair, Take after paint photo. |

Surveyor Name

Sun Pin (LKK)

Signature

6



17287-64

31/1/2020

Survey Date

21/01/2020

Save Clear

LKK Auto Consultants hence notify the Reparer of the following:

- The survey before after spray painting
- To identify damaged part(s) during resurvey
- Parts prices are subject to confirmation
- That body survey is on a "Without Prejudice" basis
- No repair modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

# REQUEST FOR SUPPLYMENT PARTS

| Contractor:          |                      | WEGA ENGINEERING PTE LTD          |             |            |
|----------------------|----------------------|-----------------------------------|-------------|------------|
| Accident Case Number | 7AX / 01 / 20 / 2089 | Date of Collection                | 23 / 1 / 20 |            |
| Vehicle No           | SHC 4574 Z           | Date of Request                   | 23 / 1 / 20 |            |
| Vehicle Model        | TOYOTA PRIUS         | Number of Days to Extend (If any) | 100% ✓      |            |
| S/N                  | Part Number          | Part Description                  | Quantity    | Unit Price |
|                      | 6450, 5152           | Bumper Side Retainer RR LH        | 1           | 94.80      |
|                      |                      | To Request One More working Day.  |             | 1 day      |
|                      |                      |                                   |             |            |
|                      |                      |                                   |             |            |
|                      |                      |                                   |             |            |
|                      |                      |                                   |             |            |
|                      |                      |                                   |             |            |
|                      |                      |                                   |             |            |
|                      |                      |                                   |             |            |

Please submit photographs for damaged parts

I, (Name) CHIA

(Position)

Do solemnly and sincerely declare that - Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration  
[To be signed in front of an authorised witness]


I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

|                 |                                                |                                           |
|-----------------|------------------------------------------------|-------------------------------------------|
| For SMRT Staff  |                                                |                                           |
| Acknowledge By  | ARC Executive / Supervisor / SA                |                                           |
| Approval By     | Surveyor / In-house Staff                      |                                           |
| Parts Ordering  | SMRT Store / Contractor Supply / Form 22 / WOC | Form 22 / PO / WOC / Reservation / Number |
| Photo Submitted | YES / NO                                       | Date of submission                        |

**Section A - Accident Details**

|                                    |                    |
|------------------------------------|--------------------|
| Registration Number                | SHC4574Z           |
| Case Reference Number              | TAX001/20/2089     |
| Registration Date                  | 10/9/2014          |
| Company Type                       | SMRT Taxis Pte Ltd |
| Make                               | TOYOTA             |
| Model                              | PRIUS              |
| Name of Driver                     | GOMEZ AUGUSTIN     |
| Type of Accident                   | Head To Side       |
| Accident Date and Time             | 19/1/2020 6:20 PM  |
| Accident Reported Date and Time    | 20/1/2020 1:46 PM  |
| Is Surveyor Required?              | Yes                |
| Survey by                          |                    |
| Vehicle is Towed Back?             | Yes                |
| Towed Back Date and Time           | 19/1/2020 10:04 PM |
| Replacement Vehicle issued?        | No                 |
| Job Card Number                    | 24105391           |
| Special Instruction to ARC, if any | TOWED \$60         |
| Prepared Date and Time             | 20/1/2020 7:04 PM  |
| Chassis Number                     |                    |
| Mileage                            |                    |
| Work Shop                          |                    |
| Repair Completion Date and Time    |                    |

**Section B - Summary of Repair Estimates**

| Summary of Repair Estimates  |                                                                                     |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable                                                 |
| Total Labour Cost            | \$507.00                                                                            | \$400.00                                                                            |
| Total Spray Cost             | \$1,674.00                                                                          | \$650.00                                                                            |
| Total Spare Part Cost        | \$6,327.88                                                                          | \$926.18                                                                            |
| Total Other Cost             | \$1,428.20                                                                          | \$73.82                                                                             |
| <b>TOTAL COST</b>            | <b>\$9,935.08</b>                                                                   | <b>\$2,050.00 (L/S)</b>                                                             |
| Lump Sum Total               | \$0.00                                                                              | \$0.00                                                                              |
| Number of Repair Days        | 8.0                                                                                 | 4.0                                                                                 |
| Prepared / Adjusted By       | Ang Bang Kien                                                                       | Sun Pin (LKK) / NTUC                                                                |
| ARC / Surveyor Sign Off Date | 30/01/2020 9:52 AM                                                                  | 30/01/2020 9:16 AM                                                                  |
| Signature                    |  |  |
| Remarks                      | Initial estimate = 5 days<br>SUP = 1 day                                            | Lump Sum repair, Take after paint photo.                                            |

## Section C - Quotation and Accident Invoice Details

|                  |              |                |  |
|------------------|--------------|----------------|--|
| Quotation Number | QN-2002-0350 | Invoice Number |  |
| Quotation Date   | 18.02.2020   | Invoice Date   |  |
| Invoice Amount   |              | Prepared Date  |  |

## Section D - Details of Repair Estimates

| Part 1 - Labour Works     |                   |                                     |
|---------------------------|-------------------|-------------------------------------|
| Job Scope                 | Quotation from AR | Adjusted by Surveyor, if applicable |
| TO REPAIR LH REAR PORTION | \$507.00          | \$400.00                            |
| Total Labour              | \$507.00          | \$400.00                            |

| Part 2 - Spray Painting & Panel Beating Related Works |                    |                                     |
|-------------------------------------------------------|--------------------|-------------------------------------|
| Job Scope                                             | Quotation from ARC | Adjusted by Surveyor, if applicable |
| TO RESPRAY REAR BUMPER                                | \$378.00           | \$200.00                            |
| TO RESPRAY BUMPER BEAM                                | \$180.00           | \$0.00                              |
| TO RESPRAY REAR FENDER LH                             | \$378.00           | \$200.00                            |
| TO RESPRAY RIM                                        | \$180.00           | \$50.00                             |
| TO REPSRAY REAR DOOR LH                               | \$378.00           | \$200.00                            |
| TO RESPRAY ROCKER PANEL MOULDING                      | \$180.00           | \$0.00                              |
| Total Spray Painting & Panel Beating                  | \$1,674.00         | \$650.00                            |

| Part 3 - Other Costs - Accident and Accident Repair Related Expense |                    |                                     |
|---------------------------------------------------------------------|--------------------|-------------------------------------|
| Job Scope                                                           | Quotation from ARC | Adjusted by Surveyor, if applicable |
| TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)                     | \$120.00           | \$30.00                             |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM                             | \$120.00           | \$0.00                              |
| TO REPLACE SUNDRY PARTS                                             | \$100.00           | \$20.00                             |
| TO CHECK WIRING AND SYSTEM FUNCTION                                 | \$80.00            | \$0.00                              |
| TO WASH AND VACUUM                                                  | \$60.00            | \$0.00                              |
| TOWING CHARGE                                                       | \$84.00            | \$0.00                              |
| TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)         | \$742.20           | \$445.32                            |
| TO DO WHEEL ALIGNMENT / TYRE BALANCING                              | \$120.00           | \$60.00                             |
| Lump Sum Adjustment by Surveyor                                     | \$0.00             | (\$481.50)                          |
| Total Other Costs                                                   | \$1,426.20         | \$73.82                             |

| Part 4 - Spare Parts / Material Usage |         |              |                               |          |                 |              |                  |                    |                   |
|---------------------------------------|---------|--------------|-------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
| Part Number                           | Portion | Stock Number | Part Name                     | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|                                       |         | 52159-47905  | BUMPER REAR                   | 1.00     | \$458.60        | 100.00       | \$0.00           | Replace            | Repair R          |
|                                       |         | 80467-07211  | BUMPER CLIPS                  | 0.00     | \$2.10          | 0.00         | \$0.00           | Replace            | Not Given Y       |
|                                       |         |              | PIXEL STICKER                 | 2.00     | \$60.00         | 0.00         | \$120.00         | Replace            | Replace ✓         |
|                                       |         | 52023-12240  | BUMPER REINFORCEMENT REAR     | 0.00     | \$205.70        | 0.00         | \$0.00           | Replace            | Check X           |
|                                       |         | 52015-47050  | ARM SUB-ASSY, RR BUMPER RH    | 0.00     | \$139.80        | 0.00         | \$0.00           | Replace            | Check Y           |
|                                       |         | 52016-47030  | ARM SUB-ASSY, RR BUMPER LH    | 0.00     | \$139.80        | 0.00         | \$0.00           | Replace            | Check Y           |
|                                       |         | 89997-30070  | ANTENNA ELECTRICAL LOWER REAR | 0.00     | \$157.40        | 0.00         | \$0.00           | Replace            | Not Given X       |

|       |             |                                |      |            |        |          |         |           |   |
|-------|-------------|--------------------------------|------|------------|--------|----------|---------|-----------|---|
|       |             | SENSOR REVERSE                 | 0.00 | \$180.00   | 0.00   | \$0.00   | Replace | Not Given | X |
|       | 52576-47020 | BUMPER SIDE RETAINER RR/LH     | 0.00 | \$94.80    | 0.00   | \$0.00   | Replace | Check     | X |
|       | 52575-47020 | BUMPER SIDE RETAINER RR/RH     | 0.00 | \$94.80    | 0.00   | \$0.00   | Replace | Not Given | X |
|       | 52592-47021 | BUMPER SEAL, RR LH             | 0.00 | \$88.90    | 0.00   | \$0.00   | Replace | Check     | X |
|       | 52591-47021 | BUMPER SEAL, RR RH             | 0.00 | \$65.70    | 0.00   | \$0.00   | Replace | Not Given | X |
|       | 76088-47020 | BUMPER LIP COVER RR/LH         | 0.00 | \$72.20    | 0.00   | \$0.00   | Replace | Not Given | X |
|       | 76087-47020 | BUMPER LIP COVER RR/RH         | 0.00 | \$118.10   | 0.00   | \$0.00   | Replace | Not Given | X |
|       | 76891-47020 | BUMPER LIP REAR                | 0.00 | \$228.90   | 0.00   | \$0.00   | Replace | Not Given | X |
|       | 58308-47011 | UNDER COVER SUB-ASSY, RR FLOOR | 0.00 | \$514.50   | 0.00   | \$0.00   | Replace | Not Given | X |
|       | 51442-12210 | UNDER COVER RR SHIELD          | 0.00 | \$63.90    | 0.00   | \$0.00   | Replace | Not Given | X |
|       | 67004-47080 | DOOR RR/LH                     | 1.00 | \$954.50   | 100.00 | \$0.00   | Replace | Repair    | R |
|       | 61602-47091 | FENDER RR/LH                   | 1.00 | \$766.80   | 25.00  | \$575.10 | Replace | Replace   | / |
|       |             | SMRT LOGO                      | 1.00 | \$7.80     | 0.00   | \$7.80   | Replace | Replace   | / |
|       |             | STICKER DECAL 65558888         | 1.00 | \$21.60    | 0.00   | \$21.60  | Replace | Replace   | / |
|       | 81561-47170 | TAIL LAMP LH                   | 0.00 | \$548.40   | 0.00   | \$0.00   | Replace | Not Given | X |
|       |             | TYRE                           | 0.00 | \$126.74   | 0.00   | \$0.00   | Replace | Not Given | X |
|       | 42611-47140 | WHEEL DISC                     | 1.00 | \$1,484.20 | 100.00 | \$0.00   | Replace | Repair    | R |
|       | 42450-47040 | WHEEL HUB REAR                 | 0.00 | \$489.40   | 0.00   | \$0.00   | Replace | Not Given | X |
|       | 42602-47060 | CAP SUB-ASSY, WHEEL            | 1.00 | \$174.10   | 25.00  | \$130.58 | Replace | Replace   | / |
|       | 75852-47900 | MOULDING BODY, LH              | 0.00 | \$673.60   | 0.00   | \$0.00   | Replace | Not Given | X |
|       | 69211-74020 | DOOR OUTER HANDLE RR/LH        | 0.00 | \$69.80    | 0.00   | \$0.00   | Replace | Not Given | X |
| Total |             |                                |      | \$8,001.74 |        | \$655.08 |         |           |   |

**Added Spare Parts / Material Usage After Surveyor Signed off**

| Part Number | Portion | Stock Number | Part Name                  | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|----------------------------|----------|---------------|--------------|------------------|-----------|----------------|
|             |         | 52576-47020  | BUMPER SIDE RETAINER RR/LH | 1.00     | \$94.80       | 25.00        | \$71.10          | Replace   | Replace        |
| Total       |         |              |                            |          | 94.80         |              | 71.10            |           |                |

CR4

926.18 /  
+ 400.00 /  
+ 1205.32 /

2531.50 /

- 20%

2025.20 /

4 days

4/5 \$2050 /-





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



|                                                                                                                                        |                                                                                      |                 |                  |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|-----------------|------------------|-------------------------------------------------------------------------------------|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20001294/Qyf3e2                                                                      |                                                                                      |                 |                  |                                                                                     |
| 73 BRAS BASAH ROAD<br>#05-01 NTUC TRADE UNION HOUSESINGAPORE<br>189556                                                                 |                                                                                      |                 | Date: 06-03-2020 |  |
| Code: INC4                                                                                                                             |                                                                                      |                 |                  |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                      |                 |                  |                                                                                     |
| Insured Veh.                                                                                                                           | SKF 2065M                                                                            | Veh. Inspected  | SHC 4574Z        |                                                                                     |
| Policy No.                                                                                                                             | 5107706888                                                                           | Coverage (\$)   | 0.00             |                                                                                     |
| Claim No.                                                                                                                              | MT/1080907-002                                                                       | Excess (\$)     | 0.00             |                                                                                     |
| Assign From                                                                                                                            |                                                                                      | Assign Date     | 21/01/2020       |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                      |                 |                  |                                                                                     |
| Make & Model                                                                                                                           | TOYOTA PRIUS                                                                         | c.c             | 1798             |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                               | Year of Reg.    | 2014             |                                                                                     |
| Chassis No.                                                                                                                            | JTDKN36UX05748859                                                                    | Colour          | MAROON           |                                                                                     |
| Odometer                                                                                                                               | 552725                                                                               | Steering        | IN ORDER         |                                                                                     |
| Brakes                                                                                                                                 | IN ORDER                                                                             | Modification    | SPORTS RIM       |                                                                                     |
| General                                                                                                                                | FAIR                                                                                 |                 |                  |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                      |                 |                  |                                                                                     |
|                                                                                                                                        | Size                                                                                 | Make            | Balance          |                                                                                     |
| R/H Front Tyre                                                                                                                         | 195/65 R15                                                                           | WEST LAKE       | 5 mm             |                                                                                     |
| L/H Front Tyre                                                                                                                         | 195/65 R15                                                                           | WEST LAKE       | 5 mm             |                                                                                     |
| R/H Rear Tyre                                                                                                                          | 195/65 R15                                                                           | WEST LAKE       | 5 mm             |                                                                                     |
| L/H Rear Tyre                                                                                                                          | 195/65 R15                                                                           | WEST LAKE       | 5 mm             |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                      |                 |                  |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.<br>DAMAGES SEE DETAILS.                                                                 |                                                                                      |                 |                  |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                      |                 |                  |                                                                                     |
| Accident Date                                                                                                                          | 19/01/2020                                                                           | Inspection Date | 21/01/2020       |                                                                                     |
| Survey held at                                                                                                                         | SMRT AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 |                 |                  |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                      |                 |                  |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                      |                 |                  |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                      |                 |                  |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                      | 4 Working Days  |                  |                                                                                     |

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4574Z**

| Qty | Description of Parts               | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b> |                      |                           |                   |
| 1   | FENDER RR/LH (DISC 25%)            | DENTED               | 766.80                    | 575.10            |
| 1   | CAP SUB-ASSY, WHEEL (DISC 25%)     | SCRATCHED            | 174.10                    | 130.58            |
| 2   | PIXEL STICKER @\$60.00 (SN)        | NECESSARY            | 120.00                    | 120.00            |
| 1   | SMRT LOGO (SN)                     | NECESSARY            | 7.80                      | 7.80              |
| 1   | STICKER DECAL 65558888 (SN)        | NECESSARY            | 21.60                     | 21.60             |
| 10  | BUMPER CLIPS @\$2.10               | SERVICEABLE          | 21.00                     | -                 |
| 1   | BUMPER REINFORCEMENT REAR          | SERVICEABLE          | 205.70                    | -                 |
| 1   | ARM SUB-ASSY. RR BUMPER RH         | SERVICEABLE          | 139.60                    | -                 |
| 1   | ARM SUB-ASSY. RR BUMPER LH         | SERVICEABLE          | 139.60                    | -                 |
| 1   | ANTENNA, ELECTRICAL LOWER REAR     | SERVICEABLE          | 157.40                    | -                 |
| 1   | SENSOR REVERSE                     | SERVICEABLE          | 180.00                    | -                 |
| 1   | BUMPER SIDE RETAINER RR/LH         | SERVICEABLE          | 94.80                     | -                 |
| 1   | BUMPER SIDE RETAINER RR/RH         | SERVICEABLE          | 94.80                     | -                 |
| 1   | BUMPER SEAL, RR LH                 | SERVICEABLE          | 88.90                     | -                 |
| 1   | BUMPER SEAL, RR RH                 | SERVICEABLE          | 65.70                     | -                 |
| 1   | BUMPER LIP COVER RR/LH             | SERVICEABLE          | 72.20                     | -                 |
| 1   | BUMPER LIP COVER RR/RH             | SERVICEABLE          | 118.10                    | -                 |
| 1   | BUMPER LIP REAR                    | SERVICEABLE          | 228.90                    | -                 |
| 1   | UNDER COVER SUB-ASSY, RR FLOOR     | SERVICEABLE          | 514.50                    | -                 |
| 1   | UNDER COVER RR SHIELD              | SERVICEABLE          | 63.90                     | -                 |
| 1   | TAIL LAMP LH                       | SERVICEABLE          | 548.40                    | -                 |
| 1   | TYRE                               | SERVICEABLE          | 126.74                    | -                 |
| 1   | WHEEL HUB REAR                     | SERVICEABLE          | 489.40                    | -                 |
| 1   | MOULDING BODY, LH                  | SERVICEABLE          | 673.60                    | -                 |
| 1   | DOOR OUTER HANDLE RR/LH            | SERVICEABLE          | 69.80                     | -                 |
| 1   | BUMPER REAR                        | TO REPAIR SEE LABOUR | 458.60                    | -                 |
| 1   | DOOR RR/LH                         | TO REPAIR SEE LABOUR | 954.50                    | -                 |
| 1   | WHEEL DISC                         | TO REPAIR SEE LABOUR | 1,484.20                  | -                 |

Report Ref No. NS/INC20001294/Qyf3e2



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983358E GST Reg. No. 20-0405911-H



Page No.:2 of 2

| Qty                                                                                     | Description of Parts                                                                          | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1                                                                                       | BUMPER SIDE RETAINER RR/LH (DISC 25%)                                                         | CRACKED       | 94.80                     | 71.10             |
| 1                                                                                       | ADVERTISEMENT STICKER (SN)                                                                    | NECESSARY     | 742.20                    | 445.32            |
|                                                                                         |                                                                                               |               | 8,917.64                  | 1,371.50          |
|                                                                                         | <b>LABOUR</b>                                                                                 |               |                           |                   |
|                                                                                         | PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF BUMPER REAR, DOOR RR/LH AND WHEEL DISC. |               | 507.00                    | 400.00            |
|                                                                                         | SPRAY PAINT.                                                                                  |               | 1,674.00                  | 650.00            |
|                                                                                         | TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).                                              |               | 120.00                    | 30.00             |
|                                                                                         | TO TEST AND REFIX REVERSE SENSOR SYSTEM.                                                      | NOT NECESSARY | 120.00                    | -                 |
|                                                                                         | TO REPLACE SUNDRY PARTS.                                                                      |               | 100.00                    | 20.00             |
|                                                                                         | TO CHECK WIRING AND SYSTEM FUNCTION.                                                          | NOT NECESSARY | 80.00                     | -                 |
|                                                                                         | TO WASH AND VACUUM.                                                                           | NOT NECESSARY | 60.00                     | -                 |
|                                                                                         | TOWING CHARGE.                                                                                |               | 84.00                     | -                 |
|                                                                                         | TO DO WHEEL ALIGNMENT / TYRE BALANCING.                                                       |               | 120.00                    | 60.00             |
|                                                                                         |                                                                                               |               | 2,865.00                  | 1,160.00          |
| <b>GRAND TOTAL</b>                                                                      |                                                                                               |               | <b>11,782.64</b>          | <b>2,531.50</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b> |                                                                                               |               |                           | <b>2,050.00</b>   |

Report Ref No. NS/INC20001294/Qyf3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.