

Repair Estimate

VAG Singapore Pte Ltd

48 Toh Guan Road East

#05-123, Enterprise Hub

Singapore 608586

Tel: 6267 9916

Fax: 6267 9313

www.avantage.sg

Date : 14/1/2020

Vehicle Num : SJX4888J

Make/Model : VW JETTA

Chassis No : WVWZZZ1KZAM117682

S/N	PARTS	QTY	PRICE	TOTAL
1	Front RH fender	1	\$ 380.00	\$ 380.00
2	Front bumper cover	1	\$ 700.00	\$ 700.00
3	Center cooling grille	1	\$ 200.00	\$ 200.00
4	Front LH bumper guide	1	\$ 25.00	\$ 25.00
5	Front RH bumper guide	1	\$ 25.00	\$ 25.00
6	Front LH lower bumper guide	1	\$ 20.00	\$ 20.00
7	Front RH lower bumper guide	1	\$ 20.00	\$ 20.00
8	Front foam insert	1	\$ 30.00	\$ 30.00
9	Front impact beam	1	\$ 330.00	\$ 330.00
10	Radiator grille	1	\$ 300.00	\$ 300.00
11	Radiator grille chrome frame	1	\$ 490.00	\$ 490.00
12	Front LH chrome strip	1	\$ 220.00	\$ 220.00
13	Front RH chrome strip	1	\$ 220.00	\$ 220.00
14	Front LH lower cover strip	1	\$ 40.00	\$ 40.00
15	Front RH lower cover strip	1	\$ 40.00	\$ 40.00
16	Rear bumper	1	\$ 680.00	\$ 680.00
17	Rear spoiler	1	\$ 390.00	\$ 390.00
18	Towing eye cap	1	\$ 45.00	\$ 45.00
19	Rear impact beam	1	\$ 380.00	\$ 380.00
20	Rear bumper attachment strip	1	\$ 60.00	\$ 60.00
21	LH rear bumper guide	1	\$ 45.00	\$ 45.00
22	RH rear bumper guide	1	\$ 45.00	\$ 45.00
	TOTAL PARTS			\$ 4,685.00
	TOTAL AMOUNT			\$ 4,685.00
	MISCELLANEOUS ITEM			
1	Licence plate with casing	2	\$ 35.00	\$ 70.00
	LABOUR			
1	Removal, refitting, panel beating of affected panels		\$ 900.00	\$ 900.00
2	Surface preparation and spray paint of affected panels		\$ 900.00	\$ 900.00
3	Sensor calibration, diagnostics and clearing of fault codes after repair		\$ 120.00	\$ 120.00
	TOTAL			\$ 6,675.00
	GST 7%			\$ 467.25
	GRAND TOTAL	1		\$ 7,142.25