

EVOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 405623

REFERENCE : INS/IC/H/0026/20
DATE : 18-JAN-2020

not allowed
also
22/1/20
take photo before party.
2-3 day.

p/r \$ 1319.24

Life Auto Consultants hence notify
the driver of the following:

- * If a driver is involved in some painting
- * If a driver is involved in denting or repair
- * If a driver is involved in the replacement
- * If a driver is involved in "Without Prejudice" basis
- * If a driver is involved in the replacement

* If a driver is involved in the replacement and
is a claimant from Insurance Company

Acknowledged by Repairer
Signature:
Date:

- 96450079

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJM75Y

S/NO JOB CODE	NATURE OF JOB	ESTIMATED	SURVEYOR'S
		CHARGES	RECOMMENDATION
1 ZZ/001	LABOUR CHARGE TO REPAIR REAR PANEL AND RENEW REAR BUMPER.	800.00	390
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	600.00	500
3 ZZ/003	REMOVE AND INSTALL REVERSE SENSOR - RENEW IF NEC.	55.00	✓
TOTAL LABOUR CHARGES		1455.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJM75Y

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	SUNDRIES	NPN		11 50.00 X
2	TRUNK TOP PLATE	84992-3VA0A	11 68.80 X	
3	SENSOR-REVERSE	SENSOR		11 200.00 X
4	STAY REAR BUMPER @ \$96.90 EACH	H5212-1HJMA	11 193.80 X	
5	ENERGY ABSORBER REAR BUMPER	B5090-5WJ0A	11 125.30 X	
6	CLIP REAR BUMPER @ \$1.30 EACH	01553-10501	11 7.80 ✓	
7	REAR BUMPER FASCIA	B5022-5WJ0H	11 460.00 ✓	
SUB TOTAL			855.70	0.00 250.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			171.14	0.00 0.00
GRAND TOTAL			684.56	0.00 250.00
OVERALL TOTAL			934.56	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

Ukk ulavau

15/6/2020 ✓

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 68467483

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0026/20
DATE : 18-JAN-2020

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

K

3 days.

OWNER'S NAME : MISS SENG CHIEW HONG (CHENG QIUFENG)
ADDRESS : BLK 108 PASIR RIS STREET 12
#12-75
S(510108)
TELEPHONE NO :

p/p \$ 1319.24

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SJM75Y
MODEL CODE : TDWARDZE12EDAY487Z
MODEL/YEAR : NOTE 1.2 BASE (IV) MY2017
ENGINE NO : HRI22752018
CHASSIS NO : JN1TAAE12Z0980143
MILEAGE : 28353 KM
DATE IN : 18/01/2020
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH
ACCIDENT DATE : 18/01/2020

96450079

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJM75Y

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOUR CHARGE TO REPAIR REAR PANEL AND RENEW REAR BUMPER.	800.00	390.00
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	600.00	500.00
3 ZZ/003	REMOVE AND INSTALL REVERSE SENSOR.	55.00	55.00
TOTAL LABOUR CHARGES		1455.00	945.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJM75Y

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 SUNDRIES	NPN			50.00 X
2 TRUNK TOP PLATE	84992-3VA0A	68.80		X
3 SENSOR-REVERSE	SENSOR			200.00 X
4 STAY REAR BUMPER @ \$96.90 EACH	H5212-1HJMA	193.80		X
5 ENERGY ABSORBER REAR BUMPER	85090-5WJ0A	125.30		X
6 CLIP REAR BUMPER @ \$1.30 EACH	01553-10501	7.80		OK
7 REAR BUMPER FASCIA	85022-5WJ0H	460.00		OK
SUB TOTAL		467.80	0.00	0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		93.56	0.00	0.00
GRAND TOTAL		374.24	0.00	0.00
OVERALL TOTAL		374.24		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SJM75Y

NETT ITEM 467.80
LESS 20.00%) -93.56
NETT AMOUNT 374.24

LIST ITEM 0.00
LESS 30.00%) 0.00
LIST AMOUNT 0.00

SPECIAL NETT ITEM 0.00
LESS .00%) 0.00
SPECIAL NETT AMOUNT 0.00

TOTAL LABOUR CHARGES 945.00
TOTAL SPARE PARTS CHARGES 374.24

TOTAL CHARGES 1319.24 ✓
ADD 7 % GST 92.35

GRAND TOTAL 1411.59