

ASS. REC. BY:

REF: CS/CT1 20001301 / kvf302

Special Instruction:

Survivor: Kenneth

ASSIGNMENT (Office)

From (Person): Tan Kah Leong

of CT2

Date/Time: 22-1-2020 10.39am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBF 4698E

Insured:

at Workshop m/s S L H Motor

Tel:

of 160 Sin Ming Drive #07-02

Policy No: DMVCSN 17 64991902

Claim No: SNM 200 200310 / GBF 4698E / TKL

Sum Insured:

Excess: \$500.00

Make of Veh:

D.O.A. 12-1-2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

mv: \$ 43K

H.O.D. Endorsement:

Date/Time: 22-1-2020 10.39am

Person Contacted:

Doris

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBF 4698E - x
23/1/2020	@ 130pm Doris will come back on the repair cost
23/1/2020	Revert via merimen pending repair cost from repairer
3/2/2020	@ 938am Doris will check
5/2/2020	@ 1134am Doris call up said request for \$114,000

ASS. REC. BY:

REF:

C12 / C8/CTI20001301/Kv3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: N/T / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/1/20

Seek mandate in merimen, repairer asking LS \$14000/-

11/1/20

@ 11:19am Denis said unable to repair the vehicle, recommend TL

11/1/20

Revert vehicle TL via merimen

21/2/20

Submit uneconomical TL - MV: \$43k LTA: \$33990 NV: \$9010

RECEIVED 21 FEB 2020

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fuel

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

21/2-Typist

270

270

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jan 2020 Sendback Est	21 Jan 2020 15:21 \$22,700.57	22 Jan 2020 10:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: AVERGO PTE LTD, Co. Reg. No.: -									
Vehicle Reg. No.: GBF4698E		Date of Loss: 12/01/2020 05:00 - :59 [37 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM20D200310/GBF4698E/TKL		Policy/Cover Note No.: DMCVSN1764991902 (Comprehensive)							
		Excess: S\$500.00							
Repairer: S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/02/2020]									
Driver/Custodian: NALLATHAMBI RAJESH (29 / Male) , NRIC: G2344003U, Tel: +6583611209 Email: NOEMAIL									
Adj Asg. Remarks: PREMIUM CLEARED. EXCESS SECT I : \$500									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

GBF4698E (SNM20D200310/GBF4698E/TKL)

OD
Jan 12 2020 5:00AM
[AVERGO PTE LTD]
S & H Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **21/02/2020 11:27 AM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - GBF4698E - Claim Handler: Tan Kah Leong

Approved:0.00:Please proceed to finalize report & forward bill for services rendered while we create tender

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 11 Feb 2020

Preliminary Advice

Vehicle No	: GBF4698E	Accident Date	: 12/01/2020
Make	: NISSAN CABSTAR	Policy No.	: DMCVSN1764991902
Assignment Date	: 22/01/2020	Excess	: S\$500.00
Date of Inspection	: 22/01/2020	Est. Duration of Repair	: 21.00
Inspection At	: S & H MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #07-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and o/s body. The undercarriage affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,700.57
Revised Amount	:S\$	13,984.37
Check Items (Estimated)	:S\$	5,815.00
Total	:S\$	19,799.37

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	43,000.00
COE / PARF Rebate	:S\$	33,990.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,010.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Repairer unable to repair within the Nett Value.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Tan Kah Leong	Date: 05 Feb 2020

Preliminary Advice

Vehicle No	: GBF4698E	Accident Date	: 12/01/2020
Make	: NISSAN CABSTAR	Policy No.	: DMCVSN1764991902
Assignment Date	: 22/01/2020	Excess	: S\$500.00
Date of Inspection	: 22/1/2020	Est. Duration of Repair	: 21
Inspection At	: S & H MOTOR PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion, o/s body. The undercarriage affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,700.57
Revised Amount	:S\$	13,984.37
Check Items (Estimated)	:S\$	5,815.00
Total	:S\$	19,799.37

Lump Sum Repair (estimated)	:S\$	15,850.00
-----------------------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	43,000.00
COE / PARF Rebate	:S\$	33,990.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,010.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note the margin repair cost is \$9,010.00
Repairer asking for Lump Sum Repair \$14,000.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Tan Kah Leong	Date:	22 Jan 2020
<u>Preliminary Advice</u>			

Vehicle No	: GBF4698E	Accident Date	: 12/01/2020
Make	: NISSAN CABSTAR	Policy No.	: DMCVSN1764991902
Assignment Date	: 22/01/2020	Excess	: S\$500.00
Date of Inspection	: 22/1/2020	Est. Duration of Repair	: 21
Inspection At	: S & H MOTOR PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion, o/s body. The undercarriage affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,700.57
Revised Amount	:S\$	13,984.37
Check Items (Estimated)	:S\$	5,815.00
Total	:S\$	19,799.37
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	43,000.00
COE / PARF Rebate	:S\$	33,990.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,010.00

Remarks

<input type="checkbox"/>	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
<input type="checkbox"/>	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
<input checked="" type="checkbox"/>	Other comments : Pending repair cost from repairer.

Colipo 23/1/2020

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	051Z
Vehicle Details	
Vehicle No.:	GBF4698E
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jan 2020
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	ZD30014155N
Chassis No.:	JN1SC2F24Z0859029
Maximum Power Output:	-
Open Market Value:	\$24,942.00
Original Registration Date:	15 Nov 2016
First Registration Date:	15 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$1,248.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Nov 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$49,890.00
COE Rebate Amount:	\$33,990.00
Total Rebate Amount:	\$33,990.00

The information contained herein is correct as at 22 Jan 2020

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	051Z
Vehicle Details	
Vehicle No.:	GBF4698E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Jan 2020
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	ZD30014155N
Chassis No.:	JN15C2F24Z0859029
Maximum Power Output:	-
Open Market Value:	\$24,942.00
Original Registration Date:	15 Nov 2016
First Registration Date:	15 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$1,248.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Nov 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$49,890.00
COE Rebate Amount:	\$34,091.00
Total Rebate Amount:	\$34,091.00

The information contained herein is correct as at 14 Jan 2020

OK

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

02/2012 Mercedes Benz E250 CGI A At 73,800

New Hardwork Engine, High Load
Aval, If Extend 50 Years CDE.
\$115,000.
Starting



KA-HUP

HOTLINE: 6741 9997

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

[VIEW OUR CARS](#)








Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

6 vehicles

nissan cabstar

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	nissan cabstar		Any	Any	2016	Any	Any	Any	Available
	Nissan Cabstar		\$41,800	\$6,650 /yr	04-May-2016	2,953 cc	-	Truck	Available
Fuel Type: Diesel Excellent 10 Feet Lorry, As Good As New, Come With Retractable Canopy And Full Checker Plate. Doorstep Viewing Can Be Arrange. ABWIN (1994) Pte Ltd Posted: 21-Jan-2020 Tags: 2016 Nissan Cabstar, 2016 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan									
	Nissan Cabstar		\$41,800	\$6,630 /yr	11-May-2016	2,953 cc	-	Truck	Available
Fuel Type: Diesel 1 Owner Only. Cabin Height Box Ideal For HDB Multi Story Parking And Basement Car Park Access, 2 Side Sliding Door, Very Well Maintained By Previous Owner, Extremely Clean Interior, Engine And Gearbox In Perfect Condition. High Trade In Guaranteed. Posted: 21-Jan-2020 Tags: 2016 Nissan Cabstar, 2016 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan									
	Nissan Cabstar		\$39,800	\$6,170 /yr	05-Jul-2016	2,953 cc	51,234 km	Truck	Available
Fuel Type: Diesel 1 Owner. Very Low Mileage. Do Not Drive Everyday. Zero Accident All In Original Condition Paintwork, View In Current Condition. Free 1 x Paintwork(Choice Of Colour) Free 1 Servicing Before HandOver Trade In Welcome. Loan Available. Contact Our Sales Consultant To Enq... Car (S) Pte Ltd Posted: 18-Jan-2020 Tags: 2016 Nissan Cabstar, 2016 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan									
	Nissan Cabstar		\$39,800	\$6,220 /yr	17-Jun-2016	2,953 cc	-	Truck	Available
Fuel Type: Diesel Excellent Condition. Comes With Checker Plate And Canopy. 100% Loan Can Do. Immediate Handover. Doorstep Viewing Available. Call To View Now ABWIN Bus Pte Ltd Posted: 17-Jan-2020 Tags: 2016 Nissan Cabstar, 2016 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan									
	Precise Auto Service - Specialist for Nissan Car repair, servicing & maintenance Your Trusted Car Workshop, a one-stop car workshop specialising in Japanese cars. More info about this shop								
	Nissan Cabstar		\$44,800	\$7,220 /yr	05-Apr-2016	2,953 cc	42,277 km	Truck	Available
Fuel Type: Diesel Selling Cheap! 04/2016 Nissan Cabstar 3.0 Mt 1 Owner, Low Mileage Canopy And Checker Plate/High Trade In Welcome/Call Us Now. Think One Automobile & Trading Posted: 26-Dec-2019 Tags: 2016 Nissan Cabstar, 2016 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan									
	Nissan Cabstar		\$41,800	\$6,490 /yr	30-Jun-2016	2,953 cc	-	Truck	Available
Fuel Type: Diesel Excellent Condition, Flexible In House Financing And High Trade In Given! Immediate Transfer Of Ownership Upon Collection, Hassle Free Transaction! Call Now To Enquire! Hui Hua Credit Pte Ltd Posted: 13-Dec-2019 Tags: 2016 Nissan Cabstar, 2016 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan									

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/01/2020 11:10
Date Of Accident	12/01/2020 05:50
Exact Location Of Accident	UPPER THOMSON RD NEAR EXIT 5 (SLE/CTE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF4698E
Insured/Policyholder	
Name Of Registered Owner	AVERGO PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83611209
Alternative Phone No	OFFICE-83611209

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1764991902
Cover Note Number	

Driver

Name of Driver	NALLATHAMBI RAJESH
Work Permit No	GXXXXX03U
Date Of Birth	17/03/1990
Occupation	OUTDOOR
Date Of Driving Pass	30/01/2018
Driving Experience	1 YEAR AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83611209
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	-
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	THOMSON NPP 25 SIN MING ROAD
Police Station Address	ROAD: 25 SIN MING ROAD #01-180 , POSTCODE: 570025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer attached police report.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLW4031X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 12th JAN 2020, I was driving my lorry along SLE towards CTE at about 0550hrs. I was travelling about 60km/h in the 3rd lane when a blue car (SLW 4031 X) suddenly hit the rear left of my lorry, just before the upper thanson exst. I felt my lorry overturned and came to a stopped, on the wheels, facing the opposite direction. As a result, the four sides of the ~~vehicle~~ lorry including the top was badly damaged.

* also attached police report.*

DECLARATION

I/We declare the foregoing particulars are true in every respect.

(2) ✓
Policyholder's Signature
Date & Time:



N. Rakesh
Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


**SINGAPORE
POLICE FORCE**


T/20200113/2148

1 of 3

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

Report No. T/20200113/2148

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/01/2020 18:08	Video Report No.:	Station Diary No.: 72
--	-------------------	--------------------------

Informant's Particulars

Name of Informant: NALLATHAMBI RAJESH			Address:	
ID Type / ID No.: FIN NO / G2344003U			Contact No.: Home/Office:	Mobile: 83611209
Nationality: INDIAN			Email:	
Sex: Male	Age: 29	Date of Birth: 17/03/1990	Type of Informant: Driver	
Race: Indian			Language:	Institution / School Name:
Occupation: CONSTRUCTION SUPERVISOR			Driving Licence Information: Class: 3	
			Date of Expiry: 22/01/2022	

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 12/01/2020 05:50	Type of Location: Straight Road
Location: Along Road 1 SELETAR EXPRESSWAY				
Along SLE towards CTE before Upper Thomson Exit		Road Surface: Dry	Road Speed Limit:	
Weather: Clear		Traffic Control: Not Controlled	Traffic Volume: Light	
Traffic Flow: One Way		Anyone conveyed by ambulance: No		
Type of Collision: Between Moving Vehicles - Head To Rear				

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF4698E	Lorry	NISSAN	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5	Silver	Seriously Damaged	0
SLW4031X	Car	TOYOTA	C-HR HYBRID 1.8S A	Blue	Seriously Damaged	0

Scanned by CamScanner



**SINGAPORE
POLICE FORCE**



T/20200113/2148

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

2 of 3

Report No. T/20200113/2148

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
GBF4698E	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMCVSN17649919 02	15/11/2019	14/11/2020

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	NALLATHAMBI RAJESH	ID No.	G2344003U
Related Vehicle	GBF4698E (Lorry)	Contact No.	83611209
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: 22/01/2022
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 12 January at about 0550hrs, I was driving my lorry (GBF4698E) along SLE towards CTE on the second lane from the left, when suddenly a blue car (SLW4031X) hit the rear left of my lorry. I felt my lorry overturn and complete a roll, landing on the wheels, facing against traffic. I immediately alighted to make a check and noticed that my lorry suffered dents on the top corners near the doors, and my left door cannot be opened anymore. Both my front and rear left tyres and rims were damaged, my right mirror broke off, and also my rear bumper broke off, and there was a dent in my rear bumper area near the left wheel. The left side of my front bumper also was unattached, and the right side of my rear side door cannot be closed anymore. There were cracks on my lorry's windscreen and the engine of my lorry could not be started as well. The top of my lorry's cabin suffered severe dents as well, and as such the cabin roof can no longer be extended. I also noticed that the blue car's front bumper was very heavily damaged, and that the airbags were deployed.

After checking that both the other driver and I were alright, the other driver called someone and left before we could exchange particulars. Traffic police arrived as well and interviewed me and asked me to make a police report when I was free. After a while, an Ambulance arrived to check on me and assessed that I did not have to be admitted. Both my vehicle and the other vehicle were towed.

I wish to state that my lorry does not have an in-car camera, and I noticed that the other vehicle has an in-car camera, however I am unsure if it was recording at the point of the accident.



**SINGAPORE
POLICE FORCE**



T/20200113/2148

3 of 3

Report No. T/20200113/2148

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan



IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 85474885 stating the report number as reference.

Signature Of Officer Recording The Report:
E /
SC2 MOHAMMAD HANIF KOH TECK WEE

Signature Of Informant:

[Handwritten Signature]

Signature Of Interpreter:
Not applicable

Date/Time:
13/01/2020 18:08

Officer In Charge Of Case:
TP / HRT /
Insp GOH GEOK LYE
Contact No.: 65478148

Classification Of Case:
SN 070

Authentication Stamp
NP168



SIGNATURE

Scanned by CamScanner

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:
Repairer Reference: 026563
Date calculated: 16/01/2020 9:40 AM

Full Report
Registration: GBF4698E
Printed: 16/01/2020 10:45 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	12/01/20
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	NISSAN		
Model:	CABSTAR		
Sub Model:	BASE MODEL		
Model Sheet Number:	71 94 01		
Registration:	GBF4698E		
VIN number:	WDD2050402R008598		
Odometer:			
Model Specs			
FROM 09/2006	AIR CONDITIONING	ELECT DOOR MIRRORS	INTERIOR MIRROR
TACHOGRAPH	FOG LAMPS	3.0 LTR 110KW	HEAVY DUTY SUSPENS
DRIVER AIRBAG	TYRES 155/85 RR 13	CHASS JIG CAROLINER	PARTICLE FILTER
SINGLE CAB	PRODUCTION IN JAPAN	TWO COAT METALLIC	PREPARE OFF VEHICLE
CLEAR COAT HARD			

Not Authorized
61 Smg @?
Reserve After Point
Ex @ 500k
Rec M's & d's body work
21 days
Fax: 62564315

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
UA10A1)	R + R FRONT BUMPER		6.0	25.20
UA10A1)	RENEW FRONT BUMPER (REMOVED)		2.0	8.40
NO NUMBER	R + R L/F BUMPER MOUNTING		2.0	8.40
RE20A1)	R + R LEFT HEADLAMP		5.0	21.00
	(FRONT GRILLE REMOVED)			
	INCLUDES: REQUIRED COVERS			
	REMOVE AND REFIT.			
	ADJUST HEADLAMPS.			
RE20A1)	R + R RIGHT HEADLAMP		3.0	12.60
	(FRONT GRILLE REMOVED)			
	INCLUDES: REQUIRED COVERS			
	REMOVE AND REFIT.			
	NOT INCLUDED: ADJUST HEADLAMPS.			
NO NUMBER	R + R L/F WIND DEFLECTOR		2.0	8.40
NO NUMBER	R + R R/F WIND DEFLECTOR		2.0	8.40
NO NUMBER	R + R L/R MUD FLAP FRONT		3.0	12.60

Code	Description	WU	Price SGD
NO NUMBER	R + R R/R MUD FLAP FRONT	3.0	12.60
RN24S1)	R + R ROOF MEMBER AERIAL	1.0	4.20
NO NUMBER	R + R FRONT VENTILATION GRILLE	2.0	8.40
UG10A1	R + R WINDSCREEN	11.0	46.20
VA10S1	R + R HEADLINING	12.0	50.40
NO NUMBER	RENEW ROOF	115.0	483.00
NO NUMBER	RENEW COMPLETE L/SIDE FRAME	150.0	630.00
VB12A1	R + R L/F LOWER DOOR SEAL	2.0	8.40
VB10A1	R + R LEFT FRONT SILL COVER	2.0	8.40
VB12A1	R + R L/FR DOOR FRAME SEL	2.0	8.40
NO NUMBER	R + R L/F STEP	2.0	8.40
UH10A1)	R + R L/F DOOR	6.0	25.20
UH10A1)	RENEW L/F DOOR (REMOVED)	17.0	71.40
NO NUMBER	RENEW COMPLETE R/SIDE FRAME	150.0	630.00
VB12A1	R + R R/F LOWER DOOR SEAL	2.0	8.40
VB10A1	R + R RIGHT FRONT SILL COVER	2.0	8.40
VB12A1	R + R R/FR DOOR FRAME SEAL	2.0	8.40
NO NUMBER	R + R R/F STEP BOARD	2.0	8.40
UH10A1)	R + R R/F DOOR	6.0	25.20
UH10A1)	RENEW R/F DOOR (REMOVED)	17.0	71.40
RE26A1	R + R BOTH REAR LAMPS	2.0	8.40
UD10A1	R + R REAR BUMPER	3.0	12.60
RE32A1	R + R REAR NUMBER PLATE LAMP	2.0	8.40
RE32A1)	R + R R/R NUMBER PLATE LAMP	1.0	4.20
NO NUMBER	R + R REAR NUMBER PLATE	1.0	4.20
VC10A1	R + R INSTRUMENT PANEL CPL	25.0	105.00
	INCLUDES: R + R COVERS, GLOVE BOX, INSTRUMENT HOUSING AND STEERING WHEEL		
NO NUMBER	DETACH + REFIT FLOOR CARPET	2.0	8.40
VE24A1	R + R L/F SEAT	2.0	8.40
VE10S1	R + R R/F SEAT	5.0	21.00
MH62A1)	R + R FRONT AXLE BEAM	40.0	168.00
MH62A1)	DIS + ASS FRONT AXLE MEMBER (REMOVED)	56.0	235.20
PW10A1)	FIT + BALANCE L/F TYRE	2.0	8.40
MH50A1)	R + R L/F STRUT	1.0	4.20
NO NUMBER	DETACH + REFIT FRONT STABILIZER	2.0	8.40
PW14A1	R + R LEFT REAR WHEEL	3.0	12.60
PW14A1	R + R RIGHT REAR WHEEL	3.0	12.60
PW10A1)	R + R L/R TYRE AND WHEEL	2.0	8.40
PW10A1)	R + R R/R TYRE AND WHEEL	2.0	8.40
NE14A1)	R + R L/R AXLE SHAFT	5.0	21.00
NE14A1)	R + R R/R AXLE SHAFT	5.0	21.00
NE15A1)	R + R REAR DRIVE SHAFT ASS-WORK	3.0	12.60
NN	TAILGATE HINGE PANEL R&R / NEW PARTS	20 30.0* ✓	126.00
3081	REAR CABIN PANEL REPAIR	25 30.0* ✓	126.00
5091	L/SIDE MEMBER REPAIR	20 30.0* ✓	126.00
5092	R/SIDE MEMBER REPAIR	20.0* 7	84.00
7306	STEERING GEAR CHECK		
Labour Cost		Hrs	WU
Panel / Mechanical Labour		80.80	808.0
Total of Labour			3,393.60

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	LEFT FRONT DOOR NEW PART PAINTING	18.0
	RIGHT FRONT DOOR NEW PART PAINTING	18.0
	L/F OUTER DOOR SILL NEW PART PAINTING	13.0
	R/F OUTER DOOR SILL NEW PART PAINTING	13.0
	L/OUTER A-PILLAR NEW PART PAINTING	12.0
	R/OUTER A-PILLAR NEW PART PAINTING	12.0
	L/OUTER B-PILLAR NEW PART PAINTING	18.0
	R/OUTER B-PILLAR NEW PART PAINTING	18.0
	ROOF NEW PART PAINTING	76.0
	BOOTLID/TAILGATE NEW PART PAINTING	25.0
	REAR CABIN PANEL REPAIR PAINTING <50%	22.0

Paint Material Per Part

Code	Description	Price SGD
1481	LEFT FRONT DOOR NEW PART PAINTING	51.60
1482	RIGHT FRONT DOOR NEW PART PAINTING	51.60
2111	L/F OUTER DOOR SILL NEW PART PAINTING	9.90
2112	R/F OUTER DOOR SILL NEW PART PAINTING	9.90
2239	L/OUTER A-PILLAR NEW PART PAINTING	8.25
2240	R/OUTER A-PILLAR NEW PART PAINTING	8.25
2291	L/OUTER B-PILLAR NEW PART PAINTING	19.25
2292	R/OUTER B-PILLAR NEW PART PAINTING	19.25
2351	ROOF NEW PART PAINTING	126.50
5403	BOOTLID/TAILGATE NEW PART PAINTING	82.56
3081	REAR CABIN PANEL REPAIR PAINTING <50%	42.31

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			245.0	
Preparation Main Work Metal		2.50	25.0	105.00
Total	10 WU/h	27.00	270.0	1,134.00

Material Cost - Paint

	Price SGD
New Part Painting	387.06
Repair Painting	42.31
Material-constant Metal Preparation	28.60
Total	457.97

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0735	AERIAL	28205 MA000		A ₁	90.00 ✓
5403	BOOTLID/TAILGATE	93400 2T230		A ₁	980.00 ✓
7011	FRONT AXLE BEAM	54400 MA000			1,100.00 ✓
0281	FRONT BUMPER	62010 MD80A		A ₁	530.00 ✓

Code	Description	Part Number	Supplier	Price SGD
1413	FRT SCREEN MNTG KIT	USE SINGLE PARTS		
1415	FRT SCREEN SUPPORTS	79714 D4000		0.00
4957	HEADLINING	73910 MA11A	Debra ✓	490.00
1737	L/DOOR MIRROR ASSY	96303 MA01A	Pro ✓	140.00
0335	L/F BUMPER BRACKET	62058 MA00A	B1 ✓	95.00
7117	L/F INN WHEEL BRG	40210 MA00A	B1 ✓	120.00
7053	L/F LWR CONTROL ARM	54501 MA00A	?	290.00
7081	L/F STEERING KNUCKLE	40015 MA00A	B1 ✓	580.00
2205	L/F STEP	96113 MA00A	CU ✓	130.00
7201	L/F WHEEL	40300 LC10B	B1 ✓	280.00
2617	L/R BUMPER BRACKET	85045 F3902	?	190.00
9265	L/R DRIVE SHAFT	38164 MA002	?	1,300.00
9131	L/R INN WHEEL BRG	43210 T6200	ne ✓	120.00
3281	L/R LAMP ASSY	26555 12T02	Pro ✓	95.00
9551	L/R WHEEL	40300 LC10B	? Pro ✓	280.00
2081	L/SIDE FRAME CPL	G6021 MA0MA	B1 ✓	1,050.00
7315	L/TIE ROD	D852A MA00A	?	110.00
7311	L/TIE ROD BALL JOINT	48520 VW025	?	110.00
7049	L/UPPER CONTROL ARM	54525 MA00B	?	290.00
1427	L/UPP W-SCREEN MLDG	72751 MA00D	ne ✓	55.00
1481	LEFT FRONT DOOR	H0101 MA0MM	B1 ✓	950.00
1000	LH TAILGATE HINGE	TAILGATE	B1 ✓	40.00
1411	LWR WINDSCREEN SEAL	G2716 89900		0.00
1600	R/F DOOR SEAL	80830 MA05A	?	95.00
2618	R/R BUMPER BRACKET	85044 F3902	R X	190.00
9266	R/R DRIVE SHAFT	38164 MA002	?	1,300.00
9132	R/R INN WHEEL BRG	43210 T6200	?	120.00
9552	R/R WHEEL	40300 LC10B	B1 ✓	280.00
2082	R/SIDE FRAME CPL	76020 MA030	R X	1,050.00
1428	R/UPP W-SCREEN MLDG	72750 MA00D	ne ✓	55.00
2581	REAR BUMPER	85022 F3903	?	450.00
1018	RH TAIL/G LOCK HINGE	TAILGATE	R X	110.00
1019	RH TAIL/G LOCK HINGE	TAILGATE	R X	110.00
1482	RIGHT FRONT DOOR	H0100 MA0MM	B1 ✓	950.00
2351	ROOF	73100 MA030	B1 ✓	980.00
1414	SPACER	72714 0P005		0.00
1017	TAILGATE HINGE PANEL	TAILGATE	B1 ✓	750.00
1001	TAILGATE NISSAN	TAILGATE	ne ✓	65.00
1401	WINDSCREEN	72712 MA000	CM ✓	750.00
1410	WINDSCREEN BOND KIT	KE150 10002		0.00
1423	WINDSCREEN MOULDING	72750 MB40D		0.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings
Subtotal

Total

LKK Auto Consultants hence notify

the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No legal enforcement is allowed

* Supplemental claim(s) must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

0.00

16,670.00

16,670.00

Extras

Code	Description	Price SGD
1002	TAILGATE "13PAX" TAILGATE	ne ✓ 5.00*
1003	TAILGATE "70KMH" TAILGATE	ne ✓ 5.00*
1004	Rear number plate Rear No Plate	ne X 35.00*
1005	T/G INNER ALUM PANEL TAILGATE	B1 ✓ 220.00*
1006	RH DOOR LETTERING DOOR	ne ✓ 25.00*

Code	Description				Price SGD
1007	LH DOOR LETTERING DOOR			na ✓	25.00*
1008	FNT W/S INNER SEAL FRNT WINDSCREEN			na ✓	20.00*
1009	FRONT W/S SEALANT FRNT WINDSCREEN			na ✓	25.00*
1010	IU BRACKET ERP			na ✓	25.00*
1011	REAR W/S ALUM PANEL REAR WINDSCREEN	(Inflow)		7	180.00*
1012	LH FRONT TYRE TYRE	Pr	84	70 2 1/2 in	120.00*
1013	RH REAR TYRE TYRE		96	80 2 1/2 in	120.00*
1014	LH REAR TYRE TYRE		96	80 2 1/2 in	120.00*
1015	Wheel alignment Wheel alignment			✓	60.00*
1016	Electrical work Electrical work			401	60.00*
1020	CARGO ROOF ASSY CARGO	Pr			0.00*
1021	RH CARGO RAILING CARGO	} Inflow ??			0.00*
1022	LH CARGO RAILING CARGO				0.00*
Total Extras					1,045.00

Final Calculation

	SGD	SGD
Parts	16,670.00	
Total Parts		16,670.00
Labour Time Base 10 WU/h		
Total 808.0 WU X 42.00 SGD/h	3,393.60	2129.40
Total of Labour		3,393.60
Total Of Extras		1,045.00
Paint Work Time Base 10 WU/h		
Labour Cost 270.0 WU X 42.00 SGD/h	1,134.00	953.40
Material Cost	457.97	420.57
Total Paint Including Material		1,591.97
Repair Cost Excludes GST		22,700.57
GST (+7.0%)		1,589.04
Repair Cost Included GST		24,289.61

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:
Repairer Reference: 026563
Date calculated: 22/01/2020 2:46 PM

Full Report
Registration: GBF4698E
Printed: 22/01/2020 2:47 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	12/01/20
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	NISSAN		
Model:	CABSTAR		
Sub Model:	BASE MODEL		
Model Sheet Number:	71 94 01		
Registration:	GBF4698E		
VIN number:	WDD2050402R008598		
Odometer:			
Model Specs			
FROM 09/2006	AIR CONDITIONING	ELECT DOOR MIRRORS	INTERIOR MIRROR
TACHOGRAPH	FOG LAMPS	3.0 LTR 110KW	HEAVY DUTY SUSPENS
DRIVER AIRBAG	TYRES 155/85 RR 13	CHASS JIG CAROLINER	PARTICLE FILTER
SINGLE CAB	PRODUCTION IN JAPAN	TWO COAT METALLIC	PREPARE OFF VEHICLE
CLEAR COAT HARD			

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
UA10A1)	R + R FRONT BUMPER		6.0	25.20
UA10A1)	RENEW FRONT BUMPER (REMOVED)		2.0	8.40
NO NUMBER	R + R L/F BUMPER MOUNTING		2.0	8.40
RE20A1)	R + R LEFT HEADLAMP (FRONT GRILLE REMOVED) INCLUDES: REQUIRED COVERS REMOVE AND REFIT. ADJUST HEADLAMPS.		5.0	21.00
NO NUMBER	R + R L/F WIND DEFLECTOR		2.0	8.40
NO NUMBER	R + R L/R MUD FLAP FRONT		3.0	12.60
RN24S1)	R + R ROOF MEMBER AERIAL		1.0	4.20
NO NUMBER	R + R FRONT VENTILATION GRILLE		2.0	8.40
UG10A1	R + R WINDSCREEN		11.0	46.20
VA10S1	R + R HEADLINING		12.0	50.40
NO NUMBER	RENEW ROOF		115.0	483.00
NO NUMBER	RENEW COMPLETE L/SIDE FRAME		150.0	630.00
VB12A1	R + R L/F LOWER DOOR SEAL		2.0	8.40
VB10A1	R + R LEFT FRONT SILL COVER		2.0	8.40
VB12A1	R + R L/FR DOOR FRAME SEL		2.0	8.40
NO NUMBER	R + R L/F STEP		2.0	8.40
UH10A1)	R + R L/F DOOR		6.0	25.20
UH10A1)	RENEW L/F DOOR (REMOVED)		17.0	71.40
UH10A1)	R + R R/F DOOR		6.0	25.20
UH10A1)	RENEW R/F DOOR (REMOVED)		17.0	71.40
RE24A1	R + R LEFT TAIL LAMP		2.0	8.40
VC10A1	R + R INSTRUMENT PANEL CPL INCLUDES: R + R COVERS, GLOVE BOX, INSTRUMENT HOUSING AND STEERING WHEEL		25.0	105.00
NO NUMBER	DETACH + REFIT FLOOR CARPET		2.0	8.40

Code	Description	WU	Price SGD
VE24A1	R + R L/F SEAT	2.0	8.40
VE10S1	R + R R/F SEAT	5.0	21.00
PW14A1	R + R LEFT FRONT WHEEL	3.0	12.60
PW10A1)	FIT + BALANCE L/F TYRE	2.0	8.40
NO NUMBER	DIS + ASS L/F WHEEL HUB AND BRAKE DISC	1.0	4.20
MH10A1)	R + R L/F STEERING KNUCKLE	1.0	4.20
MH11A1)	R + R FRONT STEERING KNUCKLE L+R	12.0	50.40
MH10A1)	DIS-/ASS LEFT FRONT STEERING KNUCKLE	6.0	25.20
PW14A1	R + R LEFT REAR WHEEL	3.0	12.60
PW14A1	R + R RIGHT REAR WHEEL	3.0	12.60
PW10A1)	R + R R/R TYRE AND WHEEL	2.0	8.40
NE15A1)	R + R REAR DRIVE SHAFT ASS-WORK	3.0	12.60
NE14H1)	R + R LEFT REAR AXLE BEARING	5.0	21.00
NN	TAILGATE HINGE PANEL R&R / NEW PARTS	20.0*	84.00
3081	REAR CABIN PANEL REPAIR	25.0*	105.00
5091	L/SIDE MEMBER REPAIR	20.0*	84.00
1600	R/F DOOR SEAL CHECK		
2581	REAR BUMPER CHECK		
2617	L/R BUMPER BRACKET CHECK		
5092	R/SIDE MEMBER CHECK		
7011	FRONT AXLE BEAM CHECK		
7049	L/UPPER CONTROL ARM CHECK		
7053	L/F LWR CONTROL ARM CHECK		
7306	STEERING GEAR CHECK		
7311	L/TIE ROD BALL JOINT CHECK		
7315	L/TIE ROD CHECK		
9132	R/R INN WHEEL BRG CHECK		
9265	L/R DRIVE SHAFT CHECK		
9266	R/R DRIVE SHAFT CHECK		
9551	L/R WHEEL CHECK		
1011	REAR W/S ALUM PANEL CHECK		180.00*
1020	CARGO ROOF ASSY CHECK		
1021	RH CARGO RAILING CHECK		
1022	LH CARGO RAILING CHECK		

Labour Cost
Panel / Mechanical Labour
Fixed Rate

Hrs **WU**
50.70 **507.0** **2,129.40**
180.00

Total of Labour

2,309.40

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	LEFT FRONT DOOR NEW PART PAINTING	18.0
	RIGHT FRONT DOOR NEW PART PAINTING	18.0
	L/F OUTER DOOR SILL NEW PART PAINTING	13.0
	L/OUTER A-PILLAR NEW PART PAINTING	12.0
	L/OUTER B-PILLAR NEW PART PAINTING	18.0
	ROOF NEW PART PAINTING	76.0
	BOOTLID/TAILGATE NEW PART PAINTING	25.0
	REAR CABIN PANEL REPAIR PAINTING <50%	22.0

Paint Material Per Part

Code	Description	Price SGD
1481	LEFT FRONT DOOR NEW PART PAINTING	51.60
1482	RIGHT FRONT DOOR NEW PART PAINTING	51.60
2111	L/F OUTER DOOR SILL NEW PART PAINTING	9.90
2239	L/OUTER A-PILLAR NEW PART PAINTING	8.25
2291	L/OUTER B-PILLAR NEW PART PAINTING	19.25
2351	ROOF NEW PART PAINTING	126.50
5403	BOOTLID/TAILGATE NEW PART PAINTING	82.56
3081	REAR CABIN PANEL REPAIR PAINTING <50%	42.31

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		202.0	
Preparation Main Work Metal	2.50	25.0	105.00
Total	10 WU/h	22.70	227.0

Material Cost - Paint

	Price SGD
New Part Painting	349.60
Repair Painting	42.31
Material-constant Metal Preparation	28.60
Total	420.57

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0735	AERIAL	28205 MA000			90.00
5403	BOOTLID/TAILGATE	93400 2T230			980.00
0281	FRONT BUMPER	62010 MD80A			530.00
1413	FRT SCREEN MNTG KIT	USE SINGLE PARTS			
1415	FRT SCREEN SUPPORTS	79714 D4000			0.00
4957	HEADLINING	73910 MA11A			490.00
1737	L/DOOR MIRROR ASSY	96303 MA01A			140.00
0335	L/F BUMPER BRACKET	62058 MA00A			95.00
7117	L/F INN WHEEL BRG	40210 MA00A			120.00
7081	L/F STEERING KNUCKLE	40015 MA00A			580.00
2205	L/F STEP	96113 MA00A			130.00
7201	L/F WHEEL	40300 LC10B			280.00
9131	L/R INN WHEEL BRG	43210 T6200			120.00
3281	L/R LAMP ASSY	26555 12T02			95.00
2081	L/SIDE FRAME CPL	G6021 MA0MA			1,050.00
1427	L/UPP W-SCREEN MLDG	72751 MA00D			55.00
1481	LEFT FRONT DOOR	H0101 MA0MM			950.00
1000	LH TAILGATE HINGE	TAILGATE			40.00
1411	LWR WINDSCREEN SEAL	G2716 89900			0.00
9552	R/R WHEEL	40300 LC10B			280.00
1428	R/UPP W-SCREEN MLDG	72750 MA00D			55.00
1482	RIGHT FRONT DOOR	H0100 MA0MM			950.00
2351	ROOF	73100 MA030			980.00
1414	SPACER	72714 0P005			0.00
1017	TAILGATE HINGE PANEL	TAILGATE			750.00

Code	Description	Part Number	Supplier	Price SGD
1001	TAILGATE NISSAN	TAILGATE		65.00
1401	WINDSCREEN	72712 MA000		750.00
1410	WINDSCREEN BOND KIT	KE150 10002		0.00
1423	WINDSCREEN MOULDING	72750 MB40D		0.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	9,575.00
Total	9,575.00

Extras

Code	Description	Price SGD
1002	TAILGATE "13PAX" TAILGATE	5.00*
1003	TAILGATE "70KMH" TAILGATE	5.00*
1005	T/G INNER ALUM PANEL TAILGATE	220.00*
1006	RH DOOR LETTERING DOOR	25.00*
1007	LH DOOR LETTERING DOOR	25.00*
1008	FNT W/S INNER SEAL FRNT WINDSCREEN	20.00*
1009	FRONT W/S SEALANT FRNT WINDSCREEN	25.00*
1010	IU BRACKET ERP	25.00*
1012	LH FRONT TYRE TYRE	84.00*
1013	RH REAR TYRE TYRE	96.00*
1014	LH REAR TYRE TYRE	96.00*
1015	Wheel alignment Wheel alignment	60.00*
1016	Electrical work Electrical work	40.00*
Total Extras		726.00

Final Calculation

	SGD	SGD
Parts	9,575.00	
Total Parts		9,575.00
Labour Time Base 10 WU/h		
Total 507.0 WU X 42.00 SGD/h	2,129.40	
Fixed Rate	180.00	
Total of Labour		2,309.40
Total Of Extras		726.00
Paint Work Time Base 10 WU/h		
Labour Cost 227.0 WU X 42.00 SGD/h	953.40	
Material Cost	420.57	
Total Paint Including Material		1,373.97
Repair Cost Excludes GST		13,984.37
GST (+7.0%)		978.97
Repair Cost Included GST		14,963.34

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jan 2020 Sendback Est	21 Jan 2020 15:21 \$22,700.57	22 Jan 2020 10:25 Edit Adj Rpt	\$13,984.37 Edit Estimates	\$13,984.37 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	AVERGO PTE LTD , Co. Reg. No.: -		
Vehicle Reg. No.:	GBF4698E	Date of Loss:	12/01/2020 05:00 - :59 [37 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM20D200310/GBF4698E/TKL	Policy/Cover Note No.:	DMCVSN1764991902 (Comprehensive)
		Excess:	\$4500.00
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/02/2020]		
Driver/Custodian:	NALLATHAMBI RAJESH (29 / Male) , NRIC: G2344003U, Tel: +6583611209 Email: NOEMAIL		
Adj Asg. Remarks:	PREMIUM CLEARED. EXCESS SECT I : \$500		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- CHINA_TAIPING (21/02/2020): Alert - Adj Mandate Approved (\$0.00) - GBF4698E - Claim Handler: Tan Kah Leong
- CHINA_TAIPING (11/02/2020): Alert - Adj Mandate Approved (\$9010.00) - GBF4698E - Claim Handler: Tan Kah Leo...

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBF4698E (SNM20D200310/GBF4698E/TKL)
OD
Jan 12 2020 5:00AM
[AVERGO PTE LTD]
S & H Motor Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

☒

No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	14/01/20 14:27	Accident Statement	Load HTM	
2	16/01/20 14:06	Addendum Sheet	Load TIF	
3	16/01/20 14:13	Accident Statement Addm. #1	Load HTM	
4	21/01/20 15:21	Repairer Estimates	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/01/20 14:00	Adjuster Immediate Advice	Load HTM	
2	05/02/20 12:32	Adjuster Immediate Advice	Load HTM	
3	11/02/20 14:54	Adjuster Immediate Advice	Load HTM	

Photos/Images

3 per page

☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/01/20 13:20	General View	Load PDF	

Documentation

1 per page

☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/01/20 13:30	MARK ESTIMATE	Load PDF	
2	23/01/20 13:31	AUDATEX	Load PDF	

Linked Accident Report Documents



View View in Browser

Assessment Reports					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print	
1	14/01/20 14:27	Accident Statement		Load HTM		
2	16/01/20 14:06	Addendum Sheet		Load TIF		
3	16/01/20 14:13	Accident Statement Addm. #1		Load HTM		
4	20/02/20 11:28	Addendum Sheet		Load TIF		
5	20/02/20 11:41	Accident Statement Addm. #2		Load HTM		

Photos/Images

3 per page ☒

No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	14/01/20 13:46	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	14/01/20 13:46	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	14/01/20 13:46	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	14/01/20 13:46	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	14/01/20 13:46	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	14/01/20 13:46	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	14/01/20 13:46	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	14/01/20 14:19	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	14/01/20 14:19	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	14/01/20 14:19	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	14/01/20 14:19	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
12	14/01/20 14:19	Accident Photo		Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
				<input checked="" type="checkbox"/>
13	14/01/20 14:19	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	14/01/20 14:19	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	16/01/20 14:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	16/01/20 14:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	16/01/20 14:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
18	16/01/20 14:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
19	16/01/20 14:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	14/01/20 13:40	Sketch Plan	 Load TIF	
2	14/01/20 13:40	Sketch Plan #2	 Load TIF	
3	14/01/20 13:41	police report	 Load TIF	
4	14/01/20 13:41	police report	 Load TIF	
5	14/01/20 13:41	police report	 Load TIF	
6	14/01/20 13:41	Identification Card	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20001301/KVF3E2

Date: 24/02/2020

REFERENCE

Insured/Claimant: AVERGO PTE LTD Policy No: DMCVSN1764991902

Date of Loss: 12/01/2020

Nature of Claim: OD

Claim No: SNM20D200310/GBF4698E/TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF4698E	Engine No:	ZD30014155N
Make & Model:	NISSAN CABSTAR, 3.0 (M)	Chassis No:	JN1SC2F24Z0859029
Reg. Date:	15/11/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	S\$43,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Sumitomo 9/9 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Sumitomo 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,670.00	9,575.00	7,095.00	42.56
Miscellaneous Items	1,045.00	726.00	319.00	30.53
Paintwork Materials	457.97	420.57	37.40	8.17
Labour	3,393.60	2,309.40	1,084.20	31.95
Paintwork Labour	1,134.00	953.40	180.60	15.93
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,700.57	13,984.37	8,716.20	38.40
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	22,700.57	13,484.37	9,216.20	40.60
+ GST 7.00/0.00% (S\$)	1,589.04	0.00	1,589.04	100.00
Nett Amount (S\$)	24,289.61	13,484.37	10,805.24	44.49

INSPECTION

Date of Assignment: 22/01/2020 Present Location:

Date Inspected: 22/01/2020 Inspected At:

S & H Motor Pte Ltd (Sin Ming)

S & H Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive #07-02, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(EXCLUDE CHECK ITEMS S\$5,815.00 NETT)

TOTAL LOSS ASPECT

Market Value :	\$43,000.00
OMV :	\$24,942.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$49,890.00
COE Rebate (2) :	\$33,990.00
Total Rebate (1) + (2) = :	\$33,990.00

The total amount incurred will be Market Value \$43,000.00 minus Total Rebate \$33,990.00 = \$9,010.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 21 Feb 2020)	
Parts:	N/A	NISSAN CABSTAR 3.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF4698E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Parts		16,670.00 F	*9,575.00 F
Total Parts (S\$)						16,670.00 9,575.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Materials</u>				
1	1	Paintwork material	457.97	420.57
<u>Miscellaneous Items</u>				
2	1	Misc	1,045.00	726.00
Sub Total (S\$)			1,502.97	1,146.57

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Labour for paintwork	New	1,134.00	953.40
<u>Labour Items</u>				
2	Labour for panel/mechanical	New	3,393.60	2,129.40
3	FIXED RATE	New	-	180.00
Gross Labour Cost (S\$)			4,527.60	3,262.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >