

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 26877

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0080/2020/NS
Date : 21-Jan-20

1st Accident.
Tambak.

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms See Chye Kim
Address : Blk 612 Telok Blangah Road
#23-09
Singapore 109026
Telephone : HP +65 91559938
Type of Claim : Own Damage Claims
Policy No. : 1800111779
Vehicle No : **SME 1081 D**
Model Code : Audi A4 Sedan 2.0 TFSI 8W
Model / Year : Sep-18
Engine No : CVK 065298
Chassis No : WAUZZZF40JA202860
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Jan-20
Place of Accident : Farrer Road Underpass

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 1081 D

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
1	FRONT BUMPER	\$	2,068.00 R _x	
2	FRONT BUMPER FIXING PARTS	\$	269.00 X	} X nn
3	FRONT BUMPER SECURING STRIP	\$	34.00 X	
4	FRONT BUMPER AIR GUIDE - RH	\$	59.00 X	
5	FRONT BUMPER AIR GUIDE GRILLE - RH	\$	127.00 X	
6	FRONT BUMPER GUIDE SECTION - RH	\$	36.00 X	
7	FRONT FENDER - RH	\$	722.00 H ✓	577.60
8	FRONT FENDER ATTACHMENT PARTS	\$	190.00 ?	} X nn
9	FRONT FENDER CLOSING ELEMENT - RH	\$	47.00 ?	
10	FRONT FENDER BRACKET - RH	\$	33.00 ?	
11	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	\$	46.00 ?	
12	FRONT FENDER BRACE - RH	\$	112.00 ?	
13	FRONT WHEEL HOUSING LINER - RH	\$	228.00 X	} X nn
14	WHEEL HOUSING LINER ATACHMENT PARTS	\$	86.00 X	
15	WHEEL SPOILER	\$	69.00 X	
16	WHEEL SPOILER TRIM - RH	\$	34.00 X	
17	STONE CHIP GUARD - RH	\$	48.00 X	
18	FENDER LEDGE COVER - RH	\$	29.00 X ✓	23.2
19	FENDER LEDGE TOP COVER - RH	\$	21.00 X ✓	16.72
20	EXTERIOR MIRROR MOUNTING - RH	\$	845.00 At ✓	675.6
21	MIRROR CAP - RH	\$	249.00 R _x	
22	FRONT ALUMINIUM RIM - RH	\$	652.00 X nn	
23	SUNDRIES	\$	300.00 ? ✓	24.48
TOTAL SPARE PARTS CHARGES		:	\$	6,304.00
TOTAL LABOUR CHARGES		:	\$	7,252.00
GRAND TOTAL		:	\$	13,556.00

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 1081 D

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle rhs front door panel trim. To remove and renew rhs wing mirror mounting.	S/N \$ 300.00 ✓	280
3	To dismantle front bumper and rhs front fender. To renew rhs front fender. To repair rhs front door. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00	1000
4	To respray front bumper, rhs front fender, rhs front door and rhs wing mirror cover.	\$ 3,500.00	1850
5	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00	X nn
6	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 7,252.00	